

ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 199405410K

Invoice Name & Address YEAP HOOI KEA (YE HUIJIE) BLK 301 CLEMENTI AVENUE 4 #04-553 SINGAPORE 120301 Contact No		Owner Name & Vehicle Info Cust No/Name LCV11013/YEAP HOOI KEA (YE HUIJIE) Reg No/Reg Date SMN9358G*ECB1/ 03/09/201 Date In/Mileage / 0 Chassis No KNAD6811VL6347613 Engine No G3LCKP112184 Make/Model KIA/STONIC 1.0 A SX BJ2 W 2 TONE RO Colour/Trim BMY BLACK ROOF W MO/ WK SATURN BLACK	
--	--	--	--

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LCV11013	CRDVCH	08/02/2021/ 18:02	BLC	442 / Cocolu	28737

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW REAR DOOR RH, SIDE SILL RH, REPAIR FRT DOOR RH	1 1/2 X 400			1200.00
E PNT88000 REMOVE & INSTALL REAR DOOR TRIMS AND GLASS				150.00
E PNT98000 SPRAY PAINT FOR FRT DOOR RH, REAR DOOR RH	2 X 350			700.00
A 90000001 CHECK WIRING & ELECTRICAL SYSTEM				30.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST				120.00
M SUNDRY APPLY SEALANT FOR ACCIDENT PORTION				40.00
M SUNDRY Sundry				20.00
P PANEL ASSY-REAR DOOR, RH	1.00	768.00	00.00	768.00
M TAPE-RR DR BLACK FRAME FR, RH	1.00	13.00	00.00	13.00
M BLACK TAPE-RR DR FRAME UPR, RH	1.00	7.00	00.00	7.00
M TAPE-RR DR FRAME BLACK RR, RH	1.00	6.00	00.00	6.00
M MOULDING ASSY-SIDE SILL, RH	1.00	248.00	00.00	248.00
M GARNISH ASSY-FR DR SIDE RH	1.00	82.00	00.00	82.00
M GARNISH ASSY-RR DR SIDE, RH	1.00	92.00	00.00	92.00
M GARNISH-QTR SIDE RH	1.00	50.00	00.00	50.00
M REGULATOR ASSY-FR DR WDO RH	1.00	195.00	00.00	195.00

Estimate

Steve (LKK) 9/2/21, 12:00pm
 OD- AM AL
 EXPRS - ?
 PIP
 By REL sy

Confirm & accepted by

- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Authorized signatory and company stamp

4 days

Nett	3,721.00
7% GST on	260.47
Total Payable	3,981.47

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.