

ASS. REC. BY:

Tanjah

REF:

C3/CT121001881/TIR93

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD (TP/WS/TP RES/OD RES/EVA/INV/MV)

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

WP

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Cien

Veh No: SMD/662S Yr Regn: 2017 Sep

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai 130 c.c. 1582Colour: Silver A/C: Insured / Std / NI / NASp. Reading: 359202 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: TMAD281 UVH J134/07

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/65R15R: 195/65R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

MAXXIS

Front

Rear

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. _____ D.O.I. 9/2/21Survey held at Premium Auto

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Report Format: _____

Lump Sum / L.B. / C. _____

Add Fee:

☐

Site Insp (\$ _____)

☐

Interview (\$ _____)

☐

Tech. Invs (\$ _____)

☐

Weekend (\$ _____)

Survey Fee:

Transportation:

S + RS. SI

Photos

Others

TOTAL

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

8-Feb-21

ESTIMATE REPAIR BILL FOR HYUNDAI I30 (A) REGN NO: SHD 1662 S

1 pc	Front n/s door	\$	1,723.60 <i>Rx</i>
2 pcs	Front n/s door hinges @ \$36.10	\$	72.20 <i>Rx</i>
1 pc	Rear n/s door	\$	2,017.48 <i>bt</i>
2 pcs	Rear n/s door hinges @ \$36.10	\$	72.20 <i>Rx</i>
1 pc	Rear bumper n/s & o/s side bracket @ \$32.50	<i>os/X</i> \$	65.00 <i>n/s ?</i>
1 pc	Rear bumper	\$	811.11 <i>Rx</i>
1 pc	Bonnet grille	\$	566.46 <i>Rx</i>
1 pc	Bonnet grille - piece moulding	\$	324.79 <i>X</i>
1 pc	Front bumper sponge	\$	218.03 <i>X</i>
1 pc	Front bumper reinforcement	\$	636.40 <i>X</i>
1 pc	Front bumper tow cap	\$	60.10 <i>X</i>
1 pc	Support panel	\$	1,243.60 <i>?</i>
1 pc	Mud guard front n/s	\$	47.48 <i>X</i>
1 pc	Front n/s fender signal light @ \$32.10	\$	32.10 <i>X</i>
1 pc	Front bumper n/s upper bracket	\$	92.60 <i>over</i>
1 pc	Front bumper n/s support bracket	\$	37.01 <i>?</i>
1 pc	Front n/s fog lamp cover	\$	25.00 <i>cut</i>
1 pc	Front n/s head lamp	\$	1,531.57 <i>cut</i>
1 pc	Front bumper	\$	811.11 <i>dis</i>
1 pc	Front bumper emblem	\$	27.80 <i>X</i>
1 pc	Front bumper n/s side bracket	\$	32.51 <i>?</i>
1 pc	Front n/s fender	\$	514.02 <i>bt</i>
1 pc	Front n/s rim	\$	246.00 <i>cut</i>
1 pc	Front n/s lower arm	\$	811.34 <i>?</i>
1 pc	Front n/s shock absorber	\$	611.56 <i>?</i>
1 pc	Front n/s tie rod end	\$	72.50 <i>X</i>
1 pc	Front n/s ball joint	\$	91.90 <i>X</i>
1 pc	Front n/s kunckle bearing	\$	349.60 <i>?</i>
1 pc	Front n/s stabilizer link	\$	88.50 <i>X</i>
1 pc	Front n/s fender inner shield	\$	176.72 <i>ht</i>
		\$	13,410.29
		Less 20%	\$ 2,682.06
			\$ 10,728.23

8-Feb-21

ESTIMATE REPAIR BILL FOR HYUNDAI I30 (A) REGN NO: SHD 1662 S

S/NETT

1 set	Front bumper clips	\$	48.00 ^{30 net}
1 pc	Front n/s fender sticker	\$	30.00 ^{net}
1 pc	Tyre front n/s	\$	200.00 X
1 set	Front n/s fender inner shield clips	\$	28.00 ^{10 net}
1 set	n/s door sticker	\$	100.00 ⁸⁰
1 pc	Rear n/s fender sticker	\$	60.00 ⁴⁰
1 set	Rear n/s fender inner shield clips	\$	28.00 X
1 set	Rear bumper clips	\$	48.00 X
	Sundry	\$	50.00 ²⁰
	Towing Fee	\$	50.00 ✓
	To check wheel alignment	\$	80.00 ✓
	To focus/check front n/s & o/s head lamps	\$	60.00 ³⁰
	To dismantle and replace the front n/s undercarriage	\$	250.00 ^{plate 120?}
	To dismantle and refit the inner components of the front & rear n/s doors into new shell door	\$	300.00 ⁶⁰
	To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.	\$	180.00 ⁶⁰
	To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the front n/s fender etc	\$	1,800.00 ⁹⁰⁰
	To putty and spray painting on front bumper, front n/s fender, front n/s wheel house, bonnet, front n/s door, rear n/s door, n/s rocker panel, rear n/s fender, rear bumper	\$	1,800.00 ¹²⁰⁰
	To apply rustproofing on the repaired and replaced panels.	\$	150.00 ⁴⁰
		\$	<u>15,990.23</u>

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Taufhin 97495747
WP' 2/2/21 @ 1530
1/3 Resurvey after repair
Taufhin @ 11 months
6-7 days.



PEOPLE'S VEHICLE SERVICE PTE LTD

BLK 3023A, UBI ROAD 1 #01-60, SINGAPORE 408717

TEL : 6743 1987 (3 LINES) FAX : 6743 0013

Email: peoplevehicle@gmail.com

Reg No: 200415052W



Date: 5/2/21

CASH SALEWORK ORDER No: PB 2911

實號

8-Mile (P17)

車號

SH116625

車型

Model No: 6/1/30

由

From: 01 May 2021

到

To: 01 May 2021

其他

Remark:

(1/24)

時間

Time: 12:38-13:38

AMOUNT: \$

NOTE: 本公司對所拖之車輛，在進行中如有任何損失或破壞，一概由車主自行負責。 Vehicle is towed at owner's risk. The company accepts no responsibility for damages or other misdemeanour to your vehicle whilst being towed.

經手人

Authorized by: Gary/423

收貨人

Received by:

- ☒ Accident/Breakdown
- ☐ Multi/Basement
- ☐ Jump Start
- ☐ Changing of Battery
- ☐ Tyre Replacement/ Patching
- ☐ Crane Up/Winch Out
- ☐ With Load/Cargo Box
- ☐ Flat Bed
- ☐ King Dolly to lift up
- ☐ Low Body Kit
- ☐ Repo
- ☐ Door Opening Service
- ☐ Collect Document/Key
- ☐ Jurong Island/Cargo Complex
- ☐ Woodlands/Tuas Checkpoint
- ☐ Cancellation Charge (Reach Location)
- ☐ Cancellation Charge (After 15 minutes)

Enquire Vehicle Registration Details**Owner Particulars**

NRIC/Passport/Company Cert No.: 200304975H
Owner ID Type: Company
Owner Name: PREMIER TAXIS PTE. LTD.
Registered Address: 23 CHANGI SOUTH AVENUE 2 #04-03 SINGAPORE 486443
Mailing Address: -
Birth Date: -

Vehicle Particulars

Vehicle No.: SHD1662S
Previous Vehicle No.: -
Effective Date of Ownership: 26 Sep 2017
Original Regn Date: 26 Sep 2017
Registration Date: 26 Sep 2017
Year of Manufacture: 2016
Vehicle Type: Public Transport Taxi (Motor Car)
Vehicle Scheme: Taxi (Company)
Vehicle Attachment 1: Air-Con (Taxi)
Vehicle Attachment 2: -
Vehicle Attachment 3: -
Vehicle Make: HYUNDAI
Vehicle Model: I30 GDH 1.6 TCI 5DR DCT
Primary Colour: Silver
Secondary Colour: -
Passenger Capacity: 4
Chassis No.: TMAD281UVHJ134107
Engine No.: D4FBGZ144460
Engine Capacity/Power Rating: 1582 cc / -
Maximum Power Output: 100.0 kW (134 bhp)
Propellant: Diesel
Max Unladen Weight: 1496 kg
Maximum Laden Weight: 1940 kg
Open Market Value: \$20,153.00
PARF Eligibility: Yes
PARF Eligibility Expiry Date: 25 Sep 2025
Minimum PARF Benefit: \$7,629.00
No. of Transfers: 0
IU Label No.: 1050707381
COE No.: 2017092601003838N
COE Expiry Date: 25 Sep 2025
COE Category: A - Car up to 1600cc & 97kW (130bhp)
COE Registration Category: A - Car up to 1600cc & 97kW (130bhp)
Quota Premium (QP) / Prevailing Quota Premium: - / \$44,081.00
PQP Paid: \$35,265.00
QP (Regn Cat): -
OPC Cash Rebate Eligibility: No