

8-Feb-21

ESTIMATE REPAIR BILL FOR HYUNDAI I30 (A) REGN NO: SHD 1662 S

1 pc	Front n/s door	\$	1,723.60 <i>Ry</i>
2 pcs	Front n/s door hinges @ \$36.10	\$	72.20 <i>Ry</i>
1 pc	Rear n/s door	\$	2,017.48 <i>bl</i>
2 pcs	Rear n/s door hinges @ \$36.10	\$	72.20 <i>Ry</i>
1 pc	Rear bumper n/s & o/s side bracket @ \$32.50	<i>os</i> X \$	65.00 <i>n/s gu</i>
1 pc	Rear bumper	\$	811.11 <i>Rx</i>
1 pc	Bonnet grille	\$	566.46 <i>Ry</i>
1 pc	Bonnet grille - piece moulding	\$	324.79 <i>X</i>
1 pc	Front bumper sponge	\$	218.03 <i>X</i>
1 pc	Front bumper reinforcement	\$	636.40 <i>X</i>
1 pc	Front bumper tow cap	\$	60.10 <i>X</i>
1 pc	Support panel	\$	1,243.60 <i>R</i>
1 pc	Mud guard front n/s	\$	47.48 <i>X</i>
1 pc	Front n/s fender signal light @ \$32.10	\$	32.10 <i>X</i>
1 pc	Front bumper n/s upper bracket	\$	92.60 <i>ant</i>
1 pc	Front bumper n/s support bracket	\$	37.01 <i>R un</i>
1 pc	Front n/s fog lamp cover	\$	25.00 <i>ant</i>
1 pc	Front n/s head lamp	\$	1,531.57 <i>ant</i>
1 pc	Front bumper	\$	811.11 <i>dis</i>
1 pc	Front bumper emblem	\$	27.80 <i>X</i>
1 pc	Front bumper n/s side bracket	\$	32.51 <i>R un</i>
1 pc	Front n/s fender	\$	514.02 <i>ht</i>
1 pc	Front n/s rim	\$	246.00 <i>ant</i>
1 pc	Front n/s lower arm	\$	811.34 <i>R</i>
1 pc	Front n/s shock absorber	\$	611.56 <i>R</i>
1 pc	Front n/s tie rod end	\$	72.50 <i>X</i>
1 pc	Front n/s ball joint	\$	91.90 <i>X</i>
1 pc	Front n/s kunckle bearing	\$	349.60 <i>R</i>
1 pc	Front n/s stabilizer link	\$	88.50 <i>X</i>
1 pc	Front n/s fender inner shield	\$	176.72 <i>ht</i>
		\$	13,410.29
		\$	2,682.06
		\$	10,728.23

5414.50
20% - 4331.60 Less 20%

8-Feb-21

ESTIMATE REPAIR BILL FOR HYUNDAI I30 (A) REGN NO: SHD 1662 S

S/NETT			
1 set	Front bumper clips	\$	48.00 ^{30 net}
1 pc	Front n/s fender sticker	\$	30.00 ^{net}
1 pc	Tyre front n/s	\$	200.00 ^{X net}
1 set	Front n/s fender inner shield clips	\$	28.00 ^{10 net}
1 set	n/s door sticker	\$	100.00 ^{80 nec}
1 pc	Rear n/s fender sticker	\$	60.00 ^{40 nec}
1 set	Rear n/s fender inner shield clips	\$	28.00 ^{X net}
1 set	Rear bumper clips	\$	48.00 ^{X net 190}
Sundry		\$	50.00 ²⁰
Towing Fee		\$	50.00 [/]
To check wheel alignment		\$	80.00 [✓]
To focus/check front n/s & o/s head lamps		\$	60.00 ³⁰
To dismantle and replace the front n/s undercarriage		\$	250.00 ^{120 X net}
To dismantle and refit the inner components of the front & rear n/s doors into new shell door		\$	300.00 ⁶⁰
To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.		\$	180.00 ⁶⁰
To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the front n/s fender etc		\$	1,800.00 ⁹⁰⁰
To putty and spray painting on front bumper, front n/s fender, front n/s wheel house, bonnet, front n/s door, rear n/s door, n/s rocker panel, rear n/s fender, rear bumper		\$	1,800.00 ¹²⁰⁰
To apply rustproofing on the repaired and replaced panels.		\$	150.00 ⁴⁰
		\$	15,990.23 ²⁴²⁰

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tanphir 97795747 4/5 \$5550
WP' 2/2/21 @ 1530 * 7 days
1/5 Resurvey after repair
Tanphir @ lkkauto.com
6-7 days.

6941.60