

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG21001888/AGA3Q2
Date: 08/07/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070036953
Claimant Vehicle No :	SJH9898G	Insured Vehicle No :	GBE8352G
Date of Loss:	05/02/2021	Nature of Claim:	TP
		Claim No:	4255325080SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJH9898G		
Make & Model:	BMW X1 SDRIVE18I, 2.0 D/AB 2WD 5DR GAS/D SR (A)	Engine No:	A286I967N46B20BD
Reg. Date:	08/03/2012 (Man. Year: 2011)	Chassis No:	WBAVL32080VP91051
Colour:	Silver	Odometer:	124612 km
Engine Capacity:	1995 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	255/85 R19	Rear Tyre Size:	255/85 R19
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,000.50	1,633.50	13,367.00	89.11
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,550.00	970.00	4,580.00	82.52
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	20,550.50	2,603.50	17,947.00	87.33
Approved Total (Overridden) (S\$)		2,050.00		

(S\$)	20,550.50	2,050.00	18,500.50	90.02
+ GST 7.00/7.00% (S\$)	1,438.54	143.50	1,295.04	90.02
Nett Amount (S\$)	21,989.04	2,193.50	19,795.54	90.02
+ Loss of Use (5.0 x S\$100.00/day) (S\$)		500.00		
(S\$)		2,693.50		
Liabe Amount (50.00%) (S\$)		1,346.75		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		1,354.20		

INSPECTION

Date of Assignment: 08/02/2021

Date Inspected: 08/02/2021

Estimated Period of Repair: 5.0 days

Inspected At: Stk Auto (s) Pte Ltd (HQ)
8 kaki bukit ave4, #03-21
Singapore 415875

Adjuster: ADRIAN LING**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RH REAR DOOR	Dented	1,155.00 FL	*1,155.00 FL
2	1		*RH REAR DOOR HANDLE	Not Necessary	85.00 FL	*- FL
3	1		*RH REAR DOOR INNER PANEL	Not Necessary	1,650.00 FL	*- FL
4	1		*RH REAR WHEEL ARCH GARNISH	Cut	160.00 FL	*160.00 FL
5	1		*RH REAR FENDER	Repair	2,850.00 FL	*- FL
6	1		*RH REAR FENDER INNER SHIELD	Not Necessary	250.00 FL	*- FL
7	1		*REAR BUMPER	Not Necessary	1,000.00 FL	*- FL
8	1		*REAR BUMPER LOWER GARNISH	Not Necessary	580.00 FL	*- FL
9	1		*REAR BUMPER REFLECTOR RH	Not Necessary	95.00 FL	*- FL
10	1		*RH REAR LOWER ARM	Not Necessary	195.00 FL	*- FL
11	1		*RH REAR UPPER ARM	Not Necessary	280.00 FL	*- FL
12	1		*RH REAR KNOCK ARM BEARING	Not Necessary	235.00 FL	*- FL
13	1		*RH REAR SHOCK ABSORBER	Not Necessary	4,500.00 FL	*- FL
14	1		*RH REAR SHOCK ABSORBER TOP MOUNT	Not Necessary	65.00 FL	*- FL
15	1		*RH REAR STABILIZER BAR	Not Necessary	650.00 FL	*- FL
16	1		*RH REAR STABILIZER BAR LINK	Not Necessary	195.00 FL	*- FL
17	10		*REAR BUMPER CLIPS	Not Necessary	50.00 FS	*- FS
18	10		*REAR END PANEL TOP GARNISH CLIPS	Not Necessary	50.00 FS	*- FS
19	10		*RH REAR FENDER INNER SHIELD CLIPS	Not Necessary	50.00 FS	*- FS
20	1		*RH REAR SPORT RIM	Cut	450.00 FS	*450.00 FS
21	1		*REAR BUMPER REVERSE SENSOR	Not Necessary	650.00 FS	*- FS
22	1		*LH REAR SPORT RIM	Repeated	1,200.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	16,395.00	1,765.00
- List Item Discount on L Items 10.00/10.00% (\$)	1,394.50	131.50
Total Parts (\$)	15,000.50	1,633.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO STRAIGHTEN AND PANEL BEAT ACCIDENT AREAS	New	2,500.00	350.00
2	TO SPRAY PAINT ON ACCIDENT AREAS	New	2,500.00	400.00
3	TO REMOVE AND REFIT RH REAR DOOR GLASS	New	150.00	80.00
4	TO CONDUCT WIRING AND REMOVE AND REFIT REVERSE	New	100.00	0.00
5	TO CONDUCT WHEEL ALIGNMENT	New	150.00	80.00
6	TO RUST PROOFING ACCIDENT AREAS	New	150.00	60.00
Gross Labour Cost (S\$)			5,550.00	970.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >