

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21001890/APA3Q2**Date:** 13/06/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100423370
Claimant Vehicle No :	SME9935M	Insured Vehicle No :	SBT11P
Date of Loss:	06/02/2021	Nature of Claim:	TP
		Claim No:	6654437101SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SME9935M	Engine No:	2ZR0C61174
Make & Model:	TOYOTA PRIUS PLUS, 1.8 (A)	Chassis No:	JTDZS3EU70J034476
Reg. Date:	25/10/2018 (Man. Year: 2018)	Odometer:	85753 km
Colour:	Silver		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Good

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,804.56	3,717.00	9,087.56	70.97
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,080.00	2,060.00	5,020.00	70.90
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	19,884.56	5,777.00	14,107.56	70.95
Approved Total (Overridden) (S\$)		4,600.00		
Nett Amount (S\$)	19,884.56	4,600.00	15,284.56	76.87
+ Loss of Use (5.0 x S\$100.00/day) (S\$)		500.00		
		(S\$)	5,100.00	
Liabe Amount (60.00%) (S\$)		3,060.00		
+ Doc/Search Fee (S\$)		36.45		
Nett Liability (S\$)		3,096.45		
Global Sum Settlement (S\$)		3,100.00		

INSPECTION

Date of Assignment:	08/02/2021	Ishare Auto Pte. Ltd. (HQ)
Date Inspected:	08/03/2021 Inspected At:	8 KAKI BUKIT AVENUE 4 #08-09 PREMIER @ KAKI BUKIT
Estimated Period of Repair:	5.0 days	Singapore 415875

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	968.70 FL	*698.00 FL
2	1		*REAR BUMPER DIFFUSER	Cut	694.30 FL	*425.00 FL
3	1		*REAR BUMPER REFLECTOR RH	Cracked	84.20 FL	*84.20 FL
4	1		*REAR BUMPER SIDE RETAINER	O/S Necessary	139.60 FL	*69.80 FL
5	1		*TAIL LAMP RH	Not Necessary	546.80 FL	*- FL
6	1		*TAIL LAMP LOWER BRACKET RH	Not Necessary	69.30 FL	*- FL
7	1		*REAR DOOR RH	Dented	1,486.60 FL	*1,324.00 FL
8	1		*REAR DOOR BLACK STICKER RH	Necessary	65.70 FL	*65.70 FL
9	1		*REAR DOOR GLASS SIDE GARNISH RH	Not Necessary	78.50 FL	*- FL
10	1		*REAR DOOR OUTER MOULDING RH	Not Necessary	125.30 FL	*- FL
11	1		*REAR DOOR INNER LOCK RH	Not Necessary	478.70 FL	*- FL
12	1		*REAR DOOR INNER TRIM RH	Not Necessary	668.20 FL	*- FL
13	1		*REAR DOOR WEATHERS TRIP RH	Not Necessary	215.40 FL	*- FL
14	2		*REAR DOOR HINGE RH	Not Necessary	312.40 FL	*- FL
15	1		*SIDE SKIRT RH	Deformed	484.88 FS	*400.00 FS
16	1		*ROCKER PANEL (OUTER) RH	Repair	632.50 FL	*- FL
17	1		*REAR FENDER RH	Repair	1,432.50 FL	*- FL
18	1		*REAR FENDER GLASS RH	Not Necessary	546.40 FL	*- FL
19	1		*REAR FENDER COWLING RH	Not Necessary	135.80 FL	*- FL
20	1		*REAR FENDER INNER TRIM RH	Not Necessary	769.90 FL	*- FL
21	1		*REAR FENDER AIR VENT RH	Not Necessary	78.40 FL	*- FL
22	1		*REAR WHEEL SPORT RIM RH	Cut	945.38 FS	*700.00 FS
23	1		*REAR WHEEL HUP CAP RH	Cut	147.53 FS	*100.00 FS
24	1		*REAR AXLE	Not Necessary	1,974.30 FL	*- FL
25	1		*REAR WHEEL HUP RH	Damaged	453.20 FL	*453.20 FL
26	1		*REAR WHEEL HUP BEARING RH	Damaged	156.10 FL	*156.10 FL
27	1		*REAR SHOCK ABSORBER RH	Not Necessary	362.90 FL	*- FL
28	1		*REAR BUMPER CLIPS (SET)	Necessary	80.00 FS	*30.00 FS
29	1		*REAR DOOR GLASS SIDE GARNISH CLIP RH (SET)	Not Necessary	60.00 FS	*- FS
30	1		*REAR DOOR INNER TRIM CLIP (SET)	Not Necessary	80.00 FS	*- FS
31	1		*SIDE SKIRT CLIP RH (SET)	Necessary	80.00 FS	*30.00 FS
32	1		*ROCKER PANEL (OUTER) SEALANT RH	Not Necessary	150.00 FS	*- FS
33	1		*REAR FENDER SEALANT RH	Not Necessary	150.00 FS	*- FS
34	1		*REAR FENDER INNER COWLING CLIP (SET)	Not Necessary	60.00 FS	*- FS
35	1		*REAR FENDER INNER TRIM CLIP (SET)	Not Necessary	60.00 FS	*- FS
36	1		*REAR FENDER GLASS SEALANT RH	Not Necessary	80.00 FS	*- FS
37	1		*REAR FENDER GLASS INNER SEAL RH	Not Necessary	60.00 FS	*- FS
38	1		*REAR FENDER GLASS SOLAR FILM RH	Not Necessary	250.00 FS	*- FS
39	1		*TAILLAMP CLIP (SET)	Not Necessary	40.00 FS	*- FS
40	1		*REAR WHEEL TYRE RH	Not Necessary	680.00 FS	*- FS
41	1		*BRAKE OIL	Not Necessary	40.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	15,923.49	4,536.00
- List Item Discount on L Items 25.00/25.00% (\$)	3,118.93	819.00
Total Parts (\$)	12,804.56	3,717.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING, REMOVING AND REPLACING PARTS	New	2,400.00	800.00
2	SPRAY PAINTING TO AFFECTED AREA	New	2,000.00	800.00
3	TUFF COAT	New	250.00	40.00
4	WIRING CHECK	New	180.00	30.00
5	REMOVE AND REFIX CUSHION SEAT/UPHOLSTRY AND ROOF LINNING TO FACILATE REPAIR	New	350.00	80.00
6	REMOVE AND REFIX AUDIO SPEAKER	New	120.00	0.00
7	RESET RADIO SYSTEM	New	200.00	0.00
8	TRANSFER REAR DOOR MECHANISM RH	New	120.00	80.00
9	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	New	80.00	50.00
10	CONDUCT WATER LEAKAGE TEST	New	120.00	0.00
11	REMOVE AND REFIX REAR UNDERCARRIAGE	New	650.00	100.00
12	TO PRESS REAR WHEEL BEARING	New	80.00	0.00
13	FOUR WHEEL ALIGNMENT	New	180.00	80.00
14	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	New	350.00	0.00
Gross Labour Cost (\$)			7,080.00	2,060.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >