

iShare Auto Pte. Ltd.

Co. Reg No: 201939376R

8 Kaki Bukit Avenue 4

#08-09 Premier @ Kaki Bukit

Singapore 415875

Tel: 6341 6789 Fax: 6341 6778

Email: ishareauto@gmail.com



DATE : 08.03.21

TO : **AIG** MOTOR CLAIMS DEPTS
VEHICLE NO : **SME9935M**
MODEL : **TOYOTA PRIUS PLUS**
DATE OF ACCIDENT : 06.02.21
TIME OF ACCIDENT : 13:15HRS

Xiao Tony

JTDZS3E470J034476

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR BUMPER <i>Defend</i>	1	\$ 968.70	\$ 968.70
2	REAR BUMPER DIFFUSER <i>Cut</i>	1	\$ 694.30	\$ 694.30
3	REAR BUMPER REFLECTOR RH <i>new could</i>	1	\$ 84.20	\$ 84.20
4	REAR BUMPER SIDE RETAINER <i>Rd M</i>	2	\$ 69.80	\$ 139.60
5	TAIL LAMP RH <i>Ne M</i>	1	\$ 546.80	\$ 546.80
6	TAILLAMP LOWER BRACKET RH <i>new</i>	1	\$ 69.30	\$ 69.30
7	REAR DOOR RH <i>Dented</i>	1	\$ 1,486.60	\$ 1,486.60
8	REAR DOOR BLACK STICKER RH <i>new</i>	1	\$ 65.70	\$ 65.70
9	REAR DOOR GLASS SIDE GARNISH RH <i>new</i>	1	\$ 78.50	\$ 78.50
10	REAR DOOR OUTER MOULDING RH <i>new</i>	1	\$ 125.30	\$ 125.30
11	REAR DOOR INNER LOCK RH <i>new</i>	1	\$ 478.70	\$ 478.70
12	REAR DOOR INNER TRIM RH <i>new</i>	1	\$ 668.20	\$ 668.20
13	REAR DOOR WEATHERSTRIP RH <i>new</i>	1	\$ 215.40	\$ 215.40
14	REAR DOOR HINGE RH <i>new</i>	2	\$ 156.20	\$ 312.40
15	SIDE SKIRT RH <i>Defend</i>	1	\$ 646.50	\$ 646.50
16	ROCKER PANEL (OUTER) RH <i>Repair</i>	1	\$ 632.50	\$ 632.50
17	REAR FENDER RH <i>Repair</i>	1	\$ 1,432.50	\$ 1,432.50
18	REAR FENDER GLASS RH <i>2</i>	1	\$ 546.40	\$ 546.40
19	REAR FENDER COWLING RH <i>1</i>	1	\$ 135.80	\$ 135.80
20	REAR FENDER INNER TRIM RH <i>1</i>	1	\$ 769.90	\$ 769.90
21	REAR FENDER AIR VENT RH <i>1</i>	1	\$ 78.40	\$ 78.40
22	REAR WHEEL SPORT RIM RH <i>Cut</i>	1	\$ 1,260.50	\$ 1,260.50
23	REAR WHEEL HUP CAP RH <i>Cut</i>	1	\$ 196.70	\$ 196.70
24	REAR AXLE <i>Ne M</i>	1	\$ 1,974.30	\$ 1,974.30
25	REAR WHEEL HUP RH <i>Defend</i>	1	\$ 453.20	\$ 453.20
26	REAR WHEEL HUP BEARING RH <i>Defend</i>	1	\$ 156.10	\$ 156.10

698

425

69.80

x

x

1324

x

x

x

x

x

x

x

400(SN)

x

x

x

x

x

x

x

700(SN)

x

x

x

x

x

TO : **AIG** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SME9935M**
 MODEL : **TOYOTA PRIUS PLUS**
 DATE OF ACCIDENT : 06.02.21
 TIME OF ACCIDENT : 13:15HRS

27	REAR SHOCK ABSORBER RH <i>new</i>	1	\$ 362.90	\$ 362.90
----	-----------------------------------	---	-----------	-----------

S.N: 1200 3276 2457

TOTAL PRICE \$ 12,692.60
 LESS 25% \$ 3,173.15
SUB TOTAL PRICE \$ 9,519.45

SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR BUMPER CLIPS (SET) <i>new</i>	1	\$ 80.00	\$ 80.00
2	REAR DOOR GLASS SIDE GARNISH CLIP RH (SET) <i>new</i>	1	\$ 60.00	\$ 60.00
3	REAR DOOR INNER TRIM CLIP (SET) <i>new</i>	1	\$ 80.00	\$ 80.00
4	SIDE SKIRT CLIP RH (SET) <i>new</i>	1	\$ 80.00	\$ 80.00
5	ROCKER PANEL (OUTER) SEALANT RH <i>new</i>	1	\$ 150.00	\$ 150.00
6	REAR FENDER SEALANT RH <i>new</i>	1	\$ 150.00	\$ 150.00
7	REAR FENDER INNER COWLING CLIP (SET) <i>new</i>	1	\$ 60.00	\$ 60.00
8	REAR FENDER INNER TRIM CLIP (SET)	1	\$ 60.00	\$ 60.00
9	REAR FENDER GLASS SEALANT RH	1	\$ 80.00	\$ 80.00
10	REAR FENDER GLASS INNER SEAL RH	1	\$ 60.00	\$ 60.00
11	REAR FENDER GLASS SOLAR FILM RH	1	\$ 250.00	\$ 250.00
12	TAILLAMP CLIP (SET)	1	\$ 40.00	\$ 40.00
13	REAR WHEEL TYRE RH	1	\$ 680.00	\$ 680.00
14	BRAKE OIL	1	\$ 40.00	\$ 40.00

60

TOTAL \$ 1,870.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (FRONT)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVING AND REPLACING PARTS	\$ 2,400.00	<i>800</i>
2	SPRAY PAINTING TO AFFECTED AREA	\$ 2,000.00	<i>800</i>
3	TUFF COAT	\$ 250.00	<i>40</i>
4	WIRING CHECK	\$ 180.00	<i>30</i>
5	REMOVE AND REFIX CUSHION SEAT/UPHOLSTERY AND ROOF LINING TO FACILITATE REPAIR	\$ 350.00	<i>80</i>
6	REMOVE & REFIX AUDIO SPEAKER	\$ 120.00	<i>x</i>
7	RESET RADIO SYSTEM	\$ 200.00	<i>x</i>
8	TRANSFER REAR DOOR MECHANISM RH	\$ 120.00	<i>80</i>

TO : **AIG** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SME9935M**
 MODEL : **TOYOTA PRIUS PLUS**
 DATE OF ACCIDENT : 06.02.21
 TIME OF ACCIDENT : 13:15HRS

9	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	50
10	CONDUCT WATER LEAKAGE TEST	\$ 120.00	x
11	REMOVE AND REFIX REAR UNDERCARRIAGE	\$ 650.00	100-
12	TO PRESS REAR WHEEL BEARING	\$ 80.00	x
13	FOUR WHEEL ALIGNMNET	\$ 180.00	80
14	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS,RESET MEMORIES TO SPECIFICATION ETC.	\$ 350.00	x

TOTAL

\$7,080.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 11,389.45
 TOTAL LABOUR COST : \$ 7,080.00
 TOTAL REPAIR COST : \$ 18,469.45

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.

PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

MICHELLE

SERVICE ADVISOR

MICHELLE

HP : 9856 4815

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian L
 r/s 08/03/21.
 058mp.

total: 5779.25

r/s: 4.6k.

4.6k

TEO HIN TYRES

11 KAKI BUKIT ROAD 1
#01-01 EUNOS TECHNOLINK
SINGAPORE 415939
TEL:67455711

Work Order: R004820

License: SME 9935 M

Date: 8.3.21 11:31

Factory Japan 2019.0.1 : Toyota : Prius Alpha : ZVW40W

Front : Left

Actual	Before	Specified Range
-0°17'		-0°55' 0°35'
4°49'		5°10' 6°40'
0°06'		0°00' 0°11'
11°51'		11°25' 12°55'
11°34'		10°30' 13°30'

Camber
Caster
Toe
SAI
Included Angle
Turning Angle Diff.

Front : Right

Actual	Before	Specified Range
-0°30'		-0°55' 0°35'
4°42'		5°10' 6°40'
-0°04'		0°00' 0°11'
9°22'		11°25' 12°55'
8°52'		10°30' 13°30'

Front

Cross Camber
Cross Caster
Cross SAI
Total Toe
Cross Turn Diff.

Actual	Before	Specified Range
0°13'		
0°07'		
2°29'		
0°02'		0°00' 0°21'

Rear : Left

Actual	Before	Specified Range
-1°06'		-1°55' -0°55'
0°12'		-0°03' 0°13'

Camber
Toe

Rear : Right

Actual	Before	Specified Range
-1°56'		-1°55' -0°55'
0°29'		-0°03' 0°13'

Rear

Cross Camber
Total Toe
Thrust Angle
Axle Offset

Actual	Before	Specified Range
0°50'		
0°41'		-0°05' 0°26'
-0°09'		
0mm		