

REPAIR ESTIMATE

COMPANY: THIRD PARTY S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS: COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305452748
 REGN NO : SHC8663Z
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : I-40
 DATE OF REGN : 17.03.2016
 DATE/TIME IN : 08.02.2021 08:45
 ACCIDENT DATE : 06.02.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0103-0738-G	COVER-RR BUMPER LWR#	1	228.00	20.00	182.40	Ry	
0002 04-01-0103-0579-G	COVER ASSY-RR BUMPER#	1	1,106.00	20.00	884.80	de	
0003 04-01-0101-0111-G	BUMPER COVER CLIP REAR	10 L	22.00	20.00	17.60	ne	
0004 04-01-0103-0739-G	ABSORBER-RR BUMPER ENERGY	1	119.50	20.00	95.60	Xun	1128
0005 04-01-0103-0740-G	BEAM-RR BUMPER#	1	428.40	20.00	342.72	Xun	20% 902.40
0006 04-01-0103-1150-A	PROTECTOR MAT	1	50.00	2.00	50.00	ne	SN 50
							8952.40
						SUB-TOTAL :	1,573.12

JOB NATURE

0000 PB	PANEL BEATING	400.00	280	
0001 SP	SPRAYPAINT CHARGE	300.00	250	560.
0002 L	REMOVE/REFIX REVERSE SENSOR	80.00	30	
				SUB-TOTAL : 780.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Tanphir 97495749
 WP 8/2/21 23pm
 45 Resurvey after repair
 02 days
 Tanphir C/Mantow

81512.14
 458 1200
 02 days