

# JEC AUTO SERVICE PTE LTD

1 KAKI BUKIT AVENUE 6, #02-11 AUTOBAY@KAKI BUKIT  
SINGAPORE 417883  
TEL: 92327457

|                                 |                         |                 |             |
|---------------------------------|-------------------------|-----------------|-------------|
| TO                              | : AXA                   | DATE            | : 17/2/2021 |
| ATTENTION                       | : MOTOR INSURANCE CLAIM | JOB TYPE        | : T/P CLAIM |
| ESTIMATE REPORT                 | :                       |                 |             |
| <b>VEHICLE DETAILS</b>          |                         |                 |             |
| VEHICLE NO                      | : SGZ35E                |                 |             |
| VEHICLE MODEL                   | : TOYOTA PREVIA         |                 |             |
| CHASSIS NO                      | : JTEGD52M20A019445     |                 |             |
| ACCIDENT DETAILS                | DATE                    | :               |             |
|                                 | TIME                    | :               |             |
| THIRD PARTY REQUESTOR / CONTACT | :                       | XIAN / 92327457 |             |

*Xiao Chan.*

## CLAIM DETAILS: PARTS

|    | ITEMS                                   | QTY | UNIT PRICE  | TOTAL       |
|----|-----------------------------------------|-----|-------------|-------------|
| 1  | REAR BUMPER <i>Dehand</i>               | 1   | \$ 534.90   | \$ 534.90   |
| 2  | REAR BUMPER SIDE HOLDER <i>new</i>      | 2   | \$ 55.90    | \$ 111.80   |
| 3  | REAR BUMPER TOW COVER <i>3 new</i>      | 1   | \$ 31.40    | \$ 31.40    |
| 4  | REAR BUMPER REFLECTOR <i>3 new</i>      | 2   | \$ 49.70    | \$ 99.40    |
| 5  | REAR END PANEL <i>Dented</i>            | 1   | \$ 625.50   | \$ 625.50   |
| 6  | REAR END PANEL TOP GARNISH <i>cut d</i> | 1   | \$ 295.20   | \$ 295.20   |
| 7  | TAILGATE <i>3 new</i>                   | 1   | \$ 1,492.50 | \$ 1,492.50 |
| 8  | TAILGATE LOCK <i>3 new</i>              | 1   | \$ 384.10   | \$ 384.10   |
| 9  | TAILGATE WEATHERSTRIPE <i>3 new</i>     | 1   | \$ 329.10   | \$ 329.10   |
| 10 | TAILGATE GLASS MOULDING <i>3 new</i>    | 1   | \$ 201.60   | \$ 201.60   |
| 11 | TOYOTA LOGO <i>3 new</i>                | 1   | \$ 68.00    | \$ 68.00    |
| 12 | TOYOTA WORDING <i>3 new</i>             | 1   | \$ 65.00    | \$ 65.00    |
| 13 | PREVIA WORDING <i>3 new</i>             | 1   | \$ 75.00    | \$ 75.00    |

TOTAL PRICE: \$ 4,313.50  
LESS 25% \$ 1,078.37  
SUB TOTAL PRICE: \$ 3,235.13

*1567.90*  
*1175.92*

## SPECIAL NETT ITEMS

|   | ITEMS                                       | QTY   | UNIT PRICE | TOTAL     |
|---|---------------------------------------------|-------|------------|-----------|
| 1 | REAR BUMPER CLIPS <i>new</i>                | 1 SET | \$ 30.00   | \$ 30.00  |
| 2 | REVERSE SENSOR <i>Damaged</i>               | 1 SET | \$ 280.00  | \$ 280.00 |
| 3 | REAR END PANEL TOP GARNISH CLIPS <i>new</i> | 1 SET | \$ 20.00   | \$ 20.00  |
| 4 | REAR END PANEL SEALANT <i>new</i>           | 1 SET | \$ 60.00   | \$ 60.00  |
| 5 | TAILGATE GLASS SEALANT <i>new</i>           | 1 SET | \$ 60.00   | \$ 60.00  |

*290*

TOTAL : \$ 450.00

#### LABOUR

|   | JOB                                   | PRICE                 | ADJUSTED COST | APPROVED |
|---|---------------------------------------|-----------------------|---------------|----------|
| 1 | PANEL BEATING, REMOVE AND REFIT PARTS | \$ <del>1000.00</del> | 600           |          |
| 2 | SPRAY PAINTING TO AFFECTED AREA       | \$ <del>1000.00</del> | 500           |          |
| 3 | WIRING CHECK                          | \$ <del>50.00</del>   | 30            |          |
| 4 | TO REMOVE REVERSE SENSOR              | \$ <del>100.00</del>  | 50            |          |
| 5 | TO REMOVE UPHOLSTERY                  | \$ <del>150.00</del>  | 60            |          |
| 6 | TO TRANSFER TAILGATE FITTINGS         | \$ 150.00             | X             |          |
| 7 | TO REMOVE TAILGATE GLASS              | \$ 180.00             | X             |          |
| 8 | TO REMOVE REAR CAMERA                 | \$ 100.00             | X             |          |

TOTAL: \$ ~~1,930.00~~  
2730

1240

#### ESTIMATE REPORT

TOTAL PARTS COST: \$ 3,685.13

TOTAL LABOUR COST: \$ ~~1,930.00~~ 2730

TOTAL REPAIR COST: \$ ~~5,615.13~~ 6415.13

#### APPROVED DETAILS

SURVEYOR:

CONTACT:

FAX:

PART BY PART / LUMP SUM:

NO. OF DAYS:

total: 2705.92

L/S: 2.11K

04 Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: