



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 7165X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	COVER ASSY-RR BUMPER	TO REPAIR SEE LABOUR	1,106.00	-
10	BUMPER COVER CLIP REAR	NOT NECESSARY	22.00	-
1	COVER-RR BUMPER LWR	TO REPAIR SEE LABOUR	228.00	-
	LESS 20% DISCOUNT		-271.20	-
			1,084.80	-
	<u>SPECIAL NETT ITEMS</u>			
1	PROTECTOR MAT (SN)	NOT NECESSARY	50.00	-
			50.00	-
	<u>LABOUR</u>			
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF COVER ASSY-RR BUMPER AND COVER-RR BUMPER LWR.		350.00	280.00
	SPRAYPAINT ON AFFECTED AREA.		300.00	250.00
			650.00	530.00
GRAND TOTAL			1,784.80	530.00
RECOMMENDED COST OF REPAIRS (CONFIRMED)				530.00

Report Ref No. NS/INC21001916/T1qd3n2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.