Our Job Ref No : 305452742			305452742		ENGINEERING				
Date 21.02.21			59	fortDelGro Engineering Pte Ltd oyang Drive Singapore 508969					
FINA	LIZAT	ION FOR	M		Fax	c: 6546 8156			
То	:		LKK		Fax				
Attn	: M	lr	TAUFIKE	1	_				
Vehic	cle Reg	g No. :	SHD7165X	CTPL	-	07.02.21			
The s	survey	and estin	nates of the repairs of	the above-mentione	ed vehicle are as follow	/s:-			
1.	The r	repair job	shall bill to:	NTU	C	GBA2381H			
2.	The f	finalized a	amount shall be:						
	(a)	Spare F	Parts after List discour	nt		\$17.6 0			
	(b)	Labour	Charges			\$530.00			
		Total fo	or Part-By-Part Repa	ir Cost		\$547.60 \$530			
	(c.)	Total fo	um Repair (if applicabl r Lumpsum repair cos umpsum Repair cost	t after Less:	20%				
3.	Estim								
	Wes			s Correct and Con	firmed if there is no r	eply from you within 7			
4	work	ing days							
4. 5.	work		your assistance.	1	We confirm the finalized amoun				
	work	k you for		1	finalized amoun				
	work Than	k you for		<u> </u>		t			
	Thank Signa	k you for	your assistance.	<u> </u>	finalized amoun	taufikh			
	Thank Signa Name	k you for sture :	your assistance.	<u> </u>	finalized amoun Signature: Name :	taufikh Taufikh			

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
Rental Rate P/Day		YES		
2. Loss of Income Paid		NO		
3. Survey Fees				
4. LTA Search Fee	\$7.49 / \$2.00			
Medical Fees (on behalf of driver, if applicable)				
6 Overrun				

Remarks:				

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 08.02.2 Time: 15:03:14

Page: 1

COMPANY: THIRD PARTY'S CLAIMS (CAS)

CUSTOMER: 7010045

ADDRESS: COMFORT TRANSPORTATION PTE LTD

383 SIN MING DRIVE

SINGAPORE SINGAPORE 575717

65508755

JOB NO

305452742

REGN NO MILEAGE SHD7165X 000000000

MAKE

HYUNDAI

MODEL

: I-40

DATE OF REGN

DATE/TIME IN

17.11.2016 **08.02.2021 10:15**

ACCIDENT DATE

07.02.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0103-0579-G COVER ASSY-RR BUMPER#

1 L 1,106.00 20.00 884.80

0002 04-01-0101-0111-G BUMPER COVER CLIP REAR

10 L 22.00 20.00 17.60 ₱≠₹≠= Xnn

0003 04-01-0103-0738-G COVER-RR BUMPER LWR#

1 L 228.00 20.00 182.40 RT

0004 04-01-0103-1150-A PROTECTOR MAT

1 N 50.00 2.00- 50.00 ⊀ nn

SUB-TOTAL : 1,134.80

JOB NATURE

0000 L

PANEL BEATING

350.00 280

0001 23-502

SPRAYPAINT ON AFFECTED AREA

SUB-TOTAL : 650.00

AUTHORISED: YES/NO

\$530

TOTAL : 1,784.80

2 days #

MVA NAME & SIGNATURE DATE:

SURVEYOR NAME & SIGNATURE

DATE:

ern after reperior

erys

[hhauto-som.

COMFORTDELGRO ENGINEERING PTE LTD

Date: 21.02.2021 Time: 15:39:34

REPAIR ESTIMATE

Page: 1

COMPANY: THIRD PARTY'S CLAIMS (CAS) JOB NO 305452742 : SHD7165X REGN NO **CUSTOMER: 7010045** MILEAGE : 0000000000 ADDRESS: COMFORT TRANSPORTATION PTE LTD HYUNDAI 383 SIN MING DRIVE MAKE

SINGAPORE SINGAPORE 575717

65508755

MODEL : I-40

DATE OF REGN : 17.11.2016 DATE/TIME IN : 08.02.2021 10:15

ACCIDENT DATE : 07.02.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0101-0111-G BUMPER COVER CLIP REAR 10 L 22.00 20.00 17.60

SUB-TOTAL: 17.60

JOB NATURE

0000 L PANEL BEATING

280.00

0001 23-502

SPRAYPAINT ON AFFECTED AREA

250.00

SUB-TOTAL: 530.00

TOTAL : 547.60

AUTHORISED: YES/NO

MVA NAME & SIGNATURE

SURVEYOR NAME & SIGNATURE

DATE: DATE: