



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Ref: CS3/LPC20005933/Evf3e2-1 Date: 24/02/2021 Code: LPC2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	XD 7467K	Veh. Inspected	SKN 3548M	
Policy No.		Coverage (\$)	0.00	
Claim No.	19/20/20/VC05/023360	Excess (\$)	0.00	
Assign From		Assign Date	09/02/2021	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	MERCEDES BENZ CLA200	c.c	1595	
Engine No.	HIDDEN	Year of Reg.	2014	
Chassis No.	WDD1173432N092302	Colour	GREY	
Odometer	123782 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	225/40 R18	BRIDGESTONE	5 mm	
L/H Front Tyre	225/40 R18	BRIDGESTONE	5 mm	
R/H Rear Tyre	225/40 R18	BRIDGESTONE	5 mm	
L/H Rear Tyre	225/40 R18	BRIDGESTONE	5 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	23/05/2020	Inspection Date	26/05/2020	
Survey held at	AKA AUTO PTE LTD 25 KAKI BUKIT ROAD 4, #05-36, SYNERGY @ KB, SINGAPORE 417800			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			6 Working Days	