

Estimate By
Workshop (S)

AIG

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



CARRIAGE

1977014696

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info														
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	<table> <tr> <td>Cust No/Name</td><td>KCV09804/BERENICE G LOW</td></tr> <tr> <td>Reg No/Reg Date</td><td>SMG3041X / 14/12/201</td></tr> <tr> <td>Date In/Mileage</td><td>/ 0</td></tr> <tr> <td>Chassis No</td><td>MMBSTA13AJH004410</td></tr> <tr> <td>Engine No</td><td>3A92UHK0848</td></tr> <tr> <td>Make/Model</td><td>MIT/18MY ATTRAGE 1.2 CVT</td></tr> <tr> <td>Colour/Trim</td><td>A06 COOL SILVER MET/ BK BLACK</td></tr> </table>	Cust No/Name	KCV09804/BERENICE G LOW	Reg No/Reg Date	SMG3041X / 14/12/201	Date In/Mileage	/ 0	Chassis No	MMBSTA13AJH004410	Engine No	3A92UHK0848	Make/Model	MIT/18MY ATTRAGE 1.2 CVT	Colour/Trim	A06 COOL SILVER MET/ BK BLACK
Cust No/Name	KCV09804/BERENICE G LOW														
Reg No/Reg Date	SMG3041X / 14/12/201														
Date In/Mileage	/ 0														
Chassis No	MMBSTA13AJH004410														
Engine No	3A92UHK0848														
Make/Model	MIT/18MY ATTRAGE 1.2 CVT														
Colour/Trim	A06 COOL SILVER MET/ BK BLACK														

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No	
KAX00008	Credit	09/02/2021/ 09:53	QUE	261 / Edwin Caina	62815	
Description of Goods / Services			Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW RR BUMPER & BOOTLID REPAIR / ALIGN RR END PNL , LHR FENDER & RHR FENDER 450.						✓ 1350 1800.00
E PNT98000 RESPRAY RR BUMPER , BOOTLID , RR END PNL , LHR FENDER & RHR FENDER 350.						✓ 1050 1750.00
E PNT88000 REMOVE & REFIT BOOTLID COMPONENT						✓ 120.00
E PNT88000 REMOVE & REFIT RR FLR BOARD,TRIM & CARPET						✓ 120.00
A 54900099 CHECK WIRING ELECTRICAL SYSTEM						✓ 30.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST						✓ 120.00
E PNT88000 REMOVE & REFIT REVERSE SENSOR						60 80.00
M SUNDRY SUPPLY REVERSE SENSOR						un. X 220.00
M SUNDRY SUPPLY C&C BADGE						nc ✓ 40.00
M SUNDRY Sundries						✓ 20.00
M	LAMP ASSY,COMB,RR LH		1.00	337	335.00 23.00	cut 257.95
M	LAMP ASSY,COMB,RR RH		1.00	337	335.00 23.00	cut 257.95
M	REFLECTOR RH		1.00		23.00 23.00	7X 17.71 X
M	FACE,RR BUMPER		1.00	751	748.00 23.00	for 575.96 X
M	CLIP,RR BUMPER		4.00		4.00 23.00	5 12.32 X
M	BRACKET,RR BUMPER,LH		1.00		28.00 23.00	X 21.56 X
M	BRACKET,RR BUMPER,RH		1.00		28.00 23.00	? 21.56 X
M	PANEL,TRUNK LID		1.00	795	791.00 23.00	bl. 609.07
M	LATCH,TRUNK LID		1.00		218.00 23.00	? 167.86 X
M	MARK,THREE-DIA		1.00	70	69.00 23.00	new 53.13
M	MARK,ATTRAGE		1.00		21.00 23.00	new 16.17

Estimate

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE



RIAGE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

ESTIMATE

GST Reg No : MR-8500111-X

97701469G

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name	KCV09804/BERENICE G LOW
	Reg No/Reg Date	SMG3041X / 14/12/201
	Date In/Mileage	/ 0
	Chassis No	MMBSTA13AJH004410
	Engine No	3A92UHK0848
	Make/Model	MIT/18MY ATTRAGE 1.2 CVT
	Colour/Trim	A06 COOL SILVER MET/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
KAX00008	Credit	09/02/2021/ 09:53	QUE	261 / Edwin Caina	62815			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M DECAL.MIVEC					1.00	36.00	23.00	27.72

Estimate

SURVEYOR NAME : Taufik 97495749

SURVEYOR SIGNATURE : [Signature]

DATE : 17/2/21 @ 1140

REMARKS : Not Authorise, Ex: tba
Resurvey before part 05 days 7 days
taufik @ hhand: con

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Confirm & accepted by

Acknowledged by Repairer

Signature:

Date:

	Nett	6,338.96
7% GST on	6338.96	443.73
Total Payable		6,782.69

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.