

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED PANDAN GARDENS CUSTOMER SERVICE CENTRE



209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

Co Reg No : 197701469G

ESTIMATE

/ to 1

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info		
AIG Asia Pacific Insurance Pte.	Cust No/Name	KCV09804/BERENICE G LOW	
Ltd.	Reg No/Reg Date	SMG3041X / 14/12/201	
MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING	Date In/Mileage	/ 0	
	Chassis No	MMBSTA13AJH004410	
SINGAPORE 079120	Engine No	3A92UHK0848	
Contact No 6419 1892	Make/Model	MIT/18MY ATTRAGE 1.2 CVT	
	Colour/Trim	A06 COOL SILVER MET/ BK BLACK	

Account No Terr	ns	Date/Time Printed	CSE	Operator		WIP No		
KAX00008 Cree	lit	09/02/2021/ 09:53	QUE	261 / Edwin Caina		62815		
B TO THE RESERVE AND A STREET OF THE STREET		Description of Goo	ds / Services		Qty	Unit Price	Disc%	Amount
E PNT98000 RESPRAY RR BU E PNT88000 REMOVE & REFI E PNT88000 REMOVE & REFI A 54900099 CHECK WIRING A 10028901 TO CARRY OUT USING HI-SCAN E PNT88000	MPEI T BO T RI ELEC PRO	B BOOTLID R END PNL , LHR FER R , BOOTLID , RR EN DOTLID COMPONENT R FLR BOARD, TRIM & CTRICAL SYSTEM GNOSTIC CHECKTUSING	NDER & RHR FE	FENDER & RHR FENDER	25°.			1350 1800.00 /050 ₁₇₅₀ .00 120.00 120.00 30.00 120.00 60 80.00
REMOVE & REFI M SUNDRY SUPPLY REVERSI M SUNDRY SUPPLY C&C BAI M SUNDRY SUNDRY SUNDRY SUNDRY ANDRY SUNDRY SUNDRY SUNDRY ALAMP ASSY, COMI M LAMP ASSY, COMI M REFLECTOR RH M FACE, RR BUMPER M CLIP, RR BUMPER M BRACKET, RR BUR M PANEL, TRUNK LI	E SE OGE 3,RR IPER IPER D	NSOR LH RH			1.00 1.00 1.00 1.00 4.00 1.00 1.00	335.00 23.00 748.00 4.00 28.00	23.00 23.00 23.00	
M LATCH, TRUNK L: M MARK, THREE-DIA M MARK, ATTRAGE Confirm & accepte	1	у	-		1.00 1.00 1.00		23.00 23.00 23.00	167.86 53.13 new 16.17

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED PANDAN GARDENS CUSTOMER SERVICE CENTRE

MITSUBISHI MOTORS

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

Co Reg No : 197701469G

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info		
AIG Asia Pacific Insurance Pte.	Cust No/Name	KCV09804/BERENICE G LOW	
Ltd.	Reg No/Reg Date	SMG3041X / 14/12/201	
MOTOR CLAIM DEPT	Date In/Mileage	/ 0	
78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Chassis No	MMBSTA13AJH004410	
	Engine No	3A92UHK0848	
	Make/Model	MIT/18MY ATTRAGE 1.2 CVT	
	Colour/Trim	A06 COOL SILVER MET/ BK BLACK	

Account No	Terms	Date/Time Printed	CSE	Operator		WIP No		
KAX00008	Credit	09/02/2021/ 09:53	QUE	261 / Edwin C	aina	62815		
		Description of Good	s / Services		Qty	Unit Price		Amount 27.72
M DECAL,MIV			SURVEYOR N SURVEYOR S DATE: REMARKS: -	SIGNATURE:	milh 9= miles 2 1140	<u>)</u> 7 947574° 	23.00	
		LKK Auto Cor the Repairer of • To resurvey bel • To display dam • Parts prices are • Third party surv • No lilegal modil	of the followin ore/after spray p aged part(s) during subject to confir ey is on a "Witho	g: ainting ng resurvey rmation out Prejudice* basis			-	
Confirm & acce	epted by	 Supplementary 	item(s) must be al approval from i		7% GST o		tt 96	6,338.96 443.73
Authorized sig	natory a	Date:				Total Payab	le	6,782.69

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.