



ComfortDelGro Engineering

320 UBI ROAD 3 SINGAPORE 408649

ACCIDENT REPAIR ESTIMATES

Our Ref:

Type of Claim : TP Vehicle No. : SLS5087A
 Make & Model : HONDA VEZEL
 Year of Manufacture : _____
 Chassis No. : RU31252265
 Engine No. : _____
 Policy No. : _____
 Date of Accident ## : 31/01/2021 Time of Accident : 17.10
 Suggested Days of Repair : _____ In-house Vehicle Assessor : _____

Repair Estimates

Parts (a) Cost / List Price Items \$ 3,192.35
 Plus/Less 20% \$ 638.47
 Total of Cost / List \$ 2,556.28 2553.88
 (b) Nett Price Items \$ -
 Less _____
 Total of Nett Item _____
 (c) Special Nett Items \$ 45.00
 Total Parts Cost (Appendix A) \$ 2,601.28
 Labour (Appendix B) \$ 1,970.00
 Total Repair Cost \$ 4,571.28 4568.88

68485725/26 - JOHARI / TINIE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

The above total will be subjected to 7% G.S.T.

Name of Surveyor : Guo Qiang 8288082
 Company : JLC
 Survey conducted on : 19/2/2021 at _____

Remarks By Surveyor

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair : 4 day(s)(c) Resurvey : Required / Not Required

(d) Excess : \$ _____

(e) Signature of surveyor : _____ Date: _____

part by part.

Before paint photos.

Guo

Car Parts

Vehicle No : SLS5087A Case Owner : _____
 Make & Model : HONDA VEZEL 1.5 Year Manufacture : _____
 Chassis No : RU31252263 Engine No : _____
 Sales Order : _____ Supplier : _____
 Order By : _____ Type of Claim : TP

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N	Disposition By Surveyor
1	HEAD LAMP RH ?	1	\$ 1,215.00				
2	HEAD LAMP BRACKET RH ?	1	\$ 28.60				
3	RHF FENDER X Repair	1	\$ 243.00				
4	RHF FENDER ARCH / re	1	\$ 60.75				
5	FRONT RADIATOR GRILLE ?	1	\$ 234.00				
6	FRONT RADIATOR GRILLE CHROME ?	1	\$ 256.50				
7	FRONT BUMPER / re	1	\$ 418.50				
8	FRONT BUMPER SPONGE ?	1					
9	FRONT BUMPER REINFORCEMENT ?	1	\$ 243.00				
10	FRONT BUMPER LOWER SPOILER X Repair	1	\$ 310.50				
11	RH FOG LAMP ?	1	\$ 162.00				
12	RH FOG LAMP COVER / re	1	\$ 20.50				
13	NUMBER PLATE X NN.	1				\$ 45.00	
14							
15							
16							
17							
18							
19							
20							
21							
22							
23							
24							
25							
26							
27							
28							
29							
30							

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

ComfortDelGro Engineering Pte Ltd

320 UBI ROAD 3 SINGAPORE 408649
Tel: 68438723/68438736 FAX : 67436072

Labour

Case Owner : _____

Year of Manufacture : _____

[illegible]

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.