



ComfortDelGro Engineering

320 UBI ROAD 3 SINGAPORE 408649

**ACCIDENT REPAIR ESTIMATES**

Our Ref:

Type of Claim : TP Vehicle No. : SLS5087A  
 Make & Model : HONDA VEZEL  
 Year of Manufacture : \_\_\_\_\_  
 Chassis No. : RU31252265  
 Engine No. : \_\_\_\_\_  
 Policy No. : \_\_\_\_\_  
 Date of Accident ## : 31/01/2021 Time of Accident : 17.10  
 Suggested Days of Repair : \_\_\_\_\_ In-house Vehicle Assessor

**Repair Estimates**

Parts (a) Cost / List Price Items \$ 3,192.35  
 Plus/Less 20% \$ 638.47  
 Total of Cost / List \$ 2,556.28  
 (b) Nett Price Items \$ -  
 Less \_\_\_\_\_  
 Total of Nett Item \_\_\_\_\_  
 (c) Special Nett Items \$ 45.00  
**Total Parts Cost (Appendix A)** \$ 2,601.28  
**Labour (Appendix B)** \$ 1,970.00  
**Total Repair Cost** \$ 4,571.28 1139.8

Case Owner : \_\_\_\_\_  
 Signature : \_\_\_\_\_  
 Contact No  
 68485725/26 - JOHARI / TINIE

LKK Auto Consultants hence notify the Repairer of the following:  
 • To resurvey before/after spray painting  
 • To display damaged part(s) during resurvey  
 • Parts prices are subject to confirmation  
 • Third party survey is on a "Without Prejudice" basis  
 • No illegal modification(s) is allowed  
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

The above total will be subjected to 7% G.S.T.

Name of Surveyor : Guo Qiang 8288082  
 Company : JLC  
 Survey conducted on : 19/2/2021 at \_\_\_\_\_  
 Remarks By Surveyor  
 (a) The repair of this vehicle is authorized / is not authorized until further notice.  
 (b) Recommended Days of Repair : 4 day(s)  
 (c) Resurvey : Required / Not Required  
 (d) Excess : \$ \_\_\_\_\_  
 (e) Signature of surveyor : \_\_\_\_\_ Date: \_\_\_\_\_

part by part.  
 before paint photos.  
 Guo

**pare Parts**

Vehicle No : SLS5087A Case Owner : \_\_\_\_\_  
 Make & Model : HONDA VEZEL 1.5 Year Manufacture : \_\_\_\_\_  
 Chassis No : RU31252263 Engine No : \_\_\_\_\_  
 Sales Order : \_\_\_\_\_ Supplier : \_\_\_\_\_  
 Order By : \_\_\_\_\_ Type of Claim : TP

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N	Disposition By Surveyor
1	HEAD LAMP RH <del>X</del> NN	1	\$ 1,215.00				
2	HEAD LAMP BRACKET RH <del>X</del> NN	1	\$ 28.60				
3	RHF FENDER <del>X</del> Repair	1	\$ 243.00				
4	RHF FENDER ARCH / <del>re</del>	1	\$ 60.75				
5	FRONT RADIATOR GRILLE <del>X</del> NN	1	\$ 234.00				
6	FRONT RADIATOR GRILLE CHROME <del>X</del> NN	1	\$ 256.50				
7	FRONT BUMPER / <del>re</del>	1	\$ 418.50				
8	FRONT BUMPER SPONGE <del>X</del> NN	1					
9	FRONT BUMPER REINFORCEMENT <del>X</del> NN	1	\$ 243.00				
10	FRONT BIMPER LOWER SPOILER <del>X</del> Repair	1	\$ 310.50				
11	RH FOG LAMP <del>X</del> NN	1	\$ 162.00				
12	RH FOG LAMP COVER / <del>re</del>	1	\$ 20.50				
13	NUMBER PLATE <del>X</del> NN	1				\$ 45.00	
14							
15							
16							
17							
18							
19							
20							
21							
22							
23							
24							
25							
26							
27							
28							
29							
30							

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

**ComfortDelGro Engineering Pte Ltd**

Tel: 68438723/68438736 FAX : 67436072

Vehicle No. : **SLS5087A**

Case Owner : \_\_\_\_\_

**Make & Model : HONDA VEZEL 1.5**

Year of Manufacture : \_\_\_\_\_

*Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.*