

SmartOne Auto Pte. Ltd.

Co. Reg No: 201939368E

8 Kaki Bukit Avenue 4

#08-09 Premier @ Kaki Bukit

Singapore 415875

Tel: 6341 6789 Fax: 6341 6778

Email: smartoneauto@gmail.com



DATE : 01.03.21

TO : AXA MOTOR CLAIMS DEPTS
VEHICLE NO : SMP7730S
MODEL : HYUNDAI AVANTE
DATE OF ACCIDENT : 04.02.21
TIME OF ACCIDENT : 10:25HRS

KMHD841CMLU997563

Cerilia

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR BUMPER <i>Rehnd</i>	1	\$ 459.40	\$ 459.40
2	REAR BUMPER LAMP RH <i>lit</i>	1	\$ 201.50	\$ 201.50
3	REAR BUMPER LAMP WIRE HARNESS <i>new</i>	1	\$ 121.00	\$ 121.00
4	REAR BUMPER CENTRE (BLACK) <i>lit</i>	1	\$ 353.50	\$ 353.50
5	REAR BUMPER RETAINER <i>new</i>	2	\$ 29.40	\$ 58.80
6	REAR BUMPER REINFORCEMENT <i>cracked</i>	1	\$ 294.80	\$ 294.80
7	REAR BUMPER REINFORCEMENT BRACKET <i>new</i>	2	\$ 5.00	\$ 10.00
8	REAR BUMPER BRACKET <i>new</i>	5	\$ 78.60	\$ 393.00
9	REAR BUMPER SIDE INNER LOWER GARNISH RH <i>torn</i>	1	\$ 37.20	\$ 37.20
10	REAR FENDER INNER COWLING (REAR) RH <i>new</i>	1	\$ 60.00	\$ 60.00
11	REAR FENDER INNER TRIM RH <i>new</i>	1	\$ 208.00	\$ 208.00
12	TAILLAMP RH <i>Rejis cracked</i>	1	\$ 1,052.10	\$ 1,052.10
13	TAILLAMP PANEL RH <i>Rejis Rejis Rejis</i>	1	\$ 193.10	\$ 193.10
14	REAR FENDER RH <i>Rejis</i>	1	\$ 1,892.00	\$ 1,892.00
15	REAR FENDER AIR VENT RH <i>new</i>	1	\$ 38.90	\$ 38.90
16	BOOTLID WEATHER STRIP <i>new</i>	1	\$ 92.50	\$ 92.50
17	REAR END PANEL <i>Rejis</i>	1	\$ 454.60	\$ 454.60
18	REAR END PANEL TOP GARNISH <i>new</i>	1	\$ 59.80	\$ 59.80
19	REAR BLIND SPOT RH <i>cracked</i>	1	\$ 1,249.60	\$ 1,249.60
20	REAR BLIND SPOT BRACKET RH <i>Best</i>	1	\$ 169.30	\$ 169.30
21	REAR BLIND SPOT WIRE HARNESS <i>new</i>	1	\$ 684.90	\$ 684.90

TOTAL PRICE \$ 8,084.00
LESS 20% \$ 1,616.80
SUB TOTAL PRICE \$ 6,467.20

3867.70

3094.16

TO : AXA MOTOR CLAIMS DEPTS
 VEHICLE NO : SMP7730S
 MODEL : HYUNDAI AVANTE
 DATE OF ACCIDENT : 04.02.21
 TIME OF ACCIDENT : 10:25HRS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR BUMPER CLIP (SET) <i>Nu</i>	1	\$ 80.00	\$ 80.00 <i>30</i>
2	TAIL LAMP CLIP (SET) <i>Nu</i>	1	\$ 40.00	\$ 40.00 <i>20</i>
3	TAILLAMP PANEL SEALANT RH <i>3 x 1</i>	1	\$ 60.00	\$ 60.00 <i>+</i>
4	REAR FENDER SEALANT RH <i>3 x 1</i>	1	\$ 150.00	\$ 150.00 <i>+</i>
5	REAR FENDER INNER COWLING CLIP (SET) <i>3 x 1</i>	1	\$ 80.00	\$ 80.00 <i>+</i>
6	REAR FENDER INNER TRIM CLIPS (SET) <i>3 x 1</i>	1	\$ 80.00	\$ 80.00 <i>+</i>
7	REAR END PANEL TOP GARNISH CLIP (SET) <i>3 x 1</i>	1	\$ 40.00	\$ 40.00 <i>+</i>
8	REAR END PANEL INSULATION SEALANT <i>3 x 1</i>	1	\$ 150.00	\$ 150.00 <i>+</i>
9	REAR WINDSCREEN SEALANT <i>3 x 1</i>	1	\$ 80.00	\$ 80.00 <i>+</i>
10	REAR WINDSCREEN INNER SHIELD <i>3 x 1</i>	1	\$ 60.00	\$ 60.00 <i>+</i>
11	REVERSE SENSOR <i>3 x 1</i>	1	\$ 220.00	\$ 220.00 <i>+</i>

50

TOTAL \$ 1,040.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 2,200.00	<i>600.</i>
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,800.00	<i>800.</i>
3	TUFF COAT	\$ 250.00	<i>60</i>
4	WIRING CHECK	\$ 180.00	<i>30</i>
5	REMOVE AND REFIX UPHOLSTRY AND ROOF LINNING TO FACILITATE REPAIR	\$ 350.00	<i>60.</i>
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	<i>50</i>
7	CONDUCT WATER LEAKAGE TEST	\$ 80.00	<i>x</i>
8	REMOVE AND REFIX REAR BLIND SPOT SENSOR	\$ 120.00	<i>50</i>
9	REMOVE AND REFIX REAR WINDSCREEN	\$ 120.00	<i>x</i>
10	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 250.00	<i>x.</i>

1650

TOTAL \$ 5,430.00

TO : **AXA** MOTOR CLAIMS DEPTS
VEHICLE NO : **SMP7730S**
MODEL : **HYUNDAI AVANTE**
DATE OF ACCIDENT : 04.02.21
TIME OF ACCIDENT : 10:25HRS

ESTIMATE REPORT

TOTAL PARTS COST : \$ 7,507.20
TOTAL LABOUR COST : \$ 5,430.00
TOTAL REPAIR COST : \$ 12,937.20

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.

PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

MICHELLE

SERVICE ADVISOR

MICHELLE

HP : 9856 4815

Adrian Lj
r/s 01/03/21.

OADmp. ✓

total: 4284.66

r/s: 3.8k ✓

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: