

ESTIMATE

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
TAN BOON SOO	Cust No/Name	/TAN BOON SOO
39 CROWHURST DRIVE	Reg No/Reg Date	SFT7710L / 07/12/201
SINGAPORE 557918	Date In/Mileage	/ 0
Contact No Mobile: 96561596	Chassis No	KNAF3416MK5022966
	Engine No	G4FGJH712643
	Make/Model	KIA/CERATO 1.6 A EX G333
	Colour/Trim	B4U GRAVITY BLUE / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CSM00081	Cash	09/02/2021/ 12:24		442 / CocoLu	28799			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000								2000.00
RENEW FRT FENDER LH, FRT DOOR LH, REAR DOOR LH, WINDMIRROR LH								
REPAIR SIDE SILL LH, REAR FENDER LH, REAR BUMPER								
E PNT88000								150.00
REMOVE & INSTALL FRT DOOR TRIMS AND GLASS								
E PNT88000								150.00
REMOVE & INSTALL REAR DOOR TRIMS AND GLASS								
E PNT98000								2450.00
SPRAY PAINT FOR FRT FENDER LH, FRT DOOR LH, REAR DOOR LH, SIDE SILL LH								
REAR FENDER LH, REAR BUMPER, WINDMIRROR LH								
B WHEELALIGNMENT								120.00
To Conduct Computerize Full Wheel Alignment								
M SUNDRY								60.00
TRANSFER FRT LEFT AND REAR LEFT RIM								
M SUNDRY								80.00
APPLY SEALANT FOR ACCIDNET PORTION								
A 90000001								30.00
CHECK WIRING & ELECTRICAL SYSTEM								
A 10028901								120.00
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST								
USING HI-SCAN PRO TEST								
M SUNDRY								20.00
Sundry								
A 90000001								300.00
RENEW FRT UNDER CARRIAGE								
M SUNDRY								360.00
SUPPLY FRT RIM LEFT								
M SUNDRY								360.00
SUPPLY REAR RIM LEFT								
P	PANEL-FENDER,LH				1.00	430.00	00.00	430.00
M	INSULATOR-FENDER LH				1.00	27.00	00.00	27.00
M	MIRROR ASSY-OUTSIDE RR VIEW,LH				1.00	559.00	00.00	559.00
P	PANEL ASSY-FRONT DOOR,LH				1.00	1277.00	00.00	1277.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE
 209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

**ESTIMATE**

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
TAN BOON SOO 39 CROWHURST DRIVE SINGAPORE 557918 Contact No Mobile: 96561596	Cust No/Name	/TAN BOON SOO
	Reg No/Reg Date	SFT7710L / 07/12/201
	Date In/Mileage	/ 0
	Chassis No	KNAF3416MK5022966
	Engine No	G4FGJH712643
	Make/Model	KIA/CERATO 1.6 A EX G333
	Colour/Trim	B4U GRAVITY BLUE / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
CSM00081	Cash	09/02/2021/ 12:24		442 / CocoLu	28799		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
M	HINGE ASSY-FRONT DOOR,LH			1.00	30.00	00.00	30.00
M	HINGE ASSY-DOOR LOWER,LH			1.00	27.00	00.00	27.00
M	MOULDING ASSY-FRT DR FRAME,LH			1.00	37.00	00.00	37.00
M	W/STRIP ASSY-FR DR BELT O/S LH			1.00	64.00	00.00	64.00
M	W/STRIP ASSY-FR DR SIDE LH			1.00	102.00	00.00	102.00
M	HANDLE ASSY-DOOR OUTSIDE,LH			1.00	164.00	00.00	164.00
M	PAD-FR DR O/S HDL HINGE,LH			1.00	5.00	00.00	5.00
M	COVER-FR DR O/S HDL LH			1.00	14.00	00.00	14.00
M	PAD-FR DR O/S HDL COVER,LH			1.00	5.00	00.00	5.00
M	BASE ASSY-FR DR O/S HANDLE LH			1.00	52.00	00.00	52.00
M	CHECKER ASSY-FRONT DOOR,LH			1.00	44.00	00.00	44.00
M	LATCH ASSY-FRONT DOOR,LH			1.00	400.00	00.00	400.00
M	GLASS ASSY-FRONT DOOR,LH			1.00	207.00	00.00	207.00
M	PANEL ASSY-FRONT DR MODULE,LH			1.00	241.00	00.00	241.00
M	PANEL ASSY-REAR DOOR,LH			1.00	1377.00	00.00	1377.00
M	GUARD ASSY-FRONT WHEEL,LH			1.00	95.00	00.00	95.00
M	HUB ASSY-FR WHEEL			1.00	436.00	00.00	436.00
M	BLACK TAPE-FR DR RR,LH			1.00	13.00	00.00	13.00
M	BLACK TAPE-RR DR FR,LH			1.00	13.00	00.00	13.00
M	BLACK TAPE-RR DR FRAME RR OTR,			1.00	8.00	00.00	8.00
M	GLASS ASSY-REAR DOOR,LH			1.00	181.00	00.00	181.00
M	MOULDING ASSY-RR DR FRAME,LH			1.00	44.00	00.00	44.00

Confirm & accepted by

Nett	12,052.00
7% GST on	843.64
Total Payable	12,895.64

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.