



AIGAsia Insured's Veh No : SKZ6596R

Date of Accident : 22 January 2021

TAN LIM MOTOR PTE LTD

1 Defu Lane 6 Singapore 539365

Tel : 68585151 (24 Hours) Fax : 68580877

GST Regn. No. : M2-8922054-2

Messrs Semgas (S) Pte Ltd

Date : 02 February 2021

LKK - Taufik

Estimate To Repair GBB1685H - Toyota Dyna 150 Manual

Chassis No : JTFAT35Y103001904

S/No	Quantity	Description	Amount
01		<u>LABOUR & MISC. CHARGES</u>	
		Panel beating, knocking and straighten the necessary portion.	\$ 200.00
02		remove and renewal of parts, adjust and realign the same.	\$ 250.00
		Putty and spray painting of the affected portion.	\$ 450.00
			150 350.00
		Total	\$ 450.00

Taufik 9749 5744

up 9/1/21 @ 10.00

2 days

Resurvey after repair

taufik @ lkkauto.com

M/S. A. T. Y.

PRS \$350.00 ✓

p/78350 2 day

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: