



TRANS EUROKARS PTE LTD



ESTIMATE COST OF REPAIRS

CHINA TAIPING INSURANCE P/L		NAME : Mr Gomathinayagam Kandasami	WIP : 47659
3 ANSON ROAD		ADDRESS : 8 Rivervale Link	EXCESS :
#16-00 SPRINGLEAF TOWER		#02-14	DATE: 11-Feb-21
SINGAPORE 079909		Singapore 545043	
ATTN. :	MOTOR CLAIMS	TEL : 85002416	
FAX :			
VEH NO :	SMH502Y	DATE IN :	CONTACT PERSON : RONALD
CHASSIS NO :	JM6TC2WLAK0307586	MILEAGE :	TYPE OF CLAIM : THIRD PARTY CLAIM
MODEL :	MAZDA CX9	DATE REG.: 9-Jan-19	POLICY NO. :

NATURE OF WORKS

Parts Description

NO	DESCRIPTION	PARTS NO	QTY	1st	Supp	REVISED	PRICES
1	GRILLE TOP	MTK48-50-7E1D2M	1			\$ 414.60	\$ 414.60
2	RIVET,GRILLE TOP	MS51S-51-833	11			\$ 44.00	\$ 44.00
3	RIVET, GRILLE TOP	MBN8F-50-355	5			\$ 28.50	\$ 28.50
4	BUMPER GRILLE	MTN57-50-710C	1			\$ 2,228.70	\$ 2,228.70
5	FRONT BUMPER	MTK49-50-031JBB	1				\$ 1,244.00
6	FOG LAMP COVER LH INNER	MTK49-50-C21C	1				\$ 45.80
7	FOG LAMP COVER RH INNER	MTK49-50-C11C	1				\$ 45.80
8	FASTENER, REINFORCEMENT	MGD7A-50-EA1	4				\$ 12.80
9	STIFF 'A' FRONT BUMPER	MTK48-50-0S0	1				\$ 202.30
10	RIVET, FRONT BUMPER	MEA01-50-037	2			\$ 16.00	\$ 16.00
11	CHROME CENTER TC	MTK51-50-120B	1			\$ 271.30	\$ 271.30
12	GUARD(R), FRONT BUMPER	MTK50-50-120A	1				\$ 162.80
13	GUARD(L),FRONT BUMPER	MTK50-50-130A	1				\$ 162.80
14	RETAINER, FRONT BUMPER	MTK48-50-0T1B	1				\$ 18.10
15	RETAINER, FRONT BUMPER	MTK48-50-0U1B	1				\$ 18.10
16	PLATE,SET	MTK48-50-1C0A	1				\$ 104.90
17	FOAM,BUMPER REINFORCEMENT	MKD53-50-111	1				\$ 99.10
18	CLIP, BUMPER REINFORCEMENT	MGS1E-56-496A	2			\$ 20.40	\$ 20.40
19	CLIP, BUMPER REINFORCEMENT	MC274-50-133	15				\$ 55.50
20	TOWING COVER	MTK48-50-A12 BB	1				\$ 3.20
21	BRACKET(R),FRONT BUMPER	MTK48-50-153B	1				\$ 14.60
22	BRACKET(L),FRONT BUMPER	MTK48-50-163B	1				\$ 14.60
23	FOG LAMP COVER RH OUTER	MTK78-50-C11B	1				\$ 30.00
24	FOG LAMP COVER LH OUTER	MTK78-50-C21B	1				\$ 30.00
25	FRONT BUMPER REINFORCEMENT	MTK48-50-070	1				\$ 853.80
26	UNDERCOVER	MTK48-56-11Y	1				\$ 90.90
27	FASTENER, FRONT BUMPER	MB45A-56-146A	10			\$ 30.00	\$ 30.00
28	FASTENER, PLATE SET	MFD01-68-AC3	2				\$ 12.40
29	HEADLAMP RH	MTK59-51-031K	1				\$ 4,322.40
30	HEADLAMP LH	MTK59-51-041K	1				\$ 4,322.40

						TOTAL PARTS	\$ 3,053.50	\$ 14,919.80
						TOTAL PARTS COST	\$ 3,053.50	\$ 14,919.80

SUPPLEMENTARY

NO	DESCRIPTION	PARTS NO	QTY	1st	Supp	REVISED	PRICES
1							
2							
3							
						TOTAL PARTS	\$ -
						TOTAL PARTS COST	\$ -

Labour Description

1		TO REPLACE FRONT BUMPER, FRONT REINFORCEMENT, GRILLE TOP AND ALL AREAS AFFECTED BY THE ACCIDENT.				\$ 660.00	\$ 2,640.00
2		TO RESPRAY FRONT BUMPER, FRONT REINFORCEMENT, GRILLE TOP AND ALL AREAS AFFECTED BY THE ACCIDENT.				\$ 630.00	\$ 2,520.00
3	MZ-BR-FRTSEN	TO TRANSFER FRONT PEDESTRIAN SENSORS.				\$ 200.00	\$ 315.00
11	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.				\$ 120.00	\$ 250.00
12	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.				\$ 150.00	\$ 350.00
16	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION.(INCLUDING NEW PARTS AND CAOUTCHOU)					\$ 250.00
19	MZ-BR-SUNDRI	SUNDRIES.				\$ 20.00	\$ 100.00

TOTAL LABOUR	\$ 1,780.00	\$ 6,425.00
TOTAL PARTS	\$ 3,053.50	\$ 14,919.80
TOTAL	\$ 4,833.50	\$ 21,344.80
LESS EXCESS	\$ -	\$ -
TOTAL AFTER EXCESS	\$ 4,833.50	
GST 7%	\$ 338.35	\$ -
GRAND TOTAL	\$ 5,171.85	\$ -

SUPPLEMENTARY LABOUR DESCRIPTION

1		#N/A						
2		#N/A						
						TOTAL LABOUR	\$ -	\$ -

TOTAL PARTS	\$ -	\$ -
TOTAL	\$ -	\$ -
LESS EXCESS	\$ -	\$ -
TOTAL AFTER EXCESS	\$ -	
GST 7%	\$ -	\$ -
GRAND TOTAL	\$ -	\$ -

TRANS EUOKARS PTE LTD

REMARKS:

*THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A **QUOTATION FEE OF \$400** WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.*

Authorised Signature