



Date of Accident : 08 February 2021

1 Defu Lane 6 Singapore 539365
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

Date : 08 February 2021

Lab - Tarfile

Chassis No : KNAF3416ML5054644

S/No	Quantity	Description	Amount
		<u>LIST ITEMS</u>	
01	1 pc	front bumper	\$ 575.00
02	8 ps	front bumper clips @ \$4.50	\$ 36.00
03	1 pc	front bumper centre grille	\$ 155.00
04	1 pc	front bumper fog lamp n/s	\$ 140.00
05	1 pc	front bumper day light n/s	\$ 185.00
06	1 pc	front bumper daylight inch n/s	\$ 65.00
07	1 pc	front bumper side retainer n/s	\$ 18.00
08	1 pc	headlamp n/s	\$ 686.00
09	1 pc	n/s front wheel bearing	\$ 108.00
		Less 20 %	
		<u>SPECIAL NETT ITEMS</u>	
10	1 pc	n/s front spot rim	\$ 450.00
		<u>LABOUR & MISC. CHARGES</u>	
01		To transfer of tyre, rim and on wheel balancing.	\$ 60.00
02		To drop front suspension undercarriage parts, remove and renewal of the necessary parts, to perform final checking and testing.	\$ 180.00
03		To check steering geometry and computer wheel alignment.	\$ 120.00
04		To check electrical lighting concerned.	\$ 120.00
05		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 500.00
06		Putty and spray painting of the affected portion.	\$ 400.00
		Total	\$ 1,380.00
			\$ 3,404.40

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Taufik 97495749 / 62583561

WP' 9/2/21 @ 1045

03 days

Resurvey new parts

taufik@lkkauto.com

1056.40

458850

3 days