

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: ECICS Limited
10 Eunos Road 8
#09-04A Singapore Post Centre
Singapore 408600

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Liu Chun Cheong

Date: 07 Apr 2021

Preliminary Advice

Insured Vehicle No	: SJL199D	Accident Date	: 04/02/2021
TP Vehicle No	: SJY1147D	Assignment Date	: 09/02/2021
Make	: TOYOTA C-HR	Est. Duration of Repair	: 2
Date of Inspection	: 08/03/2021		
Inspection At	: MY CAR CONSULTANT PTE LTD (JALAN LAM HUAT) (HQ) 60 JALAN LAM HUAT, CARROS CENTRE #05-21 SINGAPORE 737869		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	18,840.96
Revised Amount	:S\$	925.50
Check Items (Estimated)	:S\$	0.00
Total	:S\$	925.50

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :