

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: ERGO Insurance Pte. Ltd.
8 Temasek Boulevard
#04-01 Suntec Tower Three
Singapore 038988

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn:

Date: 19 Mar 2021

Preliminary Advice

Insured Vehicle No : GBK2363H
TP Vehicle No : SKW2222L
Make : HONDA ACCORD
Date of Inspection : 09/02/2021
Inspection At : CAS GARAGE PTE LTD (HQ)
NO.1, KAKI BUKIT AVE 6, #02-22 AUTOBAY
SINGAPORE 417883

Accident Date : 08/02/2021
Assignment Date : 11/02/2021
Est. Duration of Repair : 7

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

| | | |
|-----------------------------|------|-----------|
| Repairer's Estimate (Gross) | :S\$ | 17,965.68 |
| Revised Amount | :S\$ | 6,398.00 |
| Check Items (Estimated) | :S\$ | 0.00 |
| Total | :S\$ | 6,398.00 |
| | | |
| Lump Sum Repair | :S\$ | 5,100.00 |

Total Loss Consideration

| | |
|--------------------|------|
| New for Old Value | :S\$ |
| Pre-Accident Value | :S\$ |
| COE / PARF Rebate | :S\$ |
| Salvage Value | :S\$ |
| Margin for Repair | :S\$ |

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Survey on WP