



1 Kaki Bukit Ave 6, # 02-22/21/20 @ Autobay Blk D Singapore 417883  
 Company GST Registration No : 201828067M

**VEHICLE INSPECTION ESTIMATE**

M/S : Ergo Insurance Pte Ltd  
 (MOTOR CLAIM DEPARTMENT)

Email ergoinsurance@ergo.com.sg

|             |  |
|-------------|--|
| Parts - (%) |  |
| SN          |  |
| Labour      |  |
| Lump sum    |  |
| ERV         |  |

Vehicle No: SKW2222L *Denise* Date: 08.02.2021  
 Veh Model : MAZDA 3 Reg Date : 26.11.2015  
 Chassis No : JM6BM42A8G0322526 D.O.A : 08.02.2021

|    |   |   |            |
|----|---|---|------------|
| 1  | LH Headlamp Assy <i>new</i>                       | 1 | + 2,357.30 |
| 2  | LH Side Mirror Assy <i>new</i>                    | 1 | ✓ 399.30   |
| 3  | LH Side Mirror Glass <i>missing</i>               | 1 | ✓ 120.00   |
| 4  | LH Side Mirror Back Cover <i>missing</i>          | 1 | ✓ 152.00   |
| 5  | LH Side Mirror Signal Lamp <i>lit</i>             | 1 | ✓ 127.00   |
| 6  | Front Bumper <i>new</i>                           | 1 | + 1,083.30 |
| 7  | Front Fender LH <i>Repair</i>                     | 1 | + 180.60   |
| 8  | Front Fender Cowling LH <i>new</i>                | 1 | + 141.90   |
| 9  | Front LH Door Pillar <i>Repair</i>                | 1 | + 985.70   |
| 10 | Front LH Door <i>Dented</i>                       | 1 | ✓ 1,200.40 |
| 11 | Front LH Door Hinges <i>new</i>                   | 2 | + 64.10    |
| 12 | Front LH Door Lock <i>new</i>                     | 1 | + 284.00   |
| 13 | Front LH Door Quarter Garnish <i>new</i>          | 1 | + 148.80   |
| 14 | Front LH Door Upper Black Garnish <i>lit</i>      | 1 | ✓ 187.70   |
| 15 | Front LH Door Outer Chrome Moulding <i>Dented</i> | 1 | ✓ 187.70   |
| 16 | Front LH Door Black Garnish <i>lit</i>            | 1 | ✓ 138.50   |
| 17 | Front LH Door Outer Handle <i>Dented</i>          | 1 | ✓ 249.40   |
| 18 | Front LH Door Mechanisms Cover <i>Repair</i>      | 1 | + 68.00    |
| 19 | Front LH Door Handle Bracket <i>new</i>           | 1 | + 108.70   |
| 20 | Front LH Door Weather Strip <i>new</i>            | 1 | + 161.70   |

**8,346.10**

CF **8,346.10**



1 Kaki Bukit Ave 6, # 02-22/21/20 @ Autobay Blk D Singapore 417883  
 Company GST Registration No : 201828067M

**VEHICLE INSPECTION ESTIMATE**

**B/F 8,346.10**

|    |   |   |  |            |
|----|---|---|--|------------|
| 21 | Front LH Door Frame Weatherstrip <i>3/4</i>     | 1 |  | + 163.80   |
| 22 | Front LH Door Trim Board <i>3/4</i>             | 1 |  | + 1,050.60 |
| 23 | Front LH Door Window Glass <i>cut</i>           | 1 |  | ✓ 324.60   |
| 24 | Front LH Door Window Regulator <i>3/4</i>       | 1 |  | + 175.60   |
| 25 | Front LH Door Window Regulator Motor <i>3/4</i> | 1 |  | + 162.00   |
| 26 | Rear LH Door <i>Dented</i>                      | 1 |  | ✓ 1,049.30 |
| 27 | Rear LH Door Hinges <i>3/4</i>                  | 2 |  | + 68.30    |
| 28 | Rear LH Door Lock <i>3/4</i>                    | 1 |  | + 238.70   |
| 29 | Rear LH Door Upper Black Garnish                | 1 |  | + 187.70   |
| 30 | Rear LH Door Outer Chrome Moulding <i>cut</i>   | 1 |  | ✓ 187.70   |
| 31 | Rear LH Door Black Garnish <i>not cut</i>       | 1 |  | ✓ 138.50   |
| 32 | Rear LH Door Outer Handle <i>Reps</i>           | 1 |  | + 139.00   |
| 33 | Rear LH Door Cap Cover <i>Reps</i>              | 1 |  | + 78.20    |
| 34 | Rear LH Door Handle Bracket <i>2</i>            | 1 |  | + 99.90    |
| 35 | Rear LH Door Weather Strip <i>not</i>           | 1 |  | + 178.60   |
| 36 | Rear LH Door Frame Weatherstrip <i>3/4</i>      | 1 |  | + 165.50   |
| 37 | Rear LH Door Trim Board <i>3/4</i>              | 1 |  | + 782.30   |
| 38 | Rear LH Door Window Glass <i>not</i>            | 1 |  | + 349.70   |
| 39 | Rear LH Door Window Regulator <i>7</i>          | 1 |  | + 178.80   |
| 40 | Rear LH Door Window Regulator Motor <i>3/4</i>  | 1 |  | + 162.50   |
| 41 | Rear LH Door Glass Quarter Garnish <i>3/4</i>   | 1 |  | ✓ 93.60    |
| 42 | Rear Fender LH <i>Reps</i>                      | 1 |  | + 1,233.00 |
| 43 | Rear Fender Fuel Filling Cover <i>Reps</i>      | 1 |  | + 123.50   |
| 44 | Rear Fender Cowling LH <i>NE</i>                | 1 |  | + 193.10   |
| 45 | LH Tail Lamp <i>cut</i>                         | 1 |  | ✓ 866.80   |
| 46 | Rear Bumper <i>Reps</i>                         | 1 |  | + 996.70   |

17,734.10

less 20% 3,546.82

**14,187.28**

5402.50

4338

**C/F 14,187.28**



1 Kaki Bukit Ave 6, # 02-22/21/20 @ Autobay Blk D Singapore 417883  
 Company GST Registration No : 201828067M

**VEHICLE INSPECTION ESTIMATE**

**B/F 14,187.28**

**Special nett item**

|   |   |       |         |
|---|---|-------|---------|
| 1 | Front Bumper Clips <i>3 set</i>         | 1 set | + 30.00 |
| 2 | Front Fender Cowling Clips <i>1 set</i> | 1 set | + 30.00 |
| 3 | Front LH Door Edge Protector <i>1</i>   | 1     | + 28.00 |
| 4 | Rear LH Door Edge Protector <i>1</i>    | 1     | + 28.00 |
| 5 | Rear Fender Cowling Clips <i>1 set</i>  | 1 set | + 30.00 |
| 6 | Rear Bumper Clips <i>1 set</i>          | 1 set | + 30.00 |

176.00

Less 10% 17.60

**158.40**

**B/F 14,345.68**

|   |                      |
|---|----------------------|
| To panel beat/straighten/realign accident affected portion. | <i>6W</i> 800.00     |
| To respray accident affected portion.                       | <i>1300</i> 2,100.00 |
| To remove/refix/transfer both LH door mechanisms items      | <i>160</i> 500.00    |
| To conduct water leak test.                                 | + 100.00             |
| To remove/refix rear reverse sensor                         | + 120.00             |
|   | <b>17,965.68</b>     |

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

*2060*

*Adrian Lij  
 1/s - 09/02/21*

*07 days*

*to Carl: 6398  
 Llc: S.I.K.*