

Our Job Ref No : 305452238

Date : 21.02.21

COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To : LKK

Fax :

Attn : Mr TAUFIKH

Vehicle Reg No. : SHC3372X CTPL

04.02.21

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: NTUC --- GBB7669G

2. The finalized amount shall be:

(a) Spare Parts after List discount

(b) Labour Charges

Total for Part-By-Part Repair Cost

(c.) Lumpsum Repair (if applicable)

Total for Lumpsum repair cost after Less:

20%

\$1,200.00

Final Lumpsum Repair cost

\$1,200.00

3. Estimated normal period for repairs: 2 working days.

4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**

5. Thank you for your assistance.

We confirm the estimates and
finalized amount

Signature : 

Name : LIM KWOK ENG

Tel : 62148316

Fax : 65468156

Signature : 

Name : Taufikh

Date : 6/3/21

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		NO		
3. Survey Fees				
4. LTA Search Fee	\$7.49 / \$2.00			
5. Medical Fees (on behalf of driver, if applicable)				
6 Overrun				

Remarks:

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305452238
 REGN NO : SHC3372X
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : I-40
 DATE OF REGN : 21.04.2016
 DATE/TIME IN : 04.02.2021 16:55
 ACCIDENT DATE : 04.02.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0103-0579-G	COVER ASSY-RR BUMPER#	1 L	1,106.00	20.00	884.80	de
0002 04-01-0101-0111-G	BUMPER COVER CLIP REAR	10 L	22.00	20.00	17.60	net
0003 04-01-0103-0738-G	COVER-RR BUMPER LWR#	1 L	228.00	20.00	182.40	Rp
0004 09-01-9999-0068-A	REVERSE SENSOR ASSY*	1 N	135.70	10.00	122.13	? Xnn
0005 04-01-0103-1150-A	PROTECTOR MAT	1 N	50.00	1.00	50.00	net

SUB-TOTAL : 1,256.93

1,128
 -20%
 902.40
 + Net 50
 952.40

JOB NATURE

0000 L	PANEL BEATING	350.00	280
0001 23-502	SPRAYPAINT ON AFFECTED AREA	300.00	250
0002 20-22	REMOVE/REFIX REVERSE SENSOR	80.00	50

SUB-TOTAL : 730.00

Tanpin 174 15749
 - wp 5/2/21 @ 8pm

2 days

Duration

40 Rising after repair #1,200/-
 Tanpin & 1 hour