

**Note: This document has not been finalised.****LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: ECICS Limited  
10 Eunos Road 8  
#09-04A Singapore Post Centre  
Singapore 408600From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn:

Date: 02 Mar 2021

**Preliminary Advice**

Insured Vehicle No	: SLS7063E		
TP Vehicle No	: SME8525U	Accident Date	: 06/02/2021
Make	: VOLVO S40	Assignment Date	: 09/02/2021
Date of Inspection	: 09/02/2021	Est. Duration of Repair	: 8
Inspection At	: MY CAR CONSULTANT PTE LTD ( JALAN LAM HUAT ) (HQ) 60 JALAN LAM HUAT, CARROS CENTRE #05-21 SINGAPORE 737869		

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	20,605.12
Revised Amount	:S\$	8,785.76
Check Items (Estimated)	:S\$	0.00
Total	:S\$	8,785.76
 Lump Sum Repair	 :S\$	 7,000.00

**Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

**Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( ) Other comments :