

(08/11/13) wef

ASS. REC. BY: *Marcus*

REF:

CS/1521001953/49d3

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

Consistent? : Yes or No

Consistent? : Yes or No

Res.: Yes or No

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

Veh No:

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Rear

R/Bal.

L/Bal.

D.O.I.

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)

☐
☐

: Preli. Report

: Final Report

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

____ S + RS ____ SI

) Photos

) Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$

MEP-TR

7000

25/2/21 2/5 @ 7000 Confirmed with Repairer (Red \$13605.12, 66%)

07/3/21 @ 11.45am revised to ECICS via Meimien.

MY CAR CONSULTANT PTE LTD

Reg no.: 201505878Z

Address: NO:60 JALAN LAM HUAT CARROS CENTRE #05-68 S737869

HP: 98888885

Estimation

Date:

8/2/2021

Vehicle:

SME8525U

Make / Model:

HYUNDAI ELANTRA S

Chassis No:

No.	Description	Unit	Unit Price	Amount
Parts Replacement:				
1	REAR BUMPER	1	\$ 598.00	\$ 598.00
2	REAR BUMPER SIDE RETAINER	2	\$ 54.20	\$ 108.40
3	REAR BUMPER BRACKET	5	\$ 19.80	\$ 99.00
4	REAR BUMPER REFLECTOR	2	\$ 198.00	\$ 396.00
5	REAR BUMPER REINFORCEMENT	1	\$ 354.20	\$ 354.20
6	REAR BUMPER REINFORCEMENT SPONGE	1	\$ 187.00	\$ 187.00
7	BOOTLID	1	\$ 1,728.00	\$ 1,728.00
8	BOOTLID LAMP	2	\$ 298.00	\$ 596.00
9	BOOTLID LOCK DETECTOR	2	\$ 315.50	\$ 631.00
10	BOOTLID EMBLEM 'ELANTRA'	1	\$ 68.40	\$ 68.40
11	BOOTLID EMBLEM 'S'	1	\$ 35.20	\$ 35.20
12	BOOTLID LOGO	1	\$ 52.00	\$ 52.00
13	BOOTLID TOP LOCK	1	\$ 298.00	\$ 298.00
14	BOOTLID WEATHERSTRIP	1	\$ 214.00	\$ 214.00
15	BOOTLID INNER TRIM	1	\$ 312.00	\$ 312.00
16	BOOTLID HINGES	2	\$ 198.00	\$ 396.00
17	BOOTLID NUMBER PLATE LAMP	2	\$ 48.00	\$ 96.00
18	BOOTLID OUTER OPENER SENSOR	1	\$ 312.00	\$ 312.00
19	TAILAMPS	2	\$ 896.00	\$ 1,792.00
20	TAILAMP PANEL	2	\$ 258.00	\$ 518.00
21	TAILAMP LOWER BRACKET	2	\$ 68.00	\$ 136.00
22	REAR FENDER	2	\$ 785.00	\$ 1,570.00
23	REAR FENDER INNER TRIM	2	\$ 387.00	\$ 774.00
24	REAR FENDER COWLING	2	\$ 187.00	\$ 374.00
25	REAR END PANEL	1	\$ 580.20	\$ 580.20
26	REAR END PANEL TOP GARNISH	1	\$ 258.00	\$ 258.00
27	REAR FLOOR PANEL	1	\$ 1,125.00	\$ 1,125.00
28	REAR FLOOR PANEL TOP BOARD	1	\$ 338.00	\$ 338.00
29	REAR FLOOR PANEL TOOLS BOX SPONGE	1	\$ 254.00	\$ 254.00
30	REAR UNDER COVER RH	1	\$ 98.00	\$ 98.00
31	REAR UNDER COVER LH	1	\$ 198.00	\$ 198.00
32	REAR EXHAUST PIPE	1	\$ 985.00	\$ 985.00
33	REAR EXHAUST PIPE MOUNTING	2	\$ 45.00	\$ 90.00
34	REAR EXHAUST PIPE HET SHIELD	1	\$ 210.00	\$ 210.00
				\$ 15,781.40
Less 20%				\$ 3,156.28
Total				\$ 12,625.12
S/Nett items:				
1	REAR NUMBER PLATE	1	\$ 50.00	\$ 50.00

* Submit to insurance not Authorized

the

9/1/21

1/5 87000

the photo after repair

8 days.

559.40

100 75.20

294.50

165

536

48.80

35.20

48.00

166.00

116.20

204.80

1132.40

100 232.40

100 288.30

100 115.20

399.40

168.20

315.00

40

2	REAR NUMBER PLATE GARNISH	1	\$ 50.00	\$ 50.00	X
3	REAR BUMPER CLIPS SET	1	\$ 50.00	\$ 50.00	✓
4	REAR BUMPER LOWER SPORTS SPOILER	1	\$ 1,500.00	\$ 1,500.00	650
5	BOOTLID SEALANT	1	\$ 100.00	\$ 100.00	X
6	BOOTLID INSULATOR CLIPS SET	1	\$ 30.00	\$ 30.00	✓
7	BOOTLID SPOILER	1	\$ 600.00	\$ 600.00	X
8	REAR END PANEL SEALANT	1	\$ 100.00	\$ 100.00	50
9	REAR END PANEL TOP GARNISH CLIPS SET	1	\$ 30.00	\$ 30.00	X
10	TAILAMP CLIPS	1	\$ 30.00	\$ 30.00	X
11	TAILAMP SEALANT	2	\$ 60.00	\$ 120.00	X
12	REAR FENDER INNER TRIM CLIPS SET	1	\$ 60.00	\$ 60.00	X
13	REAR FENDER INNER COWLING CLIPS SET	1	\$ 60.00	\$ 60.00	X
14	REAR FLOOR PANEL INSULATION SEAL	1	\$ 150.00	\$ 150.00	X
15	REVERSE CAMERA	1	\$ 350.00	\$ 350.00	X
16	REAR REVERSE SENSOR	1 set	\$ 200.00	\$ 200.00	✓
				\$ 3,480.00	
Labour to:					
1	TO CHECK ELECTRICAL WIRING	1	\$ 150.00	\$ 150.00	30
2	CONDUCT FULL WHEEL ALIGNMENT	1	\$ 150.00	\$ 150.00	X
3	REMOVE AND REFIX REAR REVERSE SENSOR	1	\$ 150.00	\$ 150.00	50
4	REMOVE AND REFIX BOOTLID MECHANISM	1	\$ 100.00	\$ 100.00	60
5	REMOVE AND REFIX EXHAUST SYSTEM	1	\$ 100.00	\$ 100.00	X
6	TO RESPRAY UNDERCOATING	1	\$ 150.00	\$ 150.00	80
7	APPLY ANTI RUST ON AFFECTED AREAS	1	\$ 100.00	\$ 100.00	
8	SPRAY PAINTING ON AFFECTED AREAS	1	\$ 1,800.00	\$ 1,800.00	1200
9	PANEL BEATING ON AFFECTED AREAS	1	\$ 1,800.00	\$ 1,800.00	1100
				\$ 4,500.00	
			Parts Replacement Amount	\$ 16,105.12	
			Total Amount for Labour	\$ 4,500.00	
			Total Amount	\$ 20,605.12	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-6557-20
29%
P-5244-76
S-N-1020
L-2520
8784-16
2028