

TO : **AIG** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SMR339A**
 MODEL : **HONDA VEZEL**
 DATE OF ACCIDENT : 07.02.21
 TIME OF ACCIDENT : 12:15HRS

28	BUZZER <i>New</i>	1	\$ 109.00	\$ 109.00	+
29	REAR END PANEL <i>Deved</i>	1	\$ 530.00	\$ 530.00	✓
30	REAR END PANEL TOP GARNISH <i>could</i>	1	\$ 121.00	\$ 121.00	✓
31	REAR FLOOR PANEL BOTTOM GARNISH <i>could</i>	1	\$ 269.00	\$ 269.00	✓
32	REAR FLOOR PANEL TOP BOARD <i>Deved</i>	1	\$ 300.40	\$ 300.40	✓
33	REAR STORAGE BOX <i>could</i>	1	\$ 495.00	\$ 495.00	✓ 285
34	FRONT DRIVER SEAT <i>Best</i>	1	\$ 2,654.00	\$ 2,654.00	1200/sn)

6881-40 S/N: 1700
 5505-12

TOTAL PRICE	\$ 13,937.10
LESS 20%	\$ 2,787.42
SUB TOTAL PRICE	\$ 11,149.68

SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	REAR NUMBER PLATE <i>New</i>	1	\$ 80.00	\$ 80.00	+
2	REAR BUMPER CLIPS (SET) <i>New</i>	1	\$ 80.00	\$ 80.00	30
3	REAR BUMPER TOP PROTECTOR (SPECIAL TYPE) <i>missin</i>	1	\$ 650.00	\$ 650.00	280
4	TAILGATE OUTER MOULDING CLIP (SET) <i>New</i>	1	\$ 60.00	\$ 60.00	+
5	TAILGATE INNER TRIM CLIP (SET) <i>New</i>	1	\$ 80.00	\$ 80.00	30
6	TAILGATE WINDSCREEN SEALANT <i>3mm</i>	1	\$ 80.00	\$ 80.00	40
7	TAILGATE WINDSCREEN INNER SEAL <i>3mm</i>	1	\$ 60.00	\$ 60.00	40
8	TAIL LAMP CLIP (SET) <i>New</i>	1	\$ 40.00	\$ 40.00	20
9	REAR FENDER INNER TRIM CLIP (SET) <i>New</i>	1	\$ 60.00	\$ 60.00	30
10	REAR FENDER UPPER TRIM CLIP (SET) <i>New</i>	1	\$ 60.00	\$ 60.00	+
11	REAR FENDER COWLING CLIP (SET) <i>New</i>	1	\$ 60.00	\$ 60.00	+
12	REAR FENDER ARCED GARNISH CLIP (SET) <i>New</i>	1	\$ 60.00	\$ 60.00	+
13	REAR END PANEL TOP GARNISH CLIP (SET) <i>New</i>	1	\$ 50.00	\$ 50.00	10
14	REAR END PANEL INSULATION SEAL <i>New</i>	1	\$ 150.00	\$ 150.00	60
15	REAR FLOOR PANEL BOTTOM GARNISH CLIP (SET) <i>New</i>	1	\$ 60.00	\$ 60.00	+
16	REAR EXHAUST CHROME PIPE (SPECIAL TYPE) <i>New</i>	1	\$ 350.00	\$ 350.00	+
17	REVERSE SENSOR (SET) <i>Damaged</i>	1	\$ 220.00	\$ 220.00	20

740 TOTAL \$ 2,200.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 1,600.00	80
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,600.00	80
3	TUFF COAT	\$ 250.00	60

TO : **AIG** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SMR339A**
 MODEL : **HONDA VEZEL**
 DATE OF ACCIDENT : 07.02.21
 TIME OF ACCIDENT : 12:15HRS

4	REMOVE AND REFIX CUSHION SEAT/ UPHOLSTRY AND ROOF LINNING TO FACILITATE REPAIR	\$ 350.00	60
5	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	\$ 80.00	50
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	50
7	REMOVE AND REFIX VIDEO RECORDER	\$ 80.00	50
8	REAR CHASSIS ALIGNMENT	\$ 250.00	X
9	CONDUCT WATER LEAKAGE TEST	\$ 100.00	X
10	REMOVE AND REFIX TAILGATE WINDSCREEN	\$ 120.00	✓
11	TRANSFER TAILGATE MECHANISM	\$ 80.00	✓
12	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	X

TOTAL \$ 4,770.00 2070

TOTAL PARTS COST : \$ 13,349.68
 TOTAL LABOUR COST : \$ 4,770.00
 TOTAL REPAIR COST : \$ 18,119.68

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.
PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

ABBY

SERVICE ADVISOR
 ABBY
 HP : 9856 4815

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Admin Lj
 L/S 09/02/21
 06Days

total: 10015.12
 L/S: 8K

8K