

Mon 01/03 @ 10am
S&R

SMS3857X

BMW Dealer

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No.	: b1 57508	Page No. : 1 of 5
Date Estimated	: 09/02/2021	
Prepared By	: Han Kwan Yong	

- ESTIMATE REPAIR FOR - Lim Khoon 932 East Coast Road Singapore 459119	- ACCOUNT - 40000 Cash Sales - Service Singapore
---	--

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMS3857X	WBAJR12020CD69938	25/02/2020	520i	0

DESCRIPTION	VALUE
To replace rear bumper and to knock out rear right fender and dented area caused by the accident	1700 2,550.00
To respray rear bumper and rear right fender	1730 1,923.00
To replace tyre and wheel rim including balancing. (1x).	80 94.00
To check steering geometry and conduct wheel alignment in accordance with BMW specifications. (1x).	451 531.00
To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct check for proper function.	150 177.00
To check electrical wiring system and lighting at the rear section for proper function.	150 177.00
Sundries	? 80.00
Total Labour 1:	5,532.00

DESCRIPTION	QTY	PRIC	VALUE
ALLOY RIM 8JX18 DOUBLE SPK 634	1	1,149.85	cut 1,149.85
REAR BUMPER RH SIDE GUIDE	1	67.80	? 67.80
# REAR BUMPER PANEL PRIMED (PD	1	1,627.25	de 1,627.25
Total Parts :			2,844.90

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No.	: b1 57508	Page No. : 2 of 5
Date Estimated	: 09/02/2021	
Prepared By	: Han Kwan Yong	

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMS3857X	WBAJR12020CD69938	25/02/2020	520i	0

Claims OD / 3rd Party / Uninsured losses / Direct Settlement	
Regn No. <u>113/21E/090</u>	Claim No. _____
Date & Time <u>11/3/21 10:40</u>	Excess S\$ _____
Surveyor's Name <u>Tan Joon</u>	Sign <u>[Signature]</u>
Surveyor's Tel <u>97495244</u>	Authorised Yes / No _____
Authorised Date <u>11/3/21</u>	Time _____
RESURVEY PARTS PHOTO BY SURVEYOR Yes / No <u>Yes</u>	PML Yes / No _____
Surveyor's E-mail <u>TanJoon@pml.com.sg</u>	
No. of Working Days Recommend <u>4 days</u>	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:



Labour 1	:	5,532.00
Parts	:	2,844.90
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	586.38
Grand Total	:	8,963.28

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **