

**LIU'S BROTHER AUTO ENGINEERING WORKSHOP**

No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 47883

ROB No: 53291793J . Tel: 6741-1730 / 731 . Fax: 6744-5746. Email: liusbros@gmail.com

Invoice/Ref No: YN7930A201222

Estimate

Customer

Name: India International Insurance Pte Ltd

Date: 08-02-21

Address: Motor Claims Department

Vehicle No: YN7930A

64 Cecil Street #04-00 & #05-00

Model/Make: Mitsubishi

IOB Building Singapore 049711

Fuso FM65FMzRDEB

Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
	<i>S. NOTH item</i>		
1	Rear Tail Lamp Rh <i>CNE</i>	\$ 280.00	✓ 210 <i>S.M</i>
2	Safety Bar Centre Assy <i>best</i>	\$ 1,800.00	✓ 1200
3	Safety Bar Rh <i>D.S</i>	\$ 1,050.00	✓ 600
4	Hydraulic Pump Inner <i>SUC</i>	\$ 4,500.00	X
5	Hydraulic Pump Dust Cover Inner Rh <i>Torn</i>	\$ 420.00	✓ 280
6	Hydraulic Pump Dust Cover Outer Rh <i>TM</i>	\$ 380.00	✓ 280
	To check all wiring & electrical component for proper function	\$ 50.00	- 20
	To dismantle & replace hydraulic pump dust cover	\$ 200.00	- 80
	To test & realignment hydraulic pump	\$ 380.00	✓
	Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc	\$ 500.00	- 400
	To putty & spray painting & including touch up paint on accident affected ar	\$ 300.00	- 200

Total Parts & Labour of estimate for damaged vehicle

\$ 9,860.00

Total amount in Lump Sum Basis for repaired vehicle

SDLS: _____



M/s Liu's Brother Auto Engrg Wks

not Authorized
date
9/2/21
1/5 \$ 2600
the photo after repair
3 days.

Mak Cecilia

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SN \$ 2570
1-8 700
3270
WZ
2616