



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 1

M/S : AIG ASIA PACIFIC INSURANCE PTE. LTD.

78 SHENTON WAY #07-16
AIG BUILDING
SINGAPORE 079120

ATTN : MOTOR CLAIM DEPT

TEL : 6419 3000

FAX : 6415 3723

YOUR REF NO :

CLAIM TYPE : OWN DAMAGE

ACCIDENT DATE : 22/12/2020

ESTIMATE

NO : QUOT202101-000057(00)

DATE : 09/02/2021

POLICY NO : 999995580

VEH REG NO : GBF458H

MAKE/MODEL : TOYOTA TOYOTA HIACE VAN
TURBO 5 DR MANUAL

CHASSIS NO : JTFHT02P100198163

ENGINE NO : 1KD2620306

REG. DATE : 2016

Estimate Repair Cost to Vehicle No : GBF458H

Description	Quantity	Unit Price	Amount
		S\$	S\$
PARTS			
1 Bonnet	1	420.00	420.00 ✓
2 Bonnet-hinges - LH / RH	2	38.00	76.00 X
3 Bonnet emblem	1	48.00	48.00 ✓
4 Bonnet lock	1	60.00	60.00 ✓
5 Bonnet-lock-cable	1	45.00	45.00 X
6 Support Panel	1	280.00	280.00 2
7 Brace panel	1	65.00	65.00 2
8 Headlamp assy - RH / LH	2 ✓	450.00	900.00 24
9 Front grille (top)	1	165.00	165.00 ✓
10 Front grille (bottom)	1	225.00	225.00 ✓
11 Front grille (inner)	1	280.00	280.00 2
12 Front bumper	1	380.00	380.00 ✓
13 Front bumper reinforcement	1	180.00	180.00 X
14 Front bumper center grille	1	90.00	90.00 ✓
15 Front bumper clips	15	5.50	82.50 ✓
16 Radiator assy	1	780.00	780.00 2
17 Air-con condenser	1	650.00	650.00 2
Front radiator top beam	1	125.00	125.00 ✓
			4,726.50
		Add 10%	472.65
			5,199.15
SPECIAL NET			
18 Radiator coolant (bottle)	2	66.00	132.00 501
			132.00 100
LABOUR			
19 To remove and refit air-con condenser, radiator assy and refill air-con gas	1	150.00	150.00 100
20 To check and rectify wiring system	1	80.00	80.00 20
21 To panel beat and straighten front chassis frame, including replacement of parts and align where necessary, to refit and adjust the same	1	1,200.00	1,200.00 600
22 To putty and spray paint on affected areas	1	800.00	800.00 50
			2,230.00
			1220

Not Authorised
Returning B4 paint

10/02/2021

5 days

old mfg

new mfg

10%
\$ 4,468.00
446.80
\$ 4,914.80

1220



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 2

M/S : AIG ASIA PACIFIC INSURANCE PTE. LTD.

78 SHENTON WAY #07-16
AIG BUILDING
SINGAPORE 079120

ATTN : MOTOR CLAIM DEPT

TEL : 6419 3000 FAX : 6415 3723

YOUR REF NO :

CLAIM TYPE : OWN DAMAGE

ACCIDENT DATE : 22/12/2020

ESTIMATE

NO : QUOT202101-000057(00)

DATE : 09/02/2021

POLICY NO : 999995580

VEH REG NO : GBF458H

MAKE/MODEL : TOYOTA TOYOTA HIACE VAN
TURBO 5 DR MANUAL

CHASSIS NO : JTFHT02P100198163

ENGINE NO : 1KD2620306

REG. DATE : 2016

Estimate Repair Cost to Vehicle No : GBF458H

Description	Quantity	Unit Price	Amount
		S\$	S\$
		TOTAL	S\$ 7,561.15
		ADD GST @ 7%	529.28
		GRAND TOTAL	S\$ 8,090.43

SINGAPORE DOLLAR EIGHT THOUSAND NINETY AND CENTS FORTY-THREE ONLY

6,234.80
Xs 1,900.00

4,334.80
7% 303.43

4,638.23

FOR TONG LUCK AUTO PTE LTD

AUTHORISED SIGNATURE