

Adrian

AUTO BULLOX PTE LTD

53 Ubi Avenue 1#01-25 Paya Ubi Industrial Park Singapore 408934

Tel: 6844 4290 Fax: 6841 6043 Kaman Koh: 9769 9299 Email: motoricarzgarage@gmail.com

UEN:201919765N

VR3EFYHZRKJ635027

Estimation

Vehicle No: GBJ6111Y
Make/Model: Peugeot Partner
Date of Accident: 06/02/2021

TP 001
Xiao Chen

Survey Date: 10/02/2021
Surveyor Name: Adrian Ling (LKK)
Surveyor Contact : 9689 3735

No.	Description	Unit	Unit Price	Amount (S\$)
Parts Replacement:				
1	REAR BUMPER <i>Repld</i>	1	1,521.00	1,521.00 - 880
2	REAR BUMPER SIDE GARNISH <i>Neu</i>	2	489.00	978.00 +
3	REAR BUMPER TOWING COVER <i>Neu</i>	1	128.00	128.00 +
4	REAR BUMPER REINFORCEMENT <i>Neu</i>	1	845.00	845.00 +
5	REAR BUMPER CENTER BRACKET <i>Neu</i>	1	288.70	288.70 +
6	REAR BUMPER SIDE UPPER BRACKET	2	94.60	189.20 +
7	REAR BUMPER SIDE RETAINER <i>Neu</i>	2	121.00	242.00 +
8	REAR TAIL DOOR LH <i>Dented</i>	1	1,985.00	1,985.00 - 1768
9	REAR TAIL DOOR OUTER HANDLE LH <i>cut</i>	1	312.00	312.00 -
10	REAR TAIL DOOR LOCK HINGES LH <i>Best</i>	2	124.00	248.00 -
11	REAR TAIL DOOR LOCK LH <i>Dented</i>	2	258.00	516.00 - 385
12	REAR TAIL DOOR WEATHERSTRIP LH <i>cut</i>	1	224.60	224.60 -
13	REAR TAIL DOOR NUMBER PLATE LAMP LH <i>cut</i>	2	65.00	130.00 -
14	REAR TAIL DOOR EMBLEM 'PARTNER' <i>Neu</i>	1	47.60	47.60 -
15	REAR TAIL DOOR RH <i>Dented</i>	1	1,598.00	1,598.00 - 1395
16	REAR TAIL DOOR INNER LOCK RH <i>Dented</i>	2	221.40	442.80 -
17	REAR TAIL DOOR WEATHERSTRIP RH <i>cut</i>	1	224.00	224.00 +
18	REAR TAIL DOOR HINGES RH <i>Neu</i>	2	124.00	248.00 +
19	REAR TAIL DOOR INNER TRIM RH <i>Repld</i>	1	321.00	321.00 - 165
20	REAR TAIL DOOR EMBLEM 'PEUGEOT' <i>Neu</i>	1	121.00	121.00 -
21	REAR TAIL DOOR LOGO <i>Neu</i>	1	122.00	122.00 -
22	REAR END PANEL <i>Reps</i>	1	1,204.00	1,204.00 +
23	REAR END PANEL INNER <i>Reps</i>	1	658.00	658.00 +
24	REAR FLOOR PANEL <i>Reps</i>	1	1,897.00	1,897.00 +
25	REAR FENDER INNER COWLING <i>Neu</i>	2	117.30	234.60 +
26	TAILLAMP <i>cut</i>	2	987.50	1,975.00 - 720
27	TAILLAMP PANEL <i>Reps</i>	2	289.00	578.00 +
28	REAR WINDSCREEN <i>Shattered</i>	1	847.00	847.00 -
29	REAR SPARE TYRE BRACKET <i>Neu</i>	1	312.00	312.00 +
30	EXHAUST PIPE SILENCER <i>3rd</i>	1	1,046.30	1,046.30 +
31	EXHAUST MOUNTING <i>3rd</i>	2	32.80	65.60 +
				\$ 19,549.40
	<i>wiper Motor</i>		Less 10%	\$ 1,954.94
				\$ 17,594.46
S/Nett items:				
32	REAR NUMBER PLATE <i>Dented</i>	1	50.00	50.00 ✓
33	REAR BUMPER CLIP SET <i>Neu</i>	1	65.00	65.00 30
34	REVERSE CAMERA <i>Repld</i>	1	450.00	450.00 380
35	REVERSE SENSOR SET <i>Repld</i>	1	220.00	220.00 200
36	REAR TAIL DOOR SEALANT RH <i>Neu</i>	1	80.00	80.00 +

8274

7446.60

480

No.	Description	Unit	Unit Price	Amount (S\$)	
37	REAR TAIL DOOR WINDSCREEN SEALANT <i>neu</i>	2	80.00	160.00	50
38	REAR TAIL DOOR WINDSCREEN INNER SEAL <i>neu</i>	2	125.00	250.00	50
39	REAR TAIL DOOR STICKER '6PAX' <i>John</i>	1	30.00	30.00	15
40	REAR TAIL DOOR STICKER '70KM'	1	30.00	30.00	15
41	REAR END PANEL TOP GARNISH CLIP SET <i>neu</i>	1	45.00	45.00	+
42	REAR END PANEL SEALANT <i>neu</i>	1	90.00	90.00	+
43	REAR FLOOR PANEL SEALANT <i>neu</i>	1	90.00	90.00	+
44	REAR FLOOR PANEL INSULATOR <i>John</i>	1	250.00	250.00	+
45	REAR FLOOR PANEL TOP BOARD	1	800.00	800.00	+
46	REAR TAIL LAMP PANEL SEALANT <i>neu</i>	1	90.00	90.00	+
				\$ 2,700.00	
	Labour to:				
47	CONDUCT WATER LEAKAGE ON REPLACEMENT JOINT AREA		100.00	100.00	+
48	REMOVE AND RENEW REAR SENSOR. DISTANCE SENSORTY TEST		150.00	150.00	50
49	PERFORM REAR LIGHTING WIRING CHECK AND TEST FUNCTION		80.00	80.00	30
50	TRANSFER REAR TAIL DOOR MECHANISM LH/RH		300.00	300.00	120
51	REMOVE AND REFIT NEW WINDSCREEN		150.00	150.00	120
52	PERFORM DIAGNOSTIC CHECK		150.00	150.00	80
53	REMOVE AND INSTALL REAR MULTI VIEW CAMERA , ADJUST POSITION		250.00	250.00	50
54	RENEW REAR FLOOR INSULATOR		180.00	180.00	+
55	RENEW DAMAGE PARTS ON AFFECTED AREA , FLOOR PANEL AND REAR LHS FRAME , CUT OFF AND REPLACE REAR END PANEL		1,800.00	1,800.00	80
56	SPRAY PAINTING ON DAMAGE AND AFFECTED AREA		1,500.00	1,500.00	80
57	APPLY ANTI RUST ON AFFETED AREAS		120.00	120.00	80
				\$ 4,780.00	
	Total Parts Replacement Amount			\$ 20,294.46	
	Total Amount for Labour			\$ 4,780.00	
	Total Amount			\$ 25,074.46	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

Adrian L
F/S 10/02/21.
068mp

total: 10406.60.

L/S: 8.3K