



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO21001969/Kqf3n2	
			Date: 08/06/2021	
			Code: SMO	
1. Policy Particulars :- OWN DAMAGE				
	Insured Veh.	Veh. Inspected	SJA 76H	
	Policy No.	Coverage (\$)	0.00	
	Claim No. CMTD2100451/IJH	Excess (\$)	0.00	
	Assign From GRACE TEO	Assign Date	09/02/2021	
2. Vehicle Particulars & Condition				
	Make & Model BMW 520I (A)	c.c	1997	
	Engine No. HIDDEN	Year of Reg.	2014	
	Chassis No. WBA5A32040D789308	Colour	WHITE	
	Odometer 116094 KM	Steering	IN ORDER	
	Brakes IN ORDER	Modification	STANDARD ALLOY RIM	
	General GOOD			
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	225/55 R17	MICHELIN	8 mm
	L/H Front Tyre	225/55 R17	MICHELIN	8 mm
	R/H Rear Tyre	225/55 R17	MICHELIN	8 mm
	L/H Rear Tyre	225/55 R17	MICHELIN	8 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date 08/02/2021	Inspection Date	10/02/2021	
	Survey held at AH LIM MOTOR COMPANY NO 10 ANG MO KIO IND PK 2A #01-09 AMK AUTOPOINT SINGAPORE 568047			
5a. Remarks				
	A)THE MARKET VALUE IS S\$82,000.00 (EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	