

# AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047  
TEL: 6483 1244 ( 4 lines ) FAX: 6483 6170 Email: ahlimc@singnet.com.sg  
GST:M9-0009639-E RCB NO:06470300B

## SURVEYOR COPY

M/S : SOMPO INSURANCE SINGAPORE PTE LTD  
50 RAFFLES PLACE  
#03-03 SINGAPORE LAND TOWER  
SINGAPORE 048623

TEL: 64616555  
ATTN: Motor Claim Department

Estimate No: MC1901747

Date: 09 Feb 2021

Policy No: D20MTPV01006088

Veh Reg No: SJA76H

Make/Model: BMW 520I AT D/AB  
2WD

Your Ref No: SJA76H

Claim Type: Own Damage

Accident Date: 08/02/2021

*Not Authorized*  
*Repairing*

*Ex TRA 4 days 84134.25*

### Estimate Repair Cost to Vehicle No : SJA76H

| Description                                     | U/Price        | Quantity | Cost       | Amount     |
|-------------------------------------------------|----------------|----------|------------|------------|
|                                                 |                |          | <u>S\$</u> | <u>S\$</u> |
| <b>SPARE PARTS</b>                              |                |          |            |            |
| 1 HEADLAMP LH                                   |                | 1 PC     | 4,200.00   | X          |
| 2 HEADLAMP RH                                   |                | 1 PC     | 3,000.00   | X          |
| 3 HEADLAMP PANEL LH                             |                | 1 PC     | 220.00     | X          |
| 4 HEADLAMP PANEL RH                             |                | 1 PC     | 130.00     | X          |
| 5 FRONT GRILLE LH & RH                          |                | 2 PC     | 170.00     | ✓          |
| 6 FRONT BUMPER                                  | <i>Balance</i> | 1 PC     | 850.00     | 820        |
| 7 FRONT BUMPER SIDE RETAINER LH & RH            |                | 2 PC     | 48.00      | ✓          |
| 8 FRONT BUMPER RIVET                            |                | 15 PC    | 22.50      | ✓          |
| 9 FRONT BUMPER LOWER AIR GRILLE                 |                | 1 PC     | 55.00      | X          |
| 10 FRONT BUMPER REINFORCEMENT                   |                | 1 PC     | 400.00     | ✓          |
| 11 FRONT BUMPER REINFORCEMENT BRACKET LH & RH   |                | 2 PC     | 110.00     | X          |
| 12 FRONT BUMPER SPONGE                          |                | 1 PC     | 40.00      | ✓          |
| 13 FRONT BUMPER EMBLEM                          | NN             | 1 PC     | 60.00      | X          |
| 14 FRONT BUMPER PARKING SENSOR INNER            | NN             | 2 PC     | 260.00     | ✓          |
| 15 FRONT BUMPER PARKING SENSOR HOLDER SET       | NN             | 1 PC     | 50.00      | ✓          |
| 16 FRONT BUMPER PARKING SENSOR WIRE HARNESS     | LN             | 1 PC     | 120.00     | ✓          |
| 17 RADIATOR AIR GUIDE                           |                | 1 PC     | 300.00     | 240        |
| 18 FRONT BRACE PANEL LH & RH                    |                | 2 PC     | 30.00      | ✓          |
| 19 RADIATOR TOP PANEL FRT                       |                | 1 PC     | 135.00     | ✓          |
| 20 AIR CON CONDENSER                            |                | 1 PC     | 680.00     | ✓          |
| 21 RADIATOR ASSY                                |                | 1 PC     | 650.00     | X          |
| 22 INTERCOOLER                                  |                | 1 PC     | 420.00     | X          |
| 23 FOGLAMP COVER LH & RH                        |                | 2 PC     | 160.00     | X          |
| 24 FOGLAMP COVER MOULDING LH & RH - CHECK PRICE |                | 2 PC     | 0.0000     | X          |
|                                                 |                |          | 12,110.50  |            |
|                                                 | Add 10%        |          | 1,211.05   | 13,321.55  |

### Special Nett

25 NUMBER PLATE

26 RADIATOR COOLANT

1 PC 35.00 ✓  
1 PC 30.00 X

65.00

### LABOUR

27 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS  
AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS,  
TEST AND RECTIFY FOR PROPER FUNCTIONING.

1 PC 40.00 201

## AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047  
TEL: 6483 1244 ( 4 lines ) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg  
GST:M9-0009639-E RCB NO:06470300B

**SURVEYOR COPY**

M/S : SOMPO INSURANCE SINGAPORE PTE LTD  
50 RAFFLES PLACE  
#03-03 SINGAPORE LAND TOWER  
SINGAPORE 048623  
TEL: 64616555  
ATTN: Motor Claim Department

Estimate No: MC1901747  
Date: 09 Feb 2021  
Policy No: D20MTPV01006088  
Veh Reg No: SJA76H  
Make/Model: BMW 520I AT D/AB  
2WD

Your Ref No: SJA76H  
Claim Type: Own Damage  
Accident Date: 08/02/2021

### Estimate Repair Cost to Vehicle No : SJA76H

| Description                                                                                                                                                | U/Price | Quantity | Cost       | Amount     |
|------------------------------------------------------------------------------------------------------------------------------------------------------------|---------|----------|------------|------------|
|                                                                                                                                                            |         |          | <u>S\$</u> | <u>S\$</u> |
| 28 TO REMOVE AND REPLACE A/C CONDENSER AND PIPES, RADIATOR AND HOSES, VACUUM A/C SYSTEM AS WELL AS REFILL A/C GAS.                                         |         | 1 PC     | 100.00     | 2          |
| 29 LABOUR TO RESET ENGINE MANAGEMENT SYSTEM WITH DIAGNOSTIC FAULT                                                                                          |         | 1 PC     | 180.00     | 1201       |
| 30 TO DISMANTLE ALL DAMAGED PARTS TO CUT & WELD RADIATOR SUPPORT PANEL TO KNOCK & REPAIR INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME. |         | 1 PC     | 600.00     | 400        |
| 31 TO SPRAY FRONT BUMPER,SUPPORT PANEL.                                                                                                                    |         | 1 PC     | 400.00     | 2501       |
|                                                                                                                                                            |         |          |            | 1,320.00   |

Repair Amount S\$ 14,706.55

Add GST @ 7% 1,029.46

Total Amount payable S\$ 15,736.01

TOTAL: SINGAPORE DOLLAR FIFTEEN THOUSAND SEVEN HUNDRED THIRTY SIX AND CENTS ONE ONLY

Please arrange this vehicle to be surveyed soonest possible.

Thank You

For AH LIM MOTOR COMPANY

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



AUTHORISED SIGNATURE