



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924			Ref: CS/AGI21001970/T1vd3n2 Date: 16/06/2021	Code: AGI
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	FBQ 6894J	Veh. Inspected	SLL 6991U	
Policy No.		Coverage (\$)	0.00	
Claim No.	C20009021/ST	Excess (\$)	0.00	
Assign From	IVY RATILLA	Assign Date	09/02/2021	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA CAMRY	c.c	2494	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	MR053AK5004011630	Colour	SILVER	
Odometer	63135 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/55 R17	WEST LAKE	6 mm	
L/H Front Tyre	215/55 R17	WEST LAKE	6 mm	
R/H Rear Tyre	215/55 R17	WEST LAKE	6 mm	
L/H Rear Tyre	215/55 R17	WEST LAKE	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	08/02/2021	Inspection Date	10/02/2021	
Survey held at	YI HENG MOTOR WORKSHOP BLK 1 KAKI BUKIT AVE 6 #02-19 SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	