

ASS. REC. BY: Taufikh

REF:

CS/ AGI 21001970/T1vd3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: **FBQ 6894J**

Policy No. _____

Claims No. **C20009021/ST**

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

☒	☐
N/S	O/S
☐	☐

Bal. or Market Value: 980K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

WP

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: 8LL69914 Yr Regn: 2017 / MarchType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Camry c.c. 2494Colour: Silver A/C: Insured / Std / NI / NASp. Reading: 63135 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: MR0534K500401/630Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 215/55R17

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Westlake

Front

Rear

R/Bal. 6 mmR/Bal. 6 mmL/Bal. 6 mmL/Bal. 6 mmD.O.A. 8/2/21D.O.I. 10/2/21Survey held at Yp Heng

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Frt N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

15/6/21 Taufikh confirmed LS \$2400 (Red 6824.40,73%)

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2) 15/6/21-Typist

Report Format: **TP**

Lump Sum / I.B.k. / LS \$2400

Days Of Repair: **4**Resurvey No. of Trip: **2**

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Week-end (\$

Survey Fee:

Transportation:

S + RS \$

Photos

Others

TOTAL

YI HENG MOTOR WORKSHOP

BLK 1, KAKI BUKIT AVENUE 6
#02-19 AUTOBAY, SINGAPORE 417883
TEL: 6 5090052 FAX: 6 7479402

09-02-2021

OUR REF NO. SLL 6991U

BKW RENT-A-CAR PTE LTD
120 LOWER DELTA ROAD,
#02-15 CENDEX CENTRE,
SINGAPORE 169208

ESTIMATE BILL FOR VEHICLE NO. SLL 6991U MODEL : TOYOTA CAMRY 2.5A

LIST ITEM

1) FRONT BUMPER		\$ 1,635.00	de
2) FRONT BUMPER CLIPS	10PCS @\$8.90	\$ 89.00	ng
3) FRONT BUMPER SIDE ATTACHMENT	2PCS @49.24	\$ 98.48	LH & RH X
4) FRONT BUMPER SIDE GARNISH (LH)		\$ 118.00	?
5) FRONT BUMPER LOWER GRILLE		\$ 546.00	X ?
6) FRONT BUMPER LOWER GRILLE CHROME MOULDING (LH)		\$ 218.00	?
7) FRONT BUMPER LOWER GRILLE CHROME MOULDING TOP		\$ 281.00	X
8) FRONT BUMPER SPONGE		\$ 286.00	?
9) FRONT BUMPER REINFORCEMENT		\$ 653.00	X
10) FRONT BUMPER FOG LAMP (LH)		\$ 337.15	X
11) FRONT GRILLE		\$ 586.00	X
12) FRONT GRILLE LOGO		\$ 59.00	X
13) FRONT GRILLE CLIPS	2PCS @\$8.90	\$ 17.80	X
14) HEAD LAMP (LH) - dismantle photo		\$ 1,232.00	eng
15) HEAD LAMP CLIPS (LH)	2PCS @\$10.50	\$ 21.00	LH & RH X
16) FRONT FENDER (LH)		\$ 798.00	Rx
17) FRONT FENDER INNERSHIELD (LH)		\$ 286.00	?
18) FRONT FENDER INNERSHIELD CLIPS (LH)	8PCS @\$8.90	\$ 71.20	?
19) FRONT FENDER EMBLEM 'DUAL VVT-I'		\$ 49.80	ng
20) SUPPORT PANEL		\$ 1,293.00	X
21) SUPPORT PANEL TOP GARNISH		\$ 317.00	X
22) SUPPORT PANEL TOP GARNISH CLIPS	9PCS @\$8.90	\$ 80.10	X
		\$ 9,072.53	
	LESS DISCOUNT - 25%	\$ 2,268.13	
		\$ 6,804.40	

SPECIAL NETT ITEM

1) FRONT BUMPER SENSOR WITH CONTROL UNIT

\$ 380.00 ^X ~~200~~ 9
\$ 380.00

LABOUR CHARGE

1) TO CHECK WIRING SYSTEM

\$ 60.00 30.

2) TO APPLY UNDER SEALING ON AFFECTED AREAS

\$ 120.00 X

3) TO REMOVE/REFIX HEAD LAMP ASSY AND LIGHT SYSTEM

\$ 120.00 30

4) TO REMOVE/REFIX AIR-CON CONDENSOR, PIPING SYSTEM AND TOP-UP GAS

\$ 180.00 X

5) TO REMOVE/REFIX RADIATOR ASSY AND CONDUCT PRESSURE TEST

\$ 180.00 X

6) TO REPLACE NEW PART, CUT, WELD, KNOCK ETC

\$ 880.00 300

7) TO RESPRAY ON AFFECTED AREAS

\$ 880.00 400
\$ 2,420.00

GRAND TOTAL : \$ 9,224.40

Taufik 97495749

'WP' w/2/21 R 1300

L/S Resurvey after repair.

Taufik e/khantam

03 days.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	276D

Vehicle Details

Vehicle No.:	SLL6991U
Vehicle to be Exported:	Yes
Intended Deregistration Date:	08 Feb 2021
Vehicle Make:	TOYOTA
Vehicle Model:	CAMRY 2.5 AUTO
Primary Colour:	Silver
Manufacturing Year:	2016
Engine No.:	2ARU344302
Chassis No.:	MR053AK5004011630
Maximum Power Output:	133.0 kW (178 bhp)
Open Market Value:	\$29,570.00
Original Registration Date:	07 Mar 2017
First Registration Date:	07 Mar 2017
Transfer Count:	1
Actual ARF Paid:	\$33,398.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	06 Mar 2027
PARF Rebate Amount:	\$25,048.00

Intended COE Rebate Details

COE Expiry Date:	06 Mar 2027
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$53,106.00
COE Rebate Amount:	\$32,265.00
Total Rebate Amount:	\$57,313.00

The information contained herein is correct as at 08 Feb 2021

OK