

YI HENG MOTOR WORKSHOP

BLK 1, KAKI BUKIT AVENUE 6
#02-19 AUTOBAY, SINGAPORE 417883
TEL: 6 5090052 FAX: 6 7479402

09-02-2021

OUR REF NO. SLL 6991U

BKW RENT-A-CAR PTE LTD
120 LOWER DELTA ROAD,
#02-15 CENDEX CENTRE,
SINGAPORE 169208

ESTIMATE BILL FOR VEHICLE NO. SLL 6991U MODEL : TOYOTA CAMRY 2.5A

LIST ITEM

1) FRONT BUMPER		\$ 1,635.00	de
2) FRONT BUMPER CLIPS	10PCS @\$8.90	\$ 89.00	ng
3) FRONT BUMPER SIDE ATTACHMENT	2PCS @49.24	\$ 98.48	LH & RH X
4) FRONT BUMPER SIDE GARNISH (LH)		\$ 118.00	?
5) FRONT BUMPER LOWER GRILLE		\$ 546.00	X ?
6) FRONT BUMPER LOWER GRILLE CHROME MOULDING (LH)		\$ 218.00	?
7) FRONT BUMPER LOWER GRILLE CHROME MOULDING TOP		\$ 281.00	X
8) FRONT BUMPER SPONGE		\$ 286.00	?
9) FRONT BUMPER REINFORCEMENT		\$ 653.00	X
10) FRONT BUMPER FOG LAMP (LH)		\$ 337.15	X
11) FRONT GRILLE		\$ 586.00	X
12) FRONT GRILLE LOGO		\$ 59.00	X
13) FRONT GRILLE CLIPS	2PCS @\$8.90	\$ 17.80	X
14) HEAD LAMP (LH) - dismantle photo		\$ 1,232.00	eng
15) HEAD LAMP CLIPS (LH)	2PCS @\$10.50	\$ 21.00	LH & RH X
16) FRONT FENDER (LH)		\$ 798.00	RX
17) FRONT FENDER INNERSHIELD (LH)		\$ 286.00	?
18) FRONT FENDER INNERSHIELD CLIPS (LH)	8PCS @\$8.90	\$ 71.20	?
19) FRONT FENDER EMBLEM 'DUAL VVT-I'		\$ 49.80	ng
20) SUPPORT PANEL		\$ 1,293.00	X
21) SUPPORT PANEL TOP GARNISH		\$ 317.00	X
22) SUPPORT PANEL TOP GARNISH CLIPS	9PCS @\$8.90	\$ 80.10	X
		\$ 9,072.53	
	LESS DISCOUNT - 25%	\$ 2,268.13	
		\$ 6,804.40	

SPECIAL NETT ITEM

1) FRONT BUMPER SENSOR WITH CONTROL UNIT

\$ 380.00 ^X ~~300~~ 9
\$ 380.00**LABOUR CHARGE**

1) TO CHECK WIRING SYSTEM

\$ 60.00 30.

2) TO APPLY UNDER SEALING ON AFFECTED AREAS

\$ 120.00 X

3) TO REMOVE/REFIX HEAD LAMP ASSY AND LIGHT SYSTEM

\$ 120.00 30

4) TO REMOVE/REFIX AIR-CON CONDENSOR, PIPING SYSTEM AND TOP-UP GAS

\$ 180.00 X

5) TO REMOVE/REFIX RADIATOR ASSY AND CONDUCT PRESSURE TEST

\$ 180.00 X

6) TO REPLACE NEW PART, CUT, WELD, KNOCK ETC

\$ 880.00 300

7) TO RESPRAY ON AFFECTED AREAS

\$ 880.00 400
\$ 2,420.00**GRAND TOTAL : \$ 9,224.40**

Taufik 97495749

'WP' w/2/21 R 1300

L/S Resurvey after repair.

Taufik e/khantam

03 days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	276D

Vehicle Details

Vehicle No.:	SLL6991U
Vehicle to be Exported:	Yes
Intended Deregistration Date:	08 Feb 2021
Vehicle Make:	TOYOTA
Vehicle Model:	CAMRY 2.5 AUTO
Primary Colour:	Silver
Manufacturing Year:	2016
Engine No.:	2ARU344302
Chassis No.:	MR053AK5004011630
Maximum Power Output:	133.0 kW (178 bhp)
Open Market Value:	\$29,570.00
Original Registration Date:	07 Mar 2017
First Registration Date:	07 Mar 2017
Transfer Count:	1
Actual ARF Paid:	\$33,398.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	06 Mar 2027
PARF Rebate Amount:	\$25,048.00

Intended COE Rebate Details

COE Expiry Date:	06 Mar 2027
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$53,106.00
COE Rebate Amount:	\$32,265.00
Total Rebate Amount:	\$57,313.00

The information contained herein is correct as at 08 Feb 2021

OK