

BODYFIX

NO 10 ANG MO KIO INDUSTRIAL PARK 2A #04-06

AMK AUTOPOINT SINGAPORE 568047

Tel No. : 62571289 Fax No. : 64837432

E-Mail : bodyfix@singnet.com.sg

Tax Reg. No. : 53010635C Buss. Reg. No. : 53010635C

Estimate : ES210216

8 S'PORE POST CENTRE #09-04A

Claim Department

79

*Not Authorised**1/1 Rm @ 3700k**Many After Paint**4 days*

Date : 22/02/2021

Vehicle Num. : SLZ 9785 E

Make/Model : BMW 520-2018

Chassis/Eng# : WBAJA12070WC09107

Accident Date : 08/02/2021

Claim No. :

Reference :

Policy No. :

Particular

Unit Price Amount S\$

LIST ITEMS :

REAR BUMPER *1619.15*

REAR BUMPER REFLECTOR

REAR BUMPER CLIPS

REAR BUMPER SIDE RETAINER

REAR BOOTLID

BOOTLID LOGO

EMBLEM '520i'

BOOTLID REFLECTOR

BOOTLID RUBBER

TOWING COVER

REAR END PANEL INNER

REAR END PANEL OUTER

REAR END PANEL TOP GARNISH

REAR TAIL LAMP

Rear reinforcement cover

List Total S\$:

<i>BT/LM</i>		1,827.50	✓
58.50	<i>Sm</i>	117.00	X
3.50	<i>Sm</i>	28.00	—
80.00	<i>Sm</i>	160.00	X
	<i>Rm</i>	1,958.45	✓
	<i>Sm</i>	95.00	—
	<i>Sm</i>	98.00	—
378.70	<i>Sm</i>	757.40	X
<i>cut</i>	<i>502/1m</i>	159.00	—
	<i>Sm</i>	65.00	X
	<i>Rm</i>	841.95	X
	<i>Rm</i>	589.40	X
	<i>Sm</i>	145.00	X
741.15	<i>Sm</i>	1,482.30	X
		8,324.00	

SPECIAL NETT ITEMS :

REAR NUMBER PLATE WITH HOLDER

REVERSE SENSOR

SEALANT

<i>Sm</i>	45.00	X
<i>Sm</i>	320.00	X
<i>Sm</i>	80.00	X
	445.00	

Special Nett Total S\$:

LABOUR :

RUST-PROOFING ON THE ACCIDENT AFFECTED PORTIONS

TO CHECK&TEST LIGHTING FUNCTIONS & REVERSE SENSOR WIRING

<i>301</i>	60.00	
<i>2d</i>	80.00	

CONTINUE / ...

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

NO 10 ANG MO KIO INDUSTRIAL PARK 2A #04-00
AMK AUTOPOINT SINGAPORE 568047
Tel No. : 62571289 Fax No. : 64837432
E-Mail : bodyfix@singnet.com.sg
Tax Reg. No. : 53010635C Buss. Reg. No. : 53010635C

Estimate : ES210216

ED
AD 8 S'PORE POST CENTRE #09-04A

or Claim Department
4779

Date : 22/02/2021
Vehicle Num. : SLZ 9785 E
Make/Model : BMW 520-2018
Chassis/Eng# : WBAJA12070WC09107
Accident Date : 08/02/2021
Claim No. :
Reference :
Policy No. :

Particular	Unit Price	Amount S\$
TO REMOVE & REFIT REAR WINDSCREEN		150.00 X
LABOUR TO REPLACE ABOVE PARTS, PANEL BEAT, REPAIR & RE-ALIGN DAMAGE PARTS		1,200.00 400
SPRAY PAINT REAR BUMPER, BOOTLID, REAR END PANEL & OTHER AFFECTED AREAS		600 1,200.00
Labour Total S\$:		2,690.00

h Thousand Four Hundred Fifty-Nine Only

E. & O.E.

Total S\$: 11,459.00
=====