

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: ECICS Limited
10 Eunos Road 8
#09-04A Singapore Post Centre
Singapore 408600From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn:

Date: 10 Mar 2021

Preliminary Advice

Insured Vehicle No	: SKC6973G	Accident Date	: 08/02/2021
TP Vehicle No	: SLZ9785E	Assignment Date	: 09/02/2021
Make	: HYUNDAI AVANTE	Est. Duration of Repair	: 5
Date of Inspection	: 22/02/2021		
Inspection At	: BODYFIX (HQ) 10 ANG MO KIO INDUSTRIAL PARK 2, #04-06, AMK AUTOPOINT SINGAPORE 568047		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	11,459.00
Revised Amount	:S\$	4,335.76
Check Items (Estimated)	:S\$	2,938.72
Total	:S\$	7,274.48
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :