

YSK Auto Workshop

No. 1 Kaki Bukit Avenue 6, #01-49 (Autobay), Singapore 417883

H/P: 9640 2541

Email: dannyskyeo@gmail.com

TPA16.

Xiao Chen.

JM6BN2478J0193616.

Vehicle number: SLU4055M

Vehicle Made & Model: MAZDA 3

Qty	List Items	Amount \$
1	Front fender - LH <i>Repis</i>	581.60 <i>x</i>
1	Front fender inner shield <i>Not new</i>	162.40 <i>x</i>
15	Front fender inner shield clips @ 5.50 <i>new</i>	82.50 <i>x</i>
1	Front door - LH <i>Dented.</i>	1,589.60 <i>1062</i>
1	Front door outer handle <i>new</i>	191.60 <i>x</i>
1	Front door side mirror <i>Dented</i>	821.60 <i>✓</i>
1	Front door side mirror cover <i>Repis</i>	180.90 <i>x</i>
1	Front door glass outer moulding	141.20 <i>x</i>
1	Front door glass run channel <i>Not new</i>	193.60 <i>x</i>
1	Front door glass regulator	481.90 <i>x</i>
1	Front door inner lock	431.60 <i>x</i>
1	Front door w/strip <i>Not new</i>	181.70 <i>x</i>
1	Front door checker	89.90 <i>x</i>
1	Front shock absorber - LH	491.20 <i>x</i>
1	Front lower arm	591.60 <i>x</i>
1	Front knuckle arm <i>Not new</i>	580.50 <i>x</i>
1	Front wheel hub <i>Not new</i>	280.90 <i>x</i>
1	Front wheel bearing	211.30 <i>x</i>
1	Rear door - LH <i>Dented</i>	1,682.60 <i>1085</i>
1	Rear door outer handle	196.60 <i>x</i>
1	Rear door glass outer moulding	141.20 <i>x</i>
1	Rear door glass run channel	191.60 <i>x</i>
1	Rear door glass regulator	461.30 <i>x</i>
1	Rear door 1/4 glass rubber <i>Not new</i>	86.90 <i>x</i>
1	Rear door w/strip	181.30 <i>x</i>
1	Rear door checker	89.90 <i>x</i>
1	Rear shock absorber - LH	421.60 <i>x</i>
1	Rear trailing arm	581.90 <i>x</i>
1	Rear top arm <i>Not new</i>	280.60 <i>x</i>
1	Rear lower arm <i>Nec</i>	311.30 <i>x</i>
1	Rear knuckle arm	560.90 <i>x</i>

Vehicle number: SLU4055M

Vehicle Made & Model: MAZDA 3

1	Rear wheel hub bearing	<i>hol ne</i>	531.60	<i>X</i>
			Sub-total	13,004.90
			Less 20%	2,600.98
			Total List	10,403.92

2968.60
2374.88

Special Nett Items

1	Rear sport wheel - LH	<i>cut</i>	550.00	<i>400</i>
1	Rear tyre	<i>ne n</i>	350.00	<i>+</i>
1 set	Rear door black tape	<i>green</i>	120.00	<i>60</i>
1 set	Front door black tape		120.00	<i>60</i>
1	Front sport wheel - LH	<i>cut</i>	550.00	<i>400</i>
1	Front tyre	<i>hol ne</i>	350.00	<i>X</i>
			Total Special Nett	2,040.00

920

Labour charges

To check front & rear electrical wiring	<i>1560</i>	80.00	<i>30</i>
To remove, refix front & rear undercarriage		600.00	<i>X</i>
To respray undercoating		150.00	<i>50</i>
To check wheel alignment		120.00	<i>80</i>
To respray painting and etc		1,400.00	<i>800</i>
*Panel beating, cut, weld remove & replacing above parts		1,500.00	<i>600</i>
		Total Labour	3,850.00

Total: 4854.88
L/S: 3.8K
OS Dup

ESTIMATE PARTS AND LABOUR GRAND TOTAL \$ 16,293.92

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer