



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555			Ref: CS/LPC21001981/R1qf3e2 Date: 05/07/2021 Code: LPC2	
1. Policy Particulars :- OWN DAMAGE				
	Insured Veh.		Veh. Inspected	GBE 3876U
	Policy No.	z/20/VC00/108991	Coverage (\$)	0.00
	Claim No.	20/21/21/VC00/024209	Excess (\$)	1,400.00
	Assign From	KENNY LIM	Assign Date	09/02/2021
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA DYNA 150M	c.c	2982
	Engine No.	HIDDEN	Year of Reg.	2015
	Chassis No.	JTFAT35Y70K205404	Colour	GREY
	Odometer	243633 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	FAIR		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195 R15C	MAXMILER	6 mm
	L/H Front Tyre	195 R15C	MAXMILER	6 mm
	R/H Rear Tyre	155 R12C (D)	MAXMILER	5/5 mm
	L/H Rear Tyre	155 R12C (D)	MAXMILER	5/5 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	04/02/2021	Inspection Date	10/02/2021
	Survey held at	MOVA AUTOMOTIVE PTE LTD 15 FAN YONG ROAD SINGAPORE 629792		
5a. Remarks				
	A) THE MARKET VALUE IS S\$46,000.00 (EST. AVERAGE) B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		10 Working Days	