

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0128/2021/ET
DATE : 9-Feb-21
WIP : 14900

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE SURVEY ON 10.2.2021

UNITED OVERSEAS INSURANCE LIMITED

3 ANSON ROAD

#28-01 SPRINGLEAF TOWER

SINGAPORE 079909

Hi Adrian

1 day - ok - John

14-Jun-21

OWNER'S NAME : MDM KHAW PAIK SIM
ADDRESS : 42 JALAN KHAIRUDDIN
SINGAPORE 457514
TELEPHONE : (HP) +65 90081802
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : DH0M110163641801
VEHICLE NO : **SLR 7811 T**
MODEL CODE : AUDI Q2 1.0 TFSI S TRONIC
MODEL YEAR : 28/8/2017
ENGINE NO : CHZ 391780
CHASSIS NO : WAUZZZGA6JA001148
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 8-Feb-21
PLACE OF ACCIDENT : SIGLAP, SINGAPORE

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG**ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE. SLR 7811 T**

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO DISMANTLE RHS DOOR PANEL TRIM.	S/N \$	400.00	\$ 400.00
2	TO RESPRAY RHS WING MIRROR COVER AND RHS FRONT DOOR.	\$	1,900.00	\$ 200.00
4	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	\$ 192.00
TOTAL LABOUR CHARGES		:	\$ 2,492.00	\$ 792.00

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLR 7811 T

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	WING MIRROR MOUNTING RH	1	\$ 516.00	\$	515.50
2	WING MIRROR CAP RH	1	\$ 191.00	\$	191.00
3	WING MIRROR GLASS RH	1	\$ 309.00	\$	308.50
4	CORNER TRIM RH	1	\$ 46.00	\$	45.30
5	Added parts - see attached		\$ 197.00	\$	196.50
6	SUNDRIES	1	\$ 100.00		
TOTAL SPARE PARTS		:	\$ 1,359.00	\$	1,256.80
TOTAL LABOUR CHARGES		:	\$ 2,492.00	\$	792.00
GRAND TOTAL		:	\$ 3,851.00	\$	2,048.80

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.
 bl-04/05/21



Supplementary Estimate

GST Reg No. 19-9902271-W

UNITED OVERSEAS INSURANCE LIMITED 3 ANSON ROAD #28-01 SPRINGLEAF TOWER SINGAPORE 079909 Attn: Motor Claims Dept TEL: 6222 7739 - FAX 6327 3869		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0128/2021/ET 15-Mar-21 CHANG 1 of 1 SLR 7811 T AUDI Q2 1.0 TFSI	
Quantity	Description	Unit Price	Amount	
<u>PARTS</u>				
1	FRONT DOOR WINDOW - RH	\$ 197.00	\$ 196.50	
	GRAND TOTAL	\$ 197.00	\$ 196.50	

For Premium Automobiles Pte Ltd

Authorized Signature

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT