

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0124/2021/ET
DATE : 8-Feb-21
WIP : 14700

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.

YOUR INSURED VEH NO : SE 2222 L

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

ATTN: MR. ADRIAN LING - MOTOR CLAIMS DEPT

TEL: 6841 0055 - FAX: 6256 4315

OWNER'S NAME : GIAM KAH HEAN, EDWIN
ADDRESS : 3 SENNET DRIVE
SINGAPORE 466793
TELEPHONE : HP +65 9339 0999
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1800030669-01
VEHICLE NO : **SE 2222 L**
MODEL CODE : AUDI A6 1.8TFSI S tronic
MODEL YEAR : 3/4/2018
ENGINE NO : CYG 022730
CHASSIS NO : WAUZZZ4G3JN030135
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 5-Feb-21
PLACE OF ACCIDENT : 201 BALESTIER ROAD

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SE 2222 L

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR.CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE.	S/N \$ 360.00	
2	TO DISMANTLE AND RENEW REAR LID AND LHS REAR FENDER. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 2,400.00	
3	TO RESPRAY REAR BUMPER, REAR LID AND LHS REAR FENDER.	\$ 3,000.00	
4	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	
SUB-TOTAL LABOUR CHARGES		: \$ 5,952.00	

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SE 2222 L

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
1	REAR BUMPER	1	\$	3,268.00
2	REAR BUMPER FIXING PARTS	1	\$	273.00
3	REAR BUMPER SPOILER	1	\$	480.00
4	REAR BUMPER SECURING STRIP	1	\$	223.00
5	REAR BUMPER CLOSING ELEMENT - LH/RH	2	\$	162.00
6	REAR BUMPER REINFORCEMENT	1	\$	1,012.00
7	HEX COLLARED BOLT	3	\$	24.00
8	REAR BUMPER REINFORCEMENT GASKET - LH/RH	2	\$	28.00
9	REAR BUMPER TOP GUIDE SECTION - LH/RH	2	\$	66.00
10	REAR BUMPER TOP GUIDE SECTION PIN	2	\$	25.00
11	REAR BUMPER GUIDE PROFILE - LH/RH	1	\$	134.00
12	REAR BUMPER CENTRE GUIDE SECTION	1	\$	106.00
13	REAR BUMPER HOLDING STRAP - LH/RH	2	\$	126.00
14	REVERSE SENSOR	2		TBC
15	REVERSE SENSOR 'O' RING	4	\$	24.00
16	REAR LID CHROME TRIM	1	\$	366.00
17	REAR LID ADHESIVE	1	\$	19.00
18	AUDI EMBLEM	1	\$	138.00
19	A6 EMBLEM	1	\$	99.00
20	TFSI EMBLEM	1	\$	99.00
SUB - TOTAL SPARE PARTS		:	\$	6,672.00

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND:

REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

SPARE PARTS ARE SPECIAL NETT.

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SE 2222 L

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
		S/NETT	REMARKS
21 REAR LID LOCK COVER	1	\$ 8.00	
22 REAR LID LOCK	1	\$ 189.00	
23 LED TAIL LIGHT - OUTER LH	1	\$ 1,258.00	
24 LED TAIL LIGHT TRIM - OUTER LH	1	\$ 30.00	
25 LED TAIL LIGHT - INNER LH	2	\$ 1,258.00	
26 LED TAIL LIGHT TRIM - INNER LH	1	\$ 30.00	
27 EXHAUST CHROME TRIM - LH	1	\$ 568.00	
28 SUNDRIES		\$ 200.00	
TOTAL SPARE PARTS	:	\$ 10,213.00	
TOTAL LABOUR CHARGES	:	\$ 5,952.00	
GRAND TOTAL	:	\$ 16,165.00	

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND:

REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE
AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER
LAOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF
REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO
MS. NORAH KHAI AT TEL: 6768 9828 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT