

Lion City Rentals Pte Ltd
CARROS CENTER
60 JALAN LAM HUAT #04-01 S(737869)
Main +65 62524991

China Taiping Insurance Pte Ltd

Date: 12/02/2020

Attn : **MOTOR CLAIMS DEPT**

ESTIMATE

VEHICLE NO. SLD6051A

CHASSIS NO : NSP1707028749

MAKE / MODEL : Toyota Sienta 1.5X Auto

DATE OF ACCIDENT : 08/02/2020

YOUR INSURED VEHICLE NUMBER : GBE3939Y

MILEAGE : 351661 km

	<u>PARTS DESCRIPTION</u>	<u>QTY</u>	<u>UNIT PRICE</u>	<u>LIST PRICE</u>
1	Rear tailgate / DR	1PC	\$ 1,470.00	\$ 1,470.00 1,180
4	Rear tailgate weatherstrip 2 / CR4.	1PC	\$ 360.00	\$ 360.00 /
5	Rear tailgate lock assy with countersy lamp X Svc	1PC	\$ 504.00	\$ 504.00 X
6	Rear tailgate lock catch X Svc	1PC	\$ 64.80	\$ 64.80 X
11	Rear tailgate back door trimboard X Svc	1PC	\$ 580.00	\$ 580.00 X
12	Rear tray luggage compartment 2 / CR4	1PC	\$ 420.00	\$ 420.00 /
13	Rear spare tyre compartment box 2 X Svc	1PC	\$ 400.00	\$ 400.00 X
14	Rear spare tyre panel 2 X R	1PC	\$ 1,200.00	\$ 1,200.00 X
15	Rear tailgate center garnish holder / CR4	1PC	\$ 342.00	\$ 342.00 /
16	Rear tailgate Toyota logo / Nec	1PC	\$ 60.00	\$ 60.00 /
19	R/L taillamp / CR4.	1PC	\$ 550.00	\$ 550.00 425
20	R/L tailgate reflector X Svc	1PC	\$ 380.00	\$ 380.00 X
26	Rear end panel 2 / DR	1PC	\$ 828.00	\$ 828.00 550
27	Rear end panel lower 2 X Svc	1PC	\$ 633.60	\$ 633.60 X
28	Rear end panel top garnish 2 / CR4.	1PC	\$ 250.00	\$ 250.00 195
32	Rear bumper cover / CR4.	1PC	\$ 900.00	\$ 900.00 730
33	Rear bumper LH side bracket / BR	1PC	\$ 105.00	\$ 105.00 /
35	Rear bumper LH bracket X Svc	1PC	\$ 90.00	\$ 90.00 X
38	Rear bumper LH seal X Svc	1PC	\$ 104.40	\$ 104.40 X
40	Rear bumper LH support X Svc	1PC	\$ 88.05	\$ 88.05 X
41	Rear bumper LH extension side pad X Svc	1PC	\$ 216.00	\$ 216.00 X
43	Rear bumper center black pad / CR4.	1PC	\$ 288.00	\$ 288.00 /
44	Rear bumper LH reflector X Svc	1PC	\$ 133.20	\$ 133.20 X
46	Rear bumper tow cover X Svc	1PC	\$ 40.00	\$ 40.00 X
47	Keyless smart buzzer antenna X Svc.	1PC	\$ 120.00	\$ 120.00 X
LIST TOTAL S\$: \$ 10,127.05				4,655 + 486.20
25.00% DISCOUNT S\$: \$ 2,531.76				- 25%.
				\$ 7,595.29

SPECIAL NETT

1	Bumper clips / Nec.	1 SET	\$ 80.00	30
2	Reverse sensor / short.	1 SET	\$ 260.00	200
3	Windscreen sealant / Nec.	1PC	\$ 100.00	40
4	Body / Rear end panel sealant / Nec	1PC	\$ 100.00	40
5	Rear number plate / CR4	1PC	\$ 100.00	35
Special Nett Total S\$: \$ 640.00				345

LABOUR CHARGES

- | | | | |
|---|---|-------------|--------------|
| 3 | To remove and install rear tailgate glass | \$ 120.00 | / |
| | To remove and install rear 1/4 glass | \$ 120.00 | X |
| 3 | Transfer tailgate mechanism | \$ 100.00 | 60 |
| 4 | To labour charge for removing rear tailgate, rear bumper, end panel and spare tyre panel out to facilitate repairs and replacement of damaged parts. Also include straightening of both rear chassis members and floor panel. | \$ 2,500.00 | 400
1,000 |
| 5 | To respray rear tailgate, rear end panel, spare tyre panel, rear bumper, roof top and both rear fenders | \$ 1,800.00 | 800 |
| 6 | Towing fee | \$ 50.00 | X |
| 7 | To remove upholstery, seats out to facilitate repairs and replacement of damaged parts | | X |
| 8 | To conduct a standard of operating procedures post repairs diagnostic scan test as a requirements upon completion of collision repairs | \$ 300.00 | X |
| 9 | To provide transport for sending car to install DECAL | \$ 80.00 | X |

LABOUR TOTAL S\$: \$ 5,070.00 1,980
TOTAL S\$: \$ 13,305.29
7% GST \$ 931.37
GRAND TOTAL S\$: \$ 14,236.66

Repair dy - 5 dy

L15

After puim photo

Sun Pin CLK 86612627

10/02/2021

TP without prejudice.

3,855.90

345

1,980

6,180.90

- 20%

4,944.72

L15

\$4,950

5 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

VEHICLE NO. SLD6051A
CHASSIS NO : NSP1707028749
MAKE / MODEL : Toyota Sienta 1.5X Auto
DATE OF ACCIDENT : 08/02/2020
YOUR INSURED VEHICLE NUMBER :GBE3939Y
MILEAGE : 351661 km

<u>PARTS DESCRIPTION</u>		<u>QTY</u>	<u>UNIT PRICE</u>	<u>LIST PRICE</u>	
<u>Supplementary</u>					
4	Rear fender inner trim board (LH) <i>✓cku.</i>	1PC	\$ 580.00	\$ 580.00	<i>486.20</i>
					
			LIST TOTAL S\$:	\$ 580.00	
			25.00% DISCOUNT S\$:	\$ 145.00	
					
				\$ 435.00	