

**Note: This document has not been finalised.****LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road  
#16-00 Springleaf Tower  
Singapore 079909From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Cecilia Low

Date: 15 Feb 2021

**Preliminary Advice**

Insured Vehicle No	: GBE3939Y		
TP Vehicle No	: SLD6051A	Accident Date	: 08/02/2021
Make	: TOYOTA SIENTA	Assignment Date	: 10/02/2021
Date of Inspection	: 10/02/2021	Est. Duration of Repair	: 5
Inspection At	: LION CITY RENTALS PTE LTD (HQ) 60 JALAN LAM HUAT, #04-35/36 CARROS CENTRE SINGAPORE 737569		

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	13,305.29
Revised Amount	:S\$	6,504.75
Check Items (Estimated)	:S\$	0.00
Total	:S\$	6,504.75
Lump Sum Repair	:S\$	

**Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

**Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( ) Other comments :