

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**

China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road, #16-00 Springleaf Tower  
Singapore 079909

**Our File No:** CS/CTI21001999/KTD3E2**Date:** 11/05/2021**REFERENCE**

Insured/Claimant:	HAMSTER CAR RENTAL PTE LTD	Policy No:	DMHCSNA00004132000
Date of Loss:	10/01/2021	Nature of Claim:	OD
		Claim No:	SNM21D200763/C01/TOHHS

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	SLF7321D	Engine No:	LEB5910211
Make & Model:	HONDA VEZEL, 1.5 X HYBRID CVT (A)	Chassis No:	RU31210200
Reg. Date:	07/09/2016 (Man. Year: 2016)	Odometer:	0 km
Colour:	Metallic Black		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	S\$57,000.00		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Tourador 9 mm	Rear Left Side:	Dunlop 3 mm
Front Right Side:	Tourador 9 mm	Rear Right Side:	Dunlop 3 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	31,814.00	25,682.00	6,132.00	19.27
Miscellaneous Items	460.00	455.00	5.00	1.09
Labour	6,443.66	5,285.53	1,158.13	17.97
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>38,717.66</b>	<b>31,422.53</b>	<b>7,295.13</b>	<b>18.84</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>24,500.00</b>		
<b>- Excess (S\$)</b>	0.00	2,000.00	-2,000.00	
<b>(S\$)</b>	38,717.66	22,500.00	16,217.66	41.89
<b>+ GST 7.00/7.00% (S\$)</b>	2,710.24	1,575.00	1,135.24	41.89
<b>Nett Amount (S\$)</b>	<b>41,427.90</b>	<b>24,075.00</b>	<b>17,352.90</b>	<b>41.89</b>

**INSPECTION**

Date of Assignment:	10/02/2021	
Date Inspected:	10/02/2021	Inspected At: 5035 Ang Mo Kio Industrial Park 2 #01-367
Estimated Period of Repair:	26.0 days	Repairer: Goldbell Engineering Pte Ltd

**Adjuster:** KENNETH KONG**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

**Part Source:** MRM-SG      Version: 1.0 (Last Synchronised: 10 May 2021)

**Parts:** M1-SUV      HONDA VEZEL 1.5 X HYBRID CVT (A) (Catalogue:Merimen Singapore 1.0)

**Labour:** Repairer's      (Price-denominated Standard List)

**Print Code:** (Unsubmitted, no print-code for SLF7321D)

**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		<b>*Total Parts</b>		31,814.00 F	*24,352.00 F
2	1		<b>*R/F DOOR SPEAKER</b>	Dented	-	*180.00 F
3	1		<b>*R/INNER A-PILLAR</b>	Necessary	-	*610.00 F
4	1		<b>*R/F BACKREST COVER</b>	Cracked	-	*60.00 F
5	1		<b>*R/R WHEEL HUB</b>	Bent	-	*250.00 F
6	1		<b>*R/R BRAKE DISC</b>	Warped	-	*230.00 F
<b>Total Parts (S\$)</b>					<b>31,814.00</b>	<b>25,682.00</b>

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	Total Of Extras	460.00	455.00
Sub Total (\$\$)			460.00	455.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	Total of Labour	New	4,939.20	3,885.00
2	Total Paint Including Material	New	1,504.46	1,400.53
Gross Labour Cost (\$\$)			6,443.66	5,285.53

Report was unsubmitted during this print-out.

< END OF ESTIMATES >