



LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

ESTIMATE

TO : ASSURE GENERAL INSURANCE
ATTENTION : MOTOR CLAIM DEPARTMENT

DATE : 9-Feb-2021
JOB TYPE : THIRD PARTY CLAIM

VEHICLE DETAILS

VEHICLE NO. : SMF6168A
MAKE / MODEL : HONDA HR-V
CHASSIS NO. : JHMRU1810JX200714

ACCIDENT DETAIL

DATE : 6-Feb-2021
TIME : 21:30 hr

OWNER INSURANCE : LIBERTY INSURANCE
POLICY NO. : SD20V12780/VPC2/R01Q

Veron.

PERSON INCHARGE : Falcoe | T: 6702 1555 | F: 6702 1444 | falcolee@skauto.com.sg

CLAIM DETAIL : LIST PRICE (S\$)

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	Bonnet <i>Not New</i>	1	\$ 982.00	\$ 982.00
2	Bonnet Hinges LH / RH	2	\$ 57.00	\$ 114.00
3	Bonnet Lock <i>Not New</i>	1	\$ 115.00	\$ 115.00
4	Bonnet Rubber Insulator	1	\$ 141.00	\$ 141.00
5	Front Bumper <i>Rehond</i>	1	\$ 1,020.00	\$ 1,020.00
6	Front Bumper Top Side Bracket LH / RH	2	\$ 34.00	\$ 68.00
7	Front Bumper Towing Cover <i>Not New</i>	1	\$ 30.00	\$ 30.00
8	Front Bumper Foglamp Cover LH / RH	2	\$ 72.00	\$ 144.00
9	Front Bumper Foglamp LH / RH <i>cracked</i>	2	\$ 345.00	\$ 690.00
10	Front Bumper Centre Bracket <i>cracked</i>	1	\$ 55.00	\$ 55.00
11	Front Bumper Reinforcement <i>Best</i>	1	\$ 396.00	\$ 396.00
12	Front Bumper Lower Grille <i>Rehond</i>	1	\$ 148.00	\$ 148.00
13	Front Wheel Arch Garnish LH / RH <i>Not New</i>	2	\$ 234.00	\$ 468.00
14	Centre Grille Base <i>cracked</i>	1	\$ 420.00	\$ 420.00
15	Centre Grille	1	\$ 315.00	\$ 315.00
16	Centre Grille Chrome Moulding <i>cracked</i>	1	\$ 432.00	\$ 432.00
17	Centre Grille "Honda" Badge Logo <i>Not New</i>	1	\$ 43.00	\$ 43.00
18	Horn <i>Not New</i>	1	\$ 88.00	\$ 88.00
19	Headlamp LH / RH <i>2H cracked</i>	2	\$ 1,988.00	\$ 3,976.00
20	Headlamp Lower Support Bracket LH / RH <i>cracked</i>	2	\$ 48.00	\$ 96.00
21	Front Support Panel Top Garnish <i>Not New</i>	1	\$ 103.00	\$ 103.00
22	Front Support Panel <i>Not New</i>	1	\$ 633.00	\$ 633.00

23	Front Fender LH / RH	2	\$	645.00	\$	1,290.00	+
24	Front Fender Inner Cowling LH / RH	2	\$	153.00	\$	306.00	+
25	Front Fender Wheel Arch LH / RH	2	\$	145.00	\$	290.00	+
26	Tailgate <i>Distorted</i>	1	\$	1,100.00	\$	1,100.00	878
27	Tailgate Outer Top Garnish <i>Nbl new</i>	1	\$	444.00	\$	444.00	+
28	Tailgate Inner Trim Board <i>Defound</i>	1	\$	178.00	\$	178.00	✓
29	Tailgate Glass Moulding 4 pcs <i>new</i>	2	\$	168.00	\$	<u>336.00</u>	112
30	Tailgate Inner Handle <i>NE new</i>	1	\$	37.00	\$	37.00	x.
31	Tailgate Lock <i>Damaged</i>	1	\$	300.00	\$	300.00	118
32	Tailgate Lower Lock <i>Nbl new</i>	1	\$	43.00	\$	43.00	+
33	Tailgate Weather Strip <i>cut</i>	1	\$	115.00	\$	115.00	✓
34	Tailgate "HR-V" Emblem <i>NEC</i>	1	\$	57.00	\$	57.00	✓
35	Tailgate "I-VTEC" Emblem <i>NEC</i>	1	\$	48.00	\$	48.00	✓
36	Tailgate "HONDA" Badge Logo <i>NE new</i>	1	\$	42.00	\$	42.00	x.
37	Tailgate Rubber Stopper LH / RH <i>NE new</i>	2	\$	26.00	\$	52.00	x.
38	Tailgate Light Indicator LH / RH <i>cut</i>	2	\$	410.00	\$	820.00	✓
39	Taillamp LH / RH <i>cut</i>	2	\$	540.00	\$	1,080.00	✓
40	Taillamp Side Garnish LH / RH <i>NE new</i>	2	\$	224.00	\$	448.00	x.
41	Taillamp Panel LH / RH <i>NE new</i>	2	\$	158.00	\$	316.00	x.
42	Rear Bumper <i>Defound</i>	1	\$	880.00	\$	880.00	564
43	Rear Bumper Side Retainer LH / RH <i>new</i>	2	\$	25.00	\$	50.00	✓
44	Rear Bumper Reflector LH / RH <i>LH cracked.</i>	2	\$	180.00	\$	360.00	180.
45	Rear End Panel <i>Distorted</i>	1	\$	460.00	\$	460.00	✓
46	Rear End Panel Top Garnish <i>Defound</i>	1	\$	470.00	\$	<u>470.00</u>	180
47	Tailgate Sensor <i>NE new</i>	1	\$	155.00	\$	155.00	x
48	Tailgate Buzzer <i>cracked.</i>	1	\$	110.00	\$	110.00	✓
49	Rear Floor Panel Tools Box Sponge <i>Defound.</i>	1	\$	190.00	\$	190.00	✓

TOTAL PRICE : \$ 20,454.00

LIST LESS 20% : \$ 4,090.80

SUB TOTAL PRICE : \$ 16,363.20

10148.80

8119.04

CLAIM DETAIL : PARTS S/NETT

S/N	DESCRIPTION	QTY	UNIT S/N PRICE	TOTAL S/N PRICE
1	Front Number Plate Set Bert	1	\$ 80.00	\$ 80.00 50
2	Front Number Plate Seal (OPC) new	1	\$ 60.00	\$ 60.00 16.05
3	Inspection fee for OPC Seal nec	1	\$ 25.00	\$ 25.00 ✓
4	Front Bumper Under Cover Clip Set ne new	1	\$ 50.00	\$ 50.00 x
5	Front Bumper Cowling LH / RH Clip Set 3 new	2	\$ 50.00	\$ 100.00 x
6	Front Wheel Arch Outer Trim Clip Set 3 new	1	\$ 30.00	\$ 30.00 x
7	Front Support Panel Top Garnish Clip Set xtem	1	\$ 80.00	\$ 80.00 x.

8	Front Grille Clip Set <i>New</i>	1	\$ 50.00	\$ 50.00 <i>30.</i>
9	Rear Bumper Plate Set <i>Best</i>	1	\$ 50.00	\$ 50.00 <i>✓</i>
10	Rear Bumper Plate Seal (OPC) <i>New</i>	1	\$ 40.00	\$ 40.00 <i>16.05.</i>
11	Tailgate Windscreen Sealant <i>New</i>	1	\$ 80.00	\$ 80.00 <i>60.</i>
12	Tailgate Sealant <i>New</i>	1	\$ 80.00	\$ 80.00 <i>X.</i>
13	Tailgate Inner Trim Board Clip <i>New</i>	1	\$ 64.00	\$ 64.00 <i>30</i>
14	Rear End Panel Top Garnish Clip Set <i>New</i>	1	\$ 50.00	\$ 50.00 <i>20.</i>
15	Tail Lamp LH / RH Clip Set <i>New</i>	2	\$ 50.00	\$ 100.00 <i>10.</i>
16	Rear End Panel Insulation Seal <i>New</i>	1	\$ 150.00	\$ 150.00 <i>60.</i>
17	Rear Wheel Arch Outer Garnish LH / RH Clips <i>New</i>	2	\$ 48.00	\$ 96.00 <i>X</i>
18	Rear Windscreen solar film <i>New</i>	1	\$ 580.00	\$ 580.00 <i>X.</i>

S/N TOTAL PRICE: \$ 1,765.00

397.10

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

S/N	DESCRIPTION	PRICE	ADJUST
1	Computerise Diagnostic check and parameter settings for Headlights, Taillamps, Parking Camera, Parking Sensor	\$ 380.00	100.
2	Labour charge to remove & install OPC Plate & Seal	\$ 168.00	<i>80.</i>
3	(FRONT PORTION)		
	Labour charge for Panel Beating, Straightening, remove-refit and parts replacement	\$ 840.00	<i>400.</i>
4	To spray paint Bonnet, Frt Bumper, Bumper Lower Lid, LH & RH Fender, LH & RH Outer Wheel Arch Trim	\$ 1,680.00	<i>600.</i>
5	To apply anti-rust and tuff coat to affected areas	\$ 240.00	<i>50.</i>
6	To perform front electrical wiring checks and functionality checks	\$ 200.00	<i>60.</i>
7	To perform calibration and levelling for Head Lights	\$ 160.00	<i>X</i>
8	(REAR PORTION)		
	Labour charge for Panel Beating, Straightening, remove-refit and parts replacement	\$ 840.00 1200	<i>✓</i> 1000
9	To spray paint Tailgate, Tailgate Outer Garnish, End Panel and Bumper, LH & RH Bumper Side Upper	\$ 1,680.00	<i>1000</i>
10	To apply anti-rust and tuff coat to affected areas	\$ 240.00	<i>100.</i>

3230

24,916.20

total: 11746.14
H/S: 9.4K.
12 Days.