

Thurs 20/04 @ 10am
S&L

SFA1930H

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number 1800-2255269

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax: 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax: 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159946
Fax: 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Page No. : 1 of 5

Estimate No. : b1 57488
Date Estimated : 08/02/2021
Prepared By : Han Kwan Yong

- ESTIMATE REPAIR FOR -
Thanaporn Lorchirachoonkul
59 Hillview Avenue
#04-05

- ACCOUNT - 40000
Cash Sales - Service
Singapore

Singapore 669616

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SFA1930H	WBA6V120905N54314	14/08/2019	216i GT	0

DESCRIPTION

To replace rear bumper including to knock out dented area caused by the accident

To respray rear bumper

To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct check for proper function.

To check electrical wiring system and lighting at the rear section for proper function.

Sundries

	VALUE
850	1,275.00
986 934	1,088.00
168 150	177.00
168 150	177.00
?	80.00

Total Labour 1: 2,747.00

DESCRIPTION

RR BUMPER LH SIDE GUIDE ? fsvr
REAR BUMPER CARRIER ? fsvr
SUPPORT ? fsvr
RR BUMPER LH INNER SIDE GUID ? fsvr
REAR BUMPER PANEL PRIMED (LI de)
REAR BUMPER TRIM STRIP CHROM see

QTY	PRIC	VALUE
1	61.65	61.65
1	460.40	460.40
1	45.75	45.75
1	61.65	61.65
1	1,050.65	1,050.65
1	78.75	78.75
Total Parts :		1,758.85

Performance Motors Limited

A-1111, DARTY MOTOR COMPANY
 Ch. Reg. No. 197401559W GST Reg. No. M2-0020981-X
 Toll-Free Number: (1800-2255169)

315, Alexandra Road
 Blue Darby Performance Centre
 Singapore 119944
 Fax: 64796601

380, Kampong Arang Road
 East Coast Centre
 Singapore 438180
 Fax: 63449773

315, Alexandra Road
 Blue Darby Business Centre
 Singapore 159944
 (AfterSales)
 (MOCOTRA)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 57488
 Date Estimated : 08/02/2021
 Prepared By : Han Kwan Yong

Page No. : 2 of 5

REGN. NO. CHASSIS NO. REGN. DATE MODEL MILEAGE
 SFA1930H WBA6V120905N54314 14/08/2019 2161 GT 0

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. Claim No. _____
 Date & Time 20/04/21 01035 Excess S\$ _____
 Surveyor's Name Ragu Sign _____
 Surveyor's Tel 90014068 Authorised Yes / No _____
 Authorised Date _____ Time _____
 RESURVEY PARTS PHOTO BY SURVEYOR Yes / No PML Yes / No _____
 Surveyor's E-mail _____
 No. of Working Days Recommend 3 days

LKK Auto Consultants hence notify the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:



Labour 1	:	2,747.00
Parts	:	1,758.85
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	315.41
Grand Total	:	4,821.26

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**
 ** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **