



CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE
209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000 10/02/	Cust No/Name /DAVID FOO HEE CHEW Reg No/Reg Date SJW972E / 11/01/201 Date In/Mileage 10/02/2021/ 0 Chassis No KNAF3416MK5022784 Engine No G4FGJH712637 Make/Model KIA/CERATO 1.6 A SR SX G335 Colour/Trim CR5 RUNWAY RED / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LAX00000	Credit	10/02/2021/ 13:07	BLC	260 / AiTing	28804			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M SUNDRY								20.00
Sundry								
M SUNDRY								3200.00
WIRE ASSY MAIN ----91150M6490								
E PNT88000								
RENEW FRT BUMPER, BONNET, FRT FENDER RH & LH, FRT SUPPORT PANEL 8 X 400								
FRT WHEELHOUSING RH								100.00
REPAIR FRT DOOR RH & LH, A-PILLAR RH & LH, FRT CHASSIS RH								
E PNT88000								80.00
REMOVE & INSTALL AIRCON CONDENSOR & RADIATOR								
M SUNDRY								50.00
TOP UP AIRCON GAS								
M SUNDRY								4800.00
FRT NUMBER PLATE WITH FRAME								
E PNT98000								30.00
SPRAY PAINT FOR FRT BUMPER, BONNET, FRT FENDER RH & LH, FRT DOOR RH & LH, A-PILLAR RH & LH, FRT CHASSIS RH & LH 9 X 480								
FRT WHEELALIGNMENT RH								
A 90000001								120.00
CHECK WIRING & ELECTRICAL SYSTEM								
A 10028901								400.00
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST								
A 90000001								400.00
RENEW FUEL PIPE , LINK TO REAR								
A 90000001								60.00
REMOVE & INSTALL FRT CROSSMEMBER TO FACILITATE RENEW FUEL PIPE								
E PNT88000								240.00
REMOVE & INSTALL PARKING SENSOR								
E PNT88000								80.00
RENEW FRT WINDSCREEN								
M SUNDRY								
APPLY SEALANT FOR FRT WINDSCREEN								

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE
209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
DAVID FOO HEE CHEW 37 HOUGANG AVE 7 #12-06 SINGAPORE 538803 Contact No Mobile: 97897757	Cust No/Name /DAVID FOO HEE CHEW Reg No/Reg Date SJW972E / 11/01/201 Date In/Mileage / 0 Chassis No KNAF3416MK5022784 Engine No G4FGJH712637 Make/Model KIA/CERATO 1.6 A SR SX G335 Colour/Trim CR5 RUNWAY RED / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CSM00081	Cash	10/02/2021/ 12:05	Bod	442 / CocoLu	28804			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M SUNDRY								220.00
APPLY FRONT WINDSCREEN SOLAR FILM								80.00
M SUNDRY								400.00
APPLY SEALANT FOR ACCIDENT PORTION								400.00
A 90000001								400.00
RENEW INTAKE MANIFOLD & THROTTLE BODY								400.00
A 90000001								400.00
RENEW AIRBAGS AND SEAT BELTS								400.00
A 90000001								400.00
RENEW DASHBOARD & AIRBAG SENSOR								400.00
M COVER-FR BUMPER / BR					1.00	633.00	00.00	633.00
M CAP-FRONT HOOK / CRU					1.00	9.00	00.00	9.00
M GRILLE-FRONT BUMPER / BR (Back)					1.00	485.00	00.00	485.00
M COVER-FR BUMPER FOG LAMP, RH / CUT					1.00	15.00	00.00	15.00
M COVER-FR BUMPER FOG LAMP, LH X NN					1.00	15.00	00.00	15.00
M LAMP ASSY-FRONT FOG, RH X NN					1.00	303.00	00.00	303.00
M LAMP ASSY-FRONT FOG, LH X NN					1.00	303.00	00.00	303.00
M LAMP ASSY-SIDE REPEATER, RH / CUT					1.00	143.00	00.00	143.00
M LAMP ASSY-SIDE REPEATER, LH X NN					1.00	143.00	00.00	143.00
M GRILLE ASSY-RADIATOR / BR					1.00	328.00	00.00	328.00
M GARNISH-RADIATOR GRILLE / BR (Tp cover)					1.00	38.00	00.00	38.00
M AIR DUCT-FR BUMPER, RH / BR					1.00	14.00	00.00	14.00
M AIR DUCT-FR BUMPER, LH / BR					1.00	14.00	00.00	14.00
M BRACKET-FR BUMPER UPR SIDE MTG / BR (RH)					1.00	22.00	00.00	22.00
M BRACKET-FR BUMPER UPR SIDE MTG X NN					1.00	22.00	00.00	22.00
M ABSORBER-FRONT BUMPER ENERGY / BR					1.00	84.00	00.00	84.00
M WIRING ASSY-BUMPER EXTENSION / ? / BR					1.00	207.00	00.00	207.00
M ULTRASONIC SENSOR ASSY-P.A.S ? X NN					4.00	163.00	00.00	652.00
M PANEL ASSY-HOOD / DD					1.00	1502.00	00.00	1502.00
M HINGE ASSY-HOOD, RH / BT					1.00	43.00	00.00	43.00
M HINGE ASSY-HOOD, LH / BT					1.00	43.00	00.00	43.00
P PANEL-FENDER, RH / DD					1.00	430.00	00.00	430.00
P PANEL-FENDER, LH X R					1.00	430.00	00.00	430.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE



209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

CYCLE & CARRIAGE

ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 199405410K

Invoice Name & Address	Owner Name & Vehicle Info
DAVID FOO HEE CHEW 37 HOUGANG AVE 7 #12-06 SINGAPORE 538803 Contact No Mobile: 97897757	Cust No/Name /DAVID FOO HEE CHEW Reg No/Reg Date SJW972E / 11/01/201 Date In/Mileage / 0 Chassis No KNAF3416MK5022784 Engine No G4FGJH712637 Make/Model KIA/CERATO 1.6 A SR SX G335 Colour/Trim CR5 RUNWAY RED / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No				
CSM00081	Cash	10/02/2021/ 12:05	Bod	442 / CocoLu	28804	Qty	Unit Price	Disc%	Amount
Description of Goods / Services									
M	BEAM COMPLETE-FR BUMPER	DD				1.00	497.00	00.00	497.00
M	CARRIER ASSY-FRONT END MODULE	BR				1.00	675.00	00.00	675.00
M	BRACKET ASSY-FENDER & BUMPER,R	BR				1.00	9.00	00.00	9.00
M	BRACKET ASSY-FENDER & BUMPER,L	BR				1.00	9.00	00.00	9.00
M	BRACKET ASSY-FENDER & BPR MTG,	BR				1.00	14.00	00.00	14.00
M	BRACKET ASSY-FENDER & BPR MTG,	BR				1.00	538.00	00.00	538.00
M	PANEL ASSY-FNDR APRON,RH	DD				1.00	30.00	00.00	30.00
M	PNL-FENDER APRON UPR OTR,RH	BT				1.00	156.00	00.00	156.00
P	PAD-HOOD INSULATING	CRU				1.00	103.00	00.00	103.00
M	LATCH ASSY-HOOD	BT				1.00	11.00	00.00	11.00
M	COVER-AFTER SERVICE,RH	MIS				1.00	11.00	00.00	11.00
M	COVER-AFTER SERVICE,LH	MIS				1.00	56.00	00.00	56.00
M	MOULDING-WINDSHIELD GLASS	MC				1.00	247.00	00.00	247.00
M	COVER ASSY-COWL TOP	CUT				1.00	821.00	00.00	821.00
M	GLASS-WINDSHIELD	BR				1.00	95.00	00.00	95.00
M	GUARD ASSY-FRONT WHEEL,RH	BR				1.00	95.00	00.00	95.00
M	GUARD ASSY-FRONT WHEEL,LH	BR				1.00	2210.00	00.00	2210.00
M	LAMP ASSY-HEAD,RH	BR				1.00	2210.00	00.00	2210.00
M	LAMP ASSY-HEAD,LH	BR				1.00	146.00	00.00	146.00
M	RESERVOIR & PUMP ASSY-WASHER	CRU				1.00	74.00	00.00	74.00
M	HORN ASSY-LOW PITCH	BR				1.00	1279.00	00.00	1279.00
M	CRASH PAD ASSY-MAIN	BR				1.00	37.00	00.00	37.00
M	ADJUSTER ASSY-HEIGHT	BR				1.00	317.00	00.00	317.00
M	S/BELT ASSY-FR RH	BR				1.00	37.00	00.00	37.00
M	ADJUSTER ASSY-HEIGHT	BR				1.00	315.00	00.00	315.00
M	S/BELT ASSY-FR LH	BR				1.00	922.00	00.00	922.00
M	MODULE ASSY-STRG WHEEL AIR BAG	BR				1.00	1275.00	00.00	1275.00
M	AIR BAG ASSY-PASSENGER	BR				1.00	1025.00	00.00	1025.00
M	MODULE ASSY-AIR BAG CONTROL	BR				2.00	54.00	00.00	108.00
P	SENSOR ASSY-A TYPE CRASH	MC				2.00	54.00	00.00	108.00
M	SENSOR ASSY-A TYPE CRASH	MC				1.00	668.00	00.00	668.00
M	TUBE ASSY-SUCTION & LIQUID	MC				1.00	122.00	00.00	122.00
M	HOSE-DISCHARGE	MC				1.00	687.00	00.00	687.00
M	CONDENSER ASSY-COOLER	BT							

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE KIA PTE LTD

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



CYCLE & CARRIAGE

Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
DAVID FOO HEE CHEW 37 HOUGANG AVE 7 #12-06 SINGAPORE 538803 Contact No Mobile: 97897757	Cust No/Name /DAVID FOO HEE CHEW Reg No/Reg Date SJW972E / 11/01/201 Date In/Mileage / 0 Chassis No KNAF3416MK5022784 Engine No G4FGJH712637 Make/Model KIA/CERATO 1.6 A SR SX G335 Colour/Trim CR5 RUNWAY RED / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CSM00081	Cash	10/02/2021/ 12:05	Bod	442 / CocoLu	28804			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M	GUARD-AIR,RH	BR			1.00	28.00	00.00	28.00
M	GUARD-AIR,LH	BR			1.00	28.00	00.00	28.00
M	RADIATOR ASSY	BR			1.00	646.00	00.00	646.00
M	BLOWER ASSY	BR			1.00	656.00	00.00	656.00
M	FILLER NECK ASSY-RADIATOR	BR			1.00	28.00	00.00	28.00
M	HOSE ASSY-RADIATOR,UPR	CRU			1.00	27.00	00.00	27.00
M	HOSE ASSY-RADIATOR,LWR	X NN			1.00	40.00	00.00	40.00
M	WIRING ASSY-CONTROL	TAI			1.00	966.00	00.00	966.00
M	HOSE ASSY-OIL COOLING	X NN			1.00	70.00	00.00	70.00
M	HOSE ASSY-OIL COOLING	X NN			1.00	35.00	00.00	35.00
M	PIPE-DELIVERY	BT			1.00	164.00	00.00	164.00
M	CLEANER ASSY-AIR	BR			1.00	174.00	00.00	174.00
M	HOSE ASSY-AIR INTAKE	CRU			1.00	83.00	00.00	83.00
M	HOSE ASSY-BREATHER	X NN			1.00	28.00	00.00	28.00
M	DUCT ASSY-AIR	BR			1.00	55.00	00.00	55.00
M	SHIELD-AIR INTAKE	MIS			1.00	9.00	00.00	9.00
M	DUCT-EXTENSION	MIS			1.00	5.00	00.00	5.00
M	DUCT ASSY-EXTENSION	X NN			1.00	115.00	00.00	115.00
M	COVER ASSY-ENGINE	CUT			1.00	212.00	00.00	212.00
M	MANIFOLD ASSY-INTAKE	BR			1.00	906.00	00.00	906.00
M	BODY ASSY-THROTTLE	BR			1.00	636.00	00.00	636.00
M	PIPE ASSY-VACUUM	CRU			1.00	50.00	00.00	50.00
M	HOSE ASSY-WATER A	X NN			1.00	23.00	00.00	23.00
M	HOSE ASSY-WATER B	CRU			1.00	23.00	00.00	23.00
M	TUBE-FUEL FEED	BRU			1.00	142.00	00.00	142.00
M	CONTACT ASSY-CLOCK SPRING	MCC			1.00	253.00	00.00	253.00

Estimate

Steve (LKK)
00-NM AL
Express - ?
10/2/21, 12.00pm
PIP

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation

Confirm & accepted by

on a Without Prejudice basis

- No longer notification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Authorized signatory and company stamp

35,967.00

2517.69

38,484.69

Nett 35967.00

Total Payable

7% GST on

20 days

Estimate

Steve (CLKK)

00-NM AL

Express - ?

10/2/21, 12.00pm

P/P

L&K Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- For a price, are subject to confirmation

Confirm & accepted by on a "Without Prejudice" basis

- No longer available item(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Authorized signatory and company stamp

My B/L SKJ
20 days

7% GST on 35967.00

Nett 35,967.00

2517.69

Total Payable 38,484.69

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.