



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

General Details

Involving	TPVD UNKNOWN (SJR358E)
Date of Loss	February 4, 2021
Time of Loss	18.00
Loss Description	GBC2021L (INSD) C/W SJR358E (TP)
Comment	<input type="text"/>

Workshop Details

Total Rebate Amount	<input type="text" value="21528"/>
Nett Loss Amount	\$20,472.00
Assigned Workshop	LKK AUTO CONSULTANTS PTE LTD (TP)
Days of work completion *	<input type="text" value="20"/>



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Vehicle & Driver Details

Vehicle Registration# SJR358E

Purchase Date

mm/dd/yyyy



Registration State

SINGAPORE

Registration Date *

04/06/2009



Mileage

153115

Age of Vehicle

11

Driver Details

CATEGORY

POLICY
INFORMATION

ASSESSMENT INFORMATION

Manufacturing
Year

2008

Make

TPVD

TOYOTA

CATEGORY

FNOL
INFORMATIONPOST SURVEY
INFORMATION

Driver Name

TBC

Date of Birth

January 1, 1999

mm/dd/yyyy



Model CATEGORY	UNKNOWN POLICY INFORMATION	ALLION A1.5 A ASSESSMENT INFORMATION
Type		<div>▼</div>
Type of Paint		
Chassis No		<div>NZT2603037475</div>
Engine No		<div>1NZD284872</div>
Engine Capacity		<div>1496</div>
Sum Insured		<div>0</div>
Market Value		<div>42000</div>

CATEGORY Age	FNOL INFORMATION	POST SURVEY INFORMATION
Occupation	Unknown	
Education Qualification	Other	<div>▼</div>
Driving Experience	0	
Driver License #		
License Type		<div>▼</div>
License Issue Date		<div>mm/dd/yyyy</div> <div></div>
License Expiration Date		<div>mm/dd/yyyy</div> <div></div>

CATEGORY	FNOL INFORMATION	POST SURVEY
Address	TBC, Singapore	<input type="text"/>
Address type	Personal Correspondence	<input type="text" value="▼"/>
Gender	Unknown	<input type="text" value="▼"/>
Marital status	Unknown	<input type="text" value="▼"/>
Identification #	TBC	<input type="text"/>



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Detailed Assessment

Inspection Date *

08/02/2021



Total Loss

Yes

No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

0

Young/Inexperienced/
Unnamed Driver
Excess

0

Condition of Vehicle at time of survey

General condition

Good



Steering (Serviceable)

Yes

No

Footbrake (Serviceable)

Yes

No

Handbrake
(Serviceable)

Yes

No

Engine Modification

Yes

No

Pre-accident condition

Good



Other Excess

Tyre Condition

Age of Tyres

Spare wheel

Front Tyre Size

Rear Tyre Size

Front left side

Rear left side

Front right side

Rear right side



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%

Salvage%

Discount%

25

Settlement%

100

Paint Labour/Material Ratio

Paint Labour Ratio

20

Paint Material Ratio

80

Cash Loss

Yes

No

Part Supplied by AXA

Yes

No

Save



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Parts

Add







Approve

Deny

Submit All

	EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)
<input type="checkbox"/>		0	1		REAR BUMPER	Deformed	0	968.4	No		25			726.3	Reviewing
<input type="checkbox"/>		0	1		REAR BUMPER SIDE HOLDER LH	Necessary	0	68	No		25			51	Reviewing
<input type="checkbox"/>		0	1		REAR BUMPER REFLECTOR LH	Cracked	0	85.6	No		25			64.2	Reviewing
<input type="checkbox"/>		0	1		REAR BUMPER IMPACT BRACKET LH	Serviceable	0	0	No		25			0	Deny
<input type="checkbox"/>		0	1		REAR END PANEL	Repair	0	0	No		25			0	Deny
<input type="checkbox"/>		0	1		TAILLAMP LH	Cracked	0	368	No		25			276	Reviewing

Labour

<div><div>Add</div><div>Approve</div><div>Deny</div><div>Submit All</div></div>										
	EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	ESTIMATE LABOUR AMOUNT	ADJUSTED LABOUR AMOUNT	ESTIMATE PAINT AMOUNT	ADJUSTED PAINT AMOUNT	ACTION (LABOUR)	COMMENT
<input type="checkbox"/>		0		PANEL BEATING, REMOVE AND REFIT PARTS	0	300	0	0	Reviewing	
<input type="checkbox"/>		0		SPRAY PAINTING TO AFFECTED AREA	0	400	0	0	Reviewing	
<input type="checkbox"/>		0		WIRING CHECK	0	30	0	0	Reviewing	
<input type="checkbox"/>		0		TUFF COAT	0	60	0	0	Reviewing	
<input type="checkbox"/>		0		TO REMOVE REVERSE SENSOR	0	50	0	0	Reviewing	
<input type="checkbox"/>		0		TO REMOVE AND REFIT UPHOLSTERY	0	0	0	0	Deny	



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary





Add

Approve

Deny

Submit All

	EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
<input type="checkbox"/>		0	DAYS OF REPAIR : 3 DAYS	Reviewing		0		
<input type="checkbox"/>		0	SET REAR BUMPER CLIPS	Reviewing		30	NECESSARY	
<input type="checkbox"/>		0	SET REVERSE SENSOR	Deny		0	NOT NECESSARY	

	EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
<input type="checkbox"/>		0	SET REAR END PANEL SEALANT	Deny		0	NOT NECESSARY	
<input type="checkbox"/>		0	REAR LH WHEEL RIM	Reviewing		350	CUT	



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details		Vehicle & Driver Details	Vehicle Condition	Taxes & Ratio	Parts & Labour	Miscellaneous	Summary
Estimated Claim Amount	\$0.00			Adjusted Claim Amount	\$2,337.50		
CATEGORY	ESTIMATE	ADJUSTED					
Spare Parts	\$0.00	\$1,117.50					
Labour	\$0.00	\$840.00					
Miscellaneous	\$0.00	\$380.00					

Submit for Review



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Add

Approve

Deny

Submit All

EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
<input type="checkbox"/>	0	FINAL LUMP SUM	Reviewing		1800		

Submit for Review