SLQ 5603X

| | | SUPP (PARTS) | | <u>LABOUR</u> | | <u>S/N</u> | | | | <u>PARTS</u> |
|---------------|---------------------------------------|--------------|-----------------|---------------|--------|------------|--------|--------|--------|--------------|
| \$0.00 | \$0.00 | | \$10.00 | | \$0.00 | | \$0.00 | \$0.00 | \$0.00 | |
| \$0.00 | \$0.00 | | \$100.00 | | \$0.00 | | \$0.00 | \$0.00 | \$0.00 | |
| \$0.00 | \$0.00 | | \$220.00 | | \$0.00 | | \$0.00 | \$0.00 | \$0.00 | |
| \$0.00 | \$0.00 | | \$100.00 | | \$0.00 | | \$0.00 | \$0.00 | \$0.00 | |
| \$0.00 | \$0.00 | | \$0.00 | | \$0.00 | | \$0.00 | \$0.00 | \$0.00 | |
| \$0.00 | \$0.00 | | \$0.00 | | \$0.00 | | \$0.00 | \$0.00 | \$0.00 | |
| \$0.00 | \$0.00 | | \$0.00 | | \$0.00 | | \$0.00 | \$0.00 | \$0.00 | |
| \$0.00 | \$0.00 | | \$0.00 | | \$0.00 | | \$0.00 | \$0.00 | \$0.00 | |
| \$0.00 | \$0.00 | | \$0.00 | | \$0.00 | | \$0.00 | \$0.00 | \$0.00 | |
| \$0.00 | \$0.00 | | \$0.00 | | \$0.00 | | \$0.00 | \$0.00 | \$0.00 | |
| \$0.00 | \$0.00 | | \$0.00 | | \$0.00 | | \$0.00 | \$0.00 | \$0.00 | |
| | | SUPP (SN) | \$0.00 | | \$0.00 | | \$0.00 | \$0.00 | \$0.00 | |
| \$0.00 | | | \$0.00 | | \$0.00 | | | \$0.00 | \$0.00 | |
| \$0.00 | | | \$0.00 | | \$0.00 | | | \$0.00 | \$0.00 | |
| | \$0.00 | | \$0.00 | | \$0.00 | | | \$0.00 | \$0.00 | |
| <u> </u> | \$0.00 | | \$0.00 | | \$0.00 | - | | \$0.00 | \$0.00 | |
| <u>\$0.00</u> | <u>\$0.00</u> | | <u>\$430.00</u> | | \$0.00 | | \$0.00 | \$0.00 | \$0.00 | |
| | | | | | | - | | \$0.00 | \$0.00 | |
| | | SUPP(LABOUR) | | | | | \$0.00 | \$0.00 | \$0.00 | |
| \$0.00 | · · · · · · · · · · · · · · · · · · · | | | TOTAL | | | \$0.00 | \$0.00 | \$0.00 | |
| \$0.00 | \$0.00 | | \$0.00 | | | | | \$0.00 | \$0.00 | |
| \$0.00 | | | \$0.00 | | | - | | \$0.00 | \$0.00 | |
| <u>\$0.00</u> | <u>\$0.00</u> | | \$430.00 | | | | | \$0.00 | \$0.00 | |
| | | | \$0.00 | SUPP | | | \$0.00 | \$0.00 | \$0.00 | |
| 986cc) | TOYOTA HARRIER (1986cc | MAKE / MODEL | \$430.00 | P/P | | | \$0.00 | \$0.00 | \$0.00 | |
| \$0.00 | \$0.00 | MARKET VALUE | \$0.00 | | | | \$0.00 | \$0.00 | \$0.00 | |
| \$0.00 | \$0.00 | LTA REBATE | 0% | | | | \$0.00 | \$0.00 | \$0.00 | |
| \$0.00 | \$0.00 | NETT VALUE | \$0.00 | | | | \$0.00 | \$0.00 | \$0.00 | |
| 94.21 | \$4,194.21 | RED | \$0.00 | L/S | | | | \$0.00 | \$0.00 | |
| 24.21 | \$4,624.21 | TOTAL TP EST | | | ' | | \$0.00 | \$0.00 | \$0.00 | |
| <u>1</u> | | REPAIR DAYS | | | | | 0% | \$0.00 | \$0.00 | |
| | | REMARKS | | | | | \$0.00 | | \$0.00 | |